CUSTOMER #: UNIT#

504003MHS

INVOICE

PAGE 1

BUS:			CELL:			SER	VICE ADVISO	DR.					
COLOR	YEAR	and the	MAKE/MODEL	- CONTRACTOR		OLIN	VIN		LICENSE	MILEA	GE IN / OU	Т	TAG
			JVO VNL42T				39DH1KN9056	573			1/5183	91	75
DEL. DATE	PROD.	DATE	WARR. EXP.	PF	ROMISI	ED	PO NO.		RATE	PAYMENT	II.	V. DA	ATE
20217020 5			non land		0 10		GMD0 2275	70		CHC	17M	AV2	2
30AUG18 D R.O. OPE		_	DEADY	_	0 10 TIONS		STPO-2277	101	L	CHG	1 / 1/1	MIZ.	3
K.O. OP	ENEU	-	READY	OF OF	TIONS	,							
13:01 08M	AV23	07.	23 17MAY2	3									42.5
			TYPE HOURS						LIST	N	ET	TOT	AL
A CSA Che				101000	3346	14533156				200 50000		35136	
			006 CSA Ch	eck 2	2 In	specti	on						
	99	99]	C22									(N/	C)
PARTS:			LABOR:			OTHER:			TOTAL L	INE A:			1000
518391													
-							*******						
							INTO GEAR		CK AND	ADVISE			
99-0							T IT DOESN	IT					
			GEAR CHEC	K AND	ADV	/ISE							
		51 (
	62	88 (CDEF					September 1				10000	-
-								55000					1000
			FLYWHEEL					1000					1000
	CORE C			.T	T147.3	•		F816E					150
			CLUTCH K	IT, R	EMAN	V							8020
	CORE C			CVDM				500					1533
			PLANE GA					100000					14.56
			BRAKE CLN		TVO	T_CUTE	prip.	1505					1000
	TRANSM			TI VO	ПЛО	1-Shir	1	2000					
			7 PIPE					1000					100
			ZIPTIE 3/1	6				No.					
			O-RING	RICE STREET				1995					550
	Marin Marin Control		O-RING										
			PLANE GA	SKET				1973					193
			/2 UNION E		PUSH	IIN							
			SCREW					1999					199
			FITTING										
BURNOUS	-1 850	0256	50 CORE RE					133					
	-1 850	2177	71 CORE RE	TURN									
	1 2208	6413	CRANKSHA	FT SE				153					100
PARTS:			LABOR:			OTHER:		,	TOTAL L	INE B:	482	29.6	7
518391	5288 W	ent	threw and	foun	d th	nat the	clutch ha	s fa	ailed w	ould			
			ch calibr		, se		te was tol	d to			10000		
ON BEHALF OF	SERVICING (DEALER,	I HEREBY CERTIFY ACCURATE UNLESS	THAT THE		STATEMEN	NT OF DISCLAIMER			RIPTION	T	OTALS	
SHOWN, SERVICE	S DESCRIBE	DWERE	PERFORMEDAT NO	CHARGE TO	The 18	actory warra	nty constitutes all o	of the	LABOR AMO				
OWNER, THERE W.	AS NO INDIC	AT ANY	FROM THE APPEARAL PART REPAIRED OR	REPLACED	item/ite	ems. The	Seller hereby exp	ressly	PARTS AMO				
UNDER THIS CLAI	M HAD BEE	N CONN	ECTED IN ANY WAY	WITH ANY	disciair		anties either expre		GAS, OIL, LU			-	
ACCIDENT, NEGLIO ARE AVAILABLE	FOR (1) Y	EAR FR	CORDSSUPPORTING	PAYMENT		antability or	fitness for a part	ticular	SUBLET AMO		P. 10 (83)		33 73
NOTIFICATION AT	THE SER	VICING	OM THE DATE OF DEALER FOR INSPE	ECTION BY	author	izes any oth	neither assumes er person to assume	for it	MISC. CHAR			-	13.77.51.51
MANUFACTURERS	REPRESEN	MINE.			any lia	ability in cor	nnection with the s	ale of	TOTAL CHAR			-	
					THIS ILE	m/ items.			LESS INSUR	ANCE			
			100						SALES TAX				
	CENEDAL III	WAGED OF	AUTHORISE DEBEGO	(DATE)	CUSTO	MER SIGNATU	nor nor		THIS AMOU				
(SIGNED) DEALER	COENERAL MA	PROJEK OR	RAUTHORIZED PERSON	(DATE)	00010	MEN DIGNATU	1111		THO AMOU				

CUSTOMER #: UNIT#

504003MHS

INVOICE

PAGE 2

BUS:		CELL:	SE	RVICE ADVISOR:				
COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE	IN/OUT	TAG
	19	VOLVO VNL42T	4V41	WB9DH1KN905673	3	518391	/518391	T2647
DEL. DATE	PROD. D	ATE WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV.	
30AUG18 D		READY	16:00 10MAY2:	STPO-22770		CHG	17MAY2	23
13:01 08M	AY23	07:23 17MAY2	3					
LINE OPCO	DE TEC	H TYPE HOURS			LIST	NET	TOT	AL
flywheel then stal and then drive 62 done C** engine 99-0	or par and r bbed b pto a 51 too ** e oil 00-000 628 20966	ts and we di ear main 628 olted hooked nd filled tr k unit on te ********** leaks 1 engine oil 8 CDEF 752 O-RING LABOR:	nd then found dnt have parts 8 installed re up air and coansmission and st drive. unit ************************************	8 6288 pulled ear main and foolant and dri then calibra accelerated	clutch as lywheel ave line at ted needs and drove	nd and clutc and wirin s test e fine ***	h	
gasket								
D	**	******	******	*********	******	**		
29-0	USE IS 00-000: advise 628: 24009: FREIG	REQUIRED 1 trans oil e 8 WV 664 HOSE KIT HT FREIGHT SHIFT75W80PA	check and adv	check and				0000000 000000 00000 00000
PARTS: 518391 62 on transm	288 for	LABOR: und oil line n topped off	OTHER s leaking remo fluid no more	ved and replace	-1	ines		
ENVIRONMEN	NTAL/SH	HOP FEE						Name and Address of the Owner, where

INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS
SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO	The factory warranty constitutes all of the	LABOR AMOUNT	
OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED	item/items. The Seller hereby expressly	PARTS AMOUNT	
UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY	disclaims all warranties either express or	GAS, OIL, LUBE	
ACCIDENT, NEGLIGENCEOR MISUSE, RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT.	implied, including any implied warranty of merchantability or fitness for a particular	SUBLET AMOUNT	
NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY	purpose. Seller neither assumes nor authorizes any other person to assume for it	MISC. CHARGES	
MANUFACTURER S REPRESENTATIVE.	any liability in connection with the sale of	TOTAL CHARGES	
	this item/ items.	LESS INSURANCE	
		SALES TAX	
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT	

CUSTOMER #											
UNIT#						50	04003MHS				
							INVOICE				
							THYOTCE				
							naan o				
							PAGE 3				
COLOR	Iveant		CELL:			SER	RVICE ADVISOR:				
COLOR	YEAR		MAKE/MODEL				VIN	LICENSE	MILEAGE	IN/OUT	TAG
	19	VOL	VO VNL427	-		ANAWE	B9DH1KN905673		518391/	E10201	T2647
DEL. DATE		DATE	WARR. EXP.		ROMIS		PO NO.	RATE	PAYMENT	INV. [
20211010 22											
30AUG18 DI R.O. OPEN	_		READY			DMAY23	STPO-22770		CHG	17MAY2	23
THE CITE	120		READT	OF	TIONS	5:					
13:01 08MA	AY23	07:	23 17MAY2	23							
LINE OPCOI	DE TE	CH T	YPE HOURS	3				LIST			TAL
DOESN'T	INSMI	SSIO	N GETS HO	TI TO			PMENT OF OMA				
ADVISE	30 IN	10 6	E AR CHEC	K AND			S. IF YOU ARE	NOT 100	& SATISFI	ED	
0.50					EL	JUNOU C	CONTACT		100000		
											27/37/3
					nicos						
					103						
								-	In the second	TOT:	0
ON BEHALF OF SEI	AINED HER	EONIS A	ACCURATE UNLESS	OTHERWISE	*		NT OF DISCLAIMER	LABOR AMOU		TOTAL	.5
SHOWN SERVICES D	NO INDIC	WERE PI	ERFORMED AT NO C	CHARGE TO	warran	ties with re	nty constitutes all of the espect to the sale of this	PARTS AMOU			
VEHICLE OR OTHER UNDER THIS CLAIM	WISE, THA	T ANY	PART REPAIRED OR	REPLACED	disclair	ms all warr	Seller hereby expressly anties either express of	GAS, OIL, LU			
ACCIDENT NEGLIGER	NOROR MIS	USE, REC	CORDSSUPPORTING	THIS CLAIM I	implied	d, including	any implied warranty of fitness for a particular	SUBLET AMO			
ARE AVAILABLE FO	THE SERV	/ICING D	DEALER FOR INSPE	CTION BY	purpos	e. Seller	neither assumes no er person to assume for i	MISC, CHARG			
MANUFACTURER S RE	EPRESENT	ATIVE.			any lia	ability in con	nection with the sale of	TOTAL OTTE			-
					this ite	m/ items.		LESS INSURA	WACE		

CUSTOMER SIGNATURE

PLEASE PAY THIS AMOUNT

5448.02

DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

A SECTION ASSESSMENT

Repair Order:

Shop:

Status:

Make:

CLOSED

Repair Class:

NONSCHEDULED

Repair Site:

FACILITY

Opened: Closed:

11/7/2023 11/15/2023

Completed:

11/15/2023

Odometer:

556,894

Unit:

VIN:

2019 VOLVO VNR62T640

Domicile: Cost Cntr.

License:

4V4WB9DH1KN905673

Model:

VOLVO VNR62T 2019

Year. In Service: 8/30/2018

Section: Priority:

Complaint:

PM

Description

Comments:

5 Component: 000-040

Rep Reason: PM Unit War: None

Level A (40k Full)

War. Type:

NO WARRANTY

Comments

Date:

Comment Text

11/7/2023

completed 40k service [ADKAND]

Labor Date:

11/7/2023	ADKAND	
11/7/2023	ADKAND	

Mechanic

Level A (40k Full)

Level A (40k Full), PM, PERFORMED

Parts

Date:	Part ID	Description After Mkt	n espil dix
11/7/2023	DN P551807	Filter - Oil, Full Flow (D11)	
11/7/2023	DURON SHP 15W40	Oil - Engine, 15W40 DURON SHP (Petro	1
11/7/2023	FF42128NN	Filter Assembly - Fuel, Secondary	
11/7/2023	P550425	Filter - Oil, Full Flow [Volvo] (D11 - D13)	
11/7/2023	P550851	Element - Fuel Filter, Water Separator	
11/7/2023	P606555	Filter - Air Conditioner [Volvo] (D11 -	

2 Section:

NEEDS INSPEC Comments: Complaint:

Rep Reason: PM FOLLOW-UP 5 Priority: Unit War: None

Component: 002 Cab & Sheet Metal

NO WARRANTY War. Type:

Comments

Date:

Comment Text

11/7/2023

replaced cabin and bunk filters, removed trim on both mirrors, topped off fluids, Sbar wrote up in opp. inspected and

11/7/2023 run Sbar. works fine [FRINOA]

Generated by:

Version: 19.41.35

Page: 1 5/1/2024 5:58:22 PM

Total

Rate

Hours

Repair On	der:	Unit: 7047			-		
Labor					Hours	Rate	1
Date:	Mechanic	Description			1,000		
11/7/2023		Cab & Sheet M	etal, MISADJUSTED,				
Parts							
Date:	Part ID	Description		After Mkt	Qty	Unit Price	7
11/7/2023	P606555	Filter - Air Con	ditioner [Volvo] (D11	-			
Section:	3	Complaint: NEEDS INS	SPEC Comments:	700			
Priority:	5	Rep Reason: PM FOLLO	W-UP				
Component		Unit War: None					
Tire - Pneu					1		
War. Type:	NO WARRAN	IIY					
Comments							
Date:	Comment Text						
					100000		
11/7/2023	truck numbers	h of 7047s tag wheels, broke on the tires before putting th	them down, put the em in the used				
11/7/2023							
11///2023	pulled two tag v	n put the rims onto the shelv wheels that i already assemb	es in the tire shed. The	hen			
11/7/2023	filled to 100PSI	, & mounted them onto 7047	[BAN1US1				
11/8/2023		ean up any metal scrap piec		es			
	[BANJUS]						
11/9/2023	(2) Tires were p	out into the casing pile per So	cott S.				
abor							
Date:	Mechanic	Description			Hours	Rate	Total
11/7/2023	BANJUS	Tire - Pneumatio	Capacity of the Assessment	1,1698-			
11/7/2023	BANJUS	Tire - Pneumatio	west, west, and				
11/7/2023	BANJUS	Tire - Pneumatio	, WORN OUT,				
11/8/2023	BANJUS	Tire - Pneumatio	, WORN OUT,				
11/8/2023	BARRYA	Tire - Pneumatic	, WORN OUT,				
1/8/2023	BARRYA	Tire - Pneumatic					
arts							
Date:	Part ID	Description		After Mkt	0	II-N D.	100
					Qty	Unit Price	Total
1/8/2023	47798		, Tag, 455/55R 22.5 X	(
ection:	4	Complaint: PM	Comments:		100	KYON T	
riority: omponent:	5 000-009	Rep Reason: STATUTORY Unit War: None	INS				-
	ection - Tractors	Ont War. None					4 513
	Journal Hactors						

5/1/2024 5:58:22 PM

Version: 19.41.35

		Unit:	7047		-		-
omments		To the same	100				
Date:	Comment Text						
11/7/2023	changed the spe	ed					
abor	100	1					
Date:	Mechanic		Part 1-9-5 - 1000				
11/7/2023		Des	scription	- 10 April 1	Hours	Rate	Tot
Section:	-		neral Inspection - Tr	actors, PM,	655		
Priority:	5	Complaint:	NEEDS INSPEC	Comments:	974		40,300
Component:		Rep Reason:	PM FOLLOW-UP				
Filters	011-002	Unit War:	None				
War. Type:	NO WARRAN	TY					
^							
Comments							
Date:	Comment Text						
11/7/2023	replaced davco	filter because i	t was full [JONARC]	Paris of the street of	Aller Sant Sant San	and the same	1000
Labor			(OMANGA) asiash nas				
Date:	Mechanic	De	escription		Hours	Rate	Tot
11/7/2023			ters, WORN OUT, RE	DIACED NEW		100	100
		-	ters, WORN OUT, RE	PLACED NEW			
Parts Date:	Part ID	D-	and the same of th				
-		-	escription	After Mkt	Qty	Unit Price	Tot
11/7/2023	P550851		ement - Fuel Filter, \				
Section:	6	Complaint:	NEEDS INSPEC	Comments:			
Priority: Component	5 t: 034-003	Unit War:	: PM FOLLOW-UP None				
	king, & Backup L		140110				
War. Type:							
Comments							
Date:	Comment Text						
11/7/2023	7 way cord was	s rubbed pretty	bad and ziptied, was	instructed to		U.S.	11111111
111112020			wasn the same so i				
11/7/2023	a new kit of all	3 airlines and 7	way cord, [JONARO	A CONTRACTOR OF THE CONTRACTOR			
11/7/2023			after usin pipe sealar				
111112020	agricence an ar	e mange domi	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	A CONTRACTOR OF THE SECOND			
Labor							
Labor Date:	Mechanic	De	escription		Hours	Rate	Tot
				kun Lamne WOPN			
11/7/2023			gnal, Parking, & Bac				
11/7/2023		51	gnal, Parking, & Bac	kup Lamps			

- L Ondo	AF:	Unit: 7047		Qty	Unit Price	Tota
Repair Orde	1.	A	fter Mkt			
Parts		Description	E			
Date:	Part ID	Pig Tail End	E			
11/7/2023	15-730					
11/7/2023	15-730	e ABS Assembly				
11/7/2023	NT451097					
Section:	7	Complaint: LEAKING Rep Reason: INSPECTION				
	5	Unit War. None				
Component:	094	Unit War. None ings - Bulk Product Transfer Syste NTY		W. Che		
Lines, Tubes	NO WARRA	NTY			THE REST OF THE PERSON NAMED IN	
War. Type:	NO WARRY	W.				
Comments						7
Date:	Comment Text	aks in total on the front & back air tanks fittings &				
11/7/2023	5 different lea hoses. Got sta	arted on two fittings plus the				
		had together				
	noses/tdeet	gs and verified that there was no other leaks				
11/8/2023	replaced man					
				Hours	Rate	Tota
abor Date:	Mechanic	Description				
11/7/2023		Lines, Tubes, Hoses & Fittings - Bulk , LEAKING, DISASSEMBLE				
		a manage Bulk				
11/7/2023		Lines, Tubes, Hoses & Fittings - Bulk Product Transfer Syste				
11//2020		Product Hansier 575.5				
		A Sittings - Bulk				
11/8/2023		Lines, Tubes, Hoses & Fittings - Bulk Pro, LEAKING, REPAIRED				
		The same state and the same stat	fter Mkt	Qty	Unit Price	Tota
arts		- + # A	STATE OF THE STATE			
	Part ID	Description	SERVICE CO.			
Date:	Part ID 91203	A/B PUSH IN UNION 5/8 (PKG QTY 2)				
Parts Date: 11/7/2023 11/7/2023		A/B PUSH IN UNION 5/8 (PKG QTY 2) A/B PUSH ML ELB 5/8X1/2 (PKG QTY 3)				
Date: 11/7/2023 11/7/2023	91203	A/B PUSH IN UNION 5/8 (PKG QTY 2) A/B PUSH ML ELB 5/8X1/2 (PKG QTY 3) Fitting - Air System, Air Line, Hose,				
Date: 11/7/2023 11/7/2023	91203 91238	A/B PUSH IN UNION 5/8 (PKG QTY 2) A/B PUSH ML ELB 5/8X1/2 (PKG QTY 3)				
Date: 11/7/2023 11/7/2023 11/8/2023	91203 91238	A/B PUSH IN UNION 5/8 (PKG QTY 2) A/B PUSH ML ELB 5/8X1/2 (PKG QTY 3) Fitting - Air System, Air Line, Hose,				
Date: 11/7/2023 11/7/2023 11/8/2023	91203 91238 20515114	A/B PUSH IN UNION 5/8 (PKG QTY 2) A/B PUSH ML ELB 5/8X1/2 (PKG QTY 3) Fitting - Air System, Air Line, Hose, Tube, Plumbing (VOLVO) Fitting - Brake System, Air Line, Hose, Fitting - Air Line				
Date: 11/7/2023 11/7/2023 11/8/2023 11/8/2023 11/8/2023	91203 91238 20515114 20999385	A/B PUSH IN UNION 5/8 (PKG QTY 2) A/B PUSH ML ELB 5/8X1/2 (PKG QTY 3) Fitting - Air System, Air Line, Hose, Tube, Plumbing (VOLVO) Fitting - Brake System, Air Line, Hose,				
Date: 11/7/2023 11/7/2023 11/8/2023 11/8/2023 11/8/2023 11/8/2023	91203 91238 20515114 20999385 20999388	A/B PUSH IN UNION 5/8 (PKG QTY 2) A/B PUSH ML ELB 5/8X1/2 (PKG QTY 3) Fitting - Air System, Air Line, Hose, Tube, Plumbing (VOLVO) Fitting - Brake System, Air Line, Hose, Fitting - Air Line				Page

		Unit: 7047				
ection: Priority: Component: Air Type Pow Var. Type: Comments Date:	8 5 013-010 ver Brakes (see NO WARRANT	Complaint: NEEDS IN Rep Reason: PM FOLL Unit War: None 13-004 For Parking/service IY	OW-UP	Yman	STORE SECTION	
11/7/2023	replaced trailer	airlines and gladhands	The second second second			-
abor	Marith 1	animes and gladilatids				
Date:	Mechanic	Description		Hours	Rate	Tota
11/7/2023	50.00	Air Type Powe LEAKING, REP	r Brakes (see 13-004 For, LACED NEW			
11/8/2023		Air Type Powe WORN OUT, R	r Brakes (see 13-004 Fo, EPLACED NEW			
Parts						
Date:	Part ID	Description	After Mkt	Qty	Unit Price	Tota
11/7/2023	90625 90626		ED/EMERGENCY (PKG LUE/SERVICE (PKG QTY 2)	Total Total	5.m.11100	10.0
Section: Priority: Component: Suspension	9 5 016	Complaint: LEAKING Rep Reason: PM FOLLO Unit War: None	Comments:	6 60 0 000 0 000 0 000	Tropody 1 to 100	-0000 1 0000 1 0000
War. Type:	NO WARRANT	Y	1000000 princes and sold	d jedelek rojav		
Comments Date:	Comment Text			ea separation	District 45	
11/8/2023	replaced rear ai	r bags [ADKAND]		136		3250
Labor	\$100 mm					
Date:	Mechanic	Description		Hours	Rate	Total
11/8/2023	24	Suspension, LE	AKING, REPLACED NEW			
Parts						Description of the last of the
Date:	Part ID	Description	After Mkt	Qty	Unit Price	Total
11/8/2023	22564806	Air Spring - Re	ar Suspension (VOLVO)			

Generated by: wilson Version: 19.41.35

Unit: 7047 Repair Order:

Comments: INOPERATIVE Complaint: 10 Section:

Rep Reason: PM FOLLOW-UP 5 Priority: None

Unit War. Component: 054-002

Alarm - Reverse Signal

NO WARRANTY War. Type:

Comments

Comment Text Date: found bad fuse and i also checked wiring for bad spots and replaced 11/8/2023 back up alarm [ADKAND]

Labor

Total Rate Hours Description Date: Mechanic Alarm - Reverse Signal, NOT 11/8/2023

Parts

Unit Price Total Qty After Mkt Description Date: Part ID E 11/8/2023 21037699 Alarm - Reverse Signal

11 Complaint: NEEDS INSPEC Comments: Section:

Rep Reason: PM FOLLOW-UP 5 Priority:

Component: 034 Unit War.

Lighting System

NO WARRANTY War. Type:

Comments

Date:	justed visor lights back into housing	
11/8/2023	replaced driver side headlight and ordered passenger side, also adjusted visor lights back into housing	
11/10/2023	replaced passenger side headlight	

Labor

Date:	Mechanic	Description	Hours	Rate	Tota
11/8/2023	ADKAND	Lighting System			
11/8/2023	ADKAND	Lighting System			
11/9/2023	ADKAND	Lighting System	100		
11/10/2023	ADKAND	Lighting System			
11/10/2023	ADKAND	Lighting System, SHORTED, REPLACED			
Parts				19 2207	-
Date:	Part ID	Description After Mkt	Qty	Unit Price	Total
11/8/2023	78619542	Housing Assembly - Headlamp LH			
11/10/2023	78619544	Headlamps			

Generated by: Version: 19.41.35

Page: 6 5/1/2024 5:58:22 PM

Repair Order: Unit: 7047 Section: 12 Complaint: LOOSE Comments Priority: 5 Rep Reason: PM FOLLOW-UP Component: 043-004 Unit War: None Turbocharger War. Type: NO WARRANTY Comments Date: Comment Text 11/8/2023 replaced air to air boot clamps on hot side closest to the cac 11/9/2023 removed exhaust bellow because it was starting to leak in the middle of the bellow, found that the turbo diffuser was 11/9/2023 loose at the turbo. waiting on parts, replaced old 7th injector with brand new injector while the diffuser is off 11/9/2023 11/9/2023 got the parts and installed all 3 lead gaskets and v band clamps and tightened them up. ran the truck and sprayed with 11/9/2023 soap to watch for bubbles, did not find any bubbles, everything sealed up fine Labor Date: Mechanic Description Hours Rate Total 11/8/2023 Turbocharger, LEAKING, REPAIRED 11/9/2023 Turbocharger 11/9/2023 Turbocharger, LEAKING, REPLACED NEW Parts Date: Part ID Description After Mkt Unit Price Total 11/8/2023 85137462 Hose Clamp, Air Intake (VOLVO) 11/9/2023 20978469 Sleeve - Seal (VOLVO) 11/9/2023 21060426 V-clamp - Egr Exhaust To Engine (Volvo) 11/9/2023 21095721 Gasket - Turbocharger to Exhaust 11/9/2023 21407621 Injector - Doser Valve (VOLVO) 11/9/2023 23790336 Bellows - Exhaust Pipe, After-Treatment Section: 13 Complaint: **LEAKING** Comments: Priority: 5 Rep Reason: PM FOLLOW-UP Component: 065 Unit War: None Hydraulic Systems - Special Applications War. Type: NO WARRANTY

Comments

Date: Comment Text

Generated by: wilson Version: 19.41.35

Page: 7 5/1/2024 5:58:23 PM

Repair Order:		Unit: /04/	Unit: 7047					
11/9/2023	replaced orbit dust plugs for	tal motor with used one from red container added new hydro lines and transit lines and						
11/9/2023	replaced trans	sit coupler fittings						
Labor								
Date:	Mechanic	Description	Hou	irs Rate	Tot			
11/9/2023		Hydraulic Systems - Special						
Parts								
Date:	Part ID	Description After Mkt	Q	ty Unit Price	Tota			
11/9/2023	6601-8-10	1/2 ISO A HYDRAULIC COUPLER, Parker						
11/9/2023	6602-8-10	1/2 ISO A HYDRAULIC NIPPLE, Parker						
11/9/2023	97605	DUST PLUG 3/4 A NIPPLES (PKG QTY 1)						
11/9/2023	97606	DUST CAP 3/4 A NIPPLES (PKG QTY 1)						
11/9/2023	97607	DUST PLUG INTRANSIT HEAT 1/2 A						
11/9/2023	97608	DUST CAP INTRANSIT HEAT 1/2 A						
	14							
Section: Priority: Component: Cooling Sys War. Type:	5 042	Complaint: LEAKING Comments: Rep Reason: PM FOLLOW-UP Unit War: None						
Priority: Component: Cooling Sys War. Type:	5 042 tem	Rep Reason: PM FOLLOW-UP Unit War: None						
Priority: Component: Cooling Sys War. Type: Comments	5 042 tem NO WARRA	Rep Reason: PM FOLLOW-UP Unit War: None						
Priority: Component: Cooling Sys War. Type: Comments Date:	5 042 tem NO WARRA	Rep Reason: PM FOLLOW-UP Unit War: None						
Priority: Component: Cooling Sys War. Type: Comments Date:	5 042 tem NO WARRA	Rep Reason: PM FOLLOW-UP Unit War: None	Hours	Rate	Total			
Priority: Component: Cooling Sys War. Type: Comments Date: 11/9/2023	5 042 tem NO WARRA Comment Text	Rep Reason: PM FOLLOW-UP Unit War: None INTY tic return coolant lines on back side of surge tank Description	Hours	Rate	Total			
Priority: Component: Cooling Sys War. Type: Comments Date: 11/9/2023 Labor Date:	5 042 tem NO WARRA Comment Text	Rep Reason: PM FOLLOW-UP Unit War: None NTY tic return coolant lines on back side of surge tank	Hours	Rate	Total			
Priority: Component: Cooling Sys War. Type: Comments Date: 11/9/2023 Labor Date:	5 042 tem NO WARRA Comment Text	Rep Reason: PM FOLLOW-UP Unit War: None INTY tic return coolant lines on back side of surge tank Description	Rica					
Priority: Component: Cooling Sys War. Type: Comments Date: 11/9/2023 Labor Date: 11/9/2023	5 042 tem NO WARRA Comment Text replaced plast	Rep Reason: PM FOLLOW-UP Unit War: None INTY tic return coolant lines on back side of surge tank Description Cooling System, LEAKING, FILLED Description After Mkt	Hours	Rate Unit Price	Total			
Priority: Component: Cooling Sys Var. Type: Comments Date: 11/9/2023 abor Date: 11/9/2023 Parts Date:	5 042 tem NO WARRA Comment Text replaced plast Mechanic	Rep Reason: PM FOLLOW-UP Unit War: None NTY tic return coolant lines on back side of surge tank Description Cooling System, LEAKING, FILLED	Rica					

Generated by: wilson Version: 19.41.35

Page: 8 5/1/2024 5:58:23 PM

Repair Orde	er:	Unit: 7047				
Comments Date:	Comment Text	William St. St. Charles			neri facilitato	a first sorte
11/9/2023	installed new nite	system still have to secure w	iring [ADKAND]	Johnson, James	The State of	G805/110
11/10/2023	rescurred wiring f	from installing nite system [AD	DKAND1			
Labor Date:	Mechanic	Description		Hours	Rate	Tota
11/9/2023 11/9/2023 11/10/2023	99.5	Auxiliary Power Auxiliary Power Auxiliary Power, Sh	HORTED, REPLACED	3 11		
Parts Date:	Part ID	Description	After	Mkt Qty	Unit Price	Tota
11/9/2023	BSM 1001330451	Auxiliary Power Uni Pheonix Nite System		E	90 3	-
Section: Priority: Component: Seat Frame: War. Type:		Complaint: WONT RAISE Rep Reason: PM FOLLOW-U Unit War: None	Comments:	7,000		
Comments Date:	Comment Text		The state of the s			
11/10/2023	replaced driver se	eat and added risor bracket [Al	DKAND]		Section 1	wist.
Labor Date:	Mechanic	Description		Hours	Rate	Total
11/10/2023		Seat Frames & Sprin	ngs, WORN OUT,			
Parts						
Date:	Part ID	Description	After M	Vikt Qty	Unit Price	Total
11/10/2023	DMS 2D311PLBSNSN DMS SA35183 145 90					
Section: Priority: Component: Exhaust Afte War. Type:	5		Comments:	V 83355		A SHOOL AND A SHOO

Generated by: wilson Version: 19.41.35

Repair Orde	er:	Unit: 7047				
Comments Date:	Comment Text					
11/10/2023	replaced pm	sensor				
Labor					Rate	То
Date:	Mechanic	Description		Hours	Nate	
11/10/2023		Exhaust After-treatment Dev	rices, WORN			
11/10/2023		Exhaust After-treatment Dev	rices			
Parts				O4.	Unit Price	Tot
Date:	Part ID	Description	After Mkt	Qty	Unit Price	
11/10/2023	24307015	Sensor - Exhaust After-treat Particulate Trap Differenti (V	ment OLVO)			77
Section:	18	Complaint Director	nents:	7.5-1		
Priority:	5	Rep Reason: PM FOLLOW-UP				
Component:		Unit War: None				
Cab & Sheet		NTV				
War. Type:	NO WARRA	MIT				
Comments						
Date:	Comment Text			- Company		1 - 1
11/13/2023	added p clam	ps to hold fan clutch wiring from rubbing [Al	DKAND]			
Labor						
Date:	Mechanic	Description	come win tenth and	Hours	Rate	Total
11/10/2023		Cab & Sheet Metal				
11/13/2023		Cab & Sheet Metal, CRACKED),			
Parts						
Date:	Part ID	Description	After Mkt	Qty	Unit Price	Total
11/10/2023	994945	Clip - Visor	_ substant com-			
Section:	19	Complaint: BROKEN Comm	nents:			
Priority:	5	Rep Reason: PM FOLLOW-UP				NA.
Component:	002-002	Unit War: None				
Fenders War. Type:	NO WARRA	NTY			10000 1000	
				PROUD OF	17 (20 Care)	
Comments						
Date:	Comment Text					

Generated by: wilson Version: 19.41.35 Page: 10 5/1/2024 5:58:23 PM