

Invoice

Date	Invoice #
11/4/2024	553g

P.O. No.	Terms	Project
R5500 Seat/Interior	Net 7	

Quantity	Description	Rate	Amount
4.5	Shop Rate Labor 1 Husky Weather Proof Floor Mat Kit Front/Rear 1 Passenger Front Lower Seat Cushion 1 Passenger Front Lower Seat Upholstery 1 Driver Front Lower Seat Cushion 1 Driver Front Lower Seat Upholstery Service Report 11/4/24 2011 Ram 5500HD Vin: 3D6WU7CL4BG614393 Mileage: 161,159 Removed front driver and passenger seat. Pull seats apart and separate lower cover off both seats and trim pieces. Removed handle for seat adjustments. Pull all clips and retainers. Remove lower seat foam. Install new seat foam on each seat. Install new seat Upholstery for each seat. Reassemble both seats. Reinstall both seats back into truck. Place new floor liners in truck. Sales Tax		
Total			\$1,396.98

Invoice

Date	Invoice #
10/7/2024	548g

P.O. No.	Terms	Project
R5500 Brakes/ Diffs	Nct 7	

Quantity	Description	Rate	Amount
8.5	Shop Rate Labor 10/7/24		
2	Brake Pads Heavy Duty Bosch Front and Rear Set		
1	Park Brake Pad Kit with Hardware		
2	OEM Mopar/Timken Bearing Set (inner, outer, races)		
12.5	75/140w Full Syn Amsoil Diff Lube Front 5 qts and Rear 7qts Differential Flush		
1	Gasket Maker Tube RTV Black		
	Service Report 10/7/24		
	2011 Ram 5500		
	Vin: 3D6WU7CL4BG614393		
	Mileage: 160,989		
	Inspected Truck for brake work. Park brake arrived inop, pad life 15%, flush and fill rear and front diff. Removed wheel/tires. Removed front calipers. Set pistons in calipers back and installed new pads. Disks are in good servicable shape. Pulled Duals and pulled rear end down to spinles. Replace inner seals, replaced all bearings and races. Replaced park brake assembly and hardware. Reinstalled hubs. Set new bearins to spicer oem for new bears. Reinstalled brakes. Freed stuck brake pin/ slides and greased unit with antisieze. Reinstalled Tires.		
	Pulled front diff cover inspected, reinstalled and filled with syn diff fluid.		
	Drain rear axle, replaced fluid with new synthetic tipped truck side to side to prefill both rear spindles on full float axle.		
	Sales Tax		
		Total	\$1,980.83

Invoice

Date	Invoice #
10/15/2024	549g

P.O. No.	Terms	Project
R5500 Service Work	Net 7	

Quantity	Description	Rate	Amount
7.25	Shop Rate Labor 10/15/24 1 Transmission Heavy Duty Filter/ Gasket Set 1 Cummins OE Crankcase Filter 12 Engine Oil Cummins Delo Syn 15/40 CJ4 1 Wix XP Syn Oil Filter Heavy Duty 0.5 Grease Tricon xd extreme pressure moly 1 Wix Air Filter 3 Mopar Tcase Fluid Atf +4 1 Wix Primary Fuel Filter 1 Service Report 10/15/24 2011 Ram 5500 HD Vin: 3D6WU7CL4BG614393 Mileage: 161,086 Service Remaining Fluids on Truck. Change Engine Oil, Change Air filter, Replace Transfer Case Fluid. Change Primary fuel filter/ ORing. Replace and extract broken exhaust stud with extra from shop. Pull Transmission pan for filter replacement and fluid replacement. Cleaned magnet (found no abnormal debris.) Replaced Transmission fluid. Greased truck chassis. Replace CCV Filter with OEM Cummins. Replace Upper Valve Cover Gasket Sales Tax		
		Total	\$1,648.74

Invoice

Date	Invoice #
10/16/2024	550g

P.O. No.	Terms	Project
R5500 Tires/Wheels	Net 7	

Quantity	Description	Rate	Amount
1	Tire Mount and Dismount 16ply X6		
6	GreenMax 16ply GDR202 245/70R19.5 135/133M All Season Tires		
1	Wheel Cover 19.5 Set 10lug Polished		
	Service Report 10/16/24		
	2011 Ram 5500HD		
	Vin: 3D6WU7CL4BG614393		
	Mileage: 161,092		
	Mount and Dismount New Tires Reinstall on truck. Install Wheel Cover Package		
	Torque wheels to spec		
	Sales Tax		
		Total	\$1,845.00

Invoice

Date	Invoice #
10/21/2024	551g

P.O. No.	Terms	Project
R5500 Light Update	Net 7	

Quantity	Description	Rate	Amount
7.25	<p>Shop Rate Labor 10/21/24</p> <p>1 Led Marker Lights (Top Cab) X5</p> <p>5 Led Marker Lights (Rear Flatbed)</p> <p>2 Headache Rack Reverse Lights LED</p> <p>4 Headache Rack Turn Signal/Brake Lights LED</p> <p>4 Rear Flatbed Brake/Turn Lights LED square</p> <p>2 Rear Flatbed Reverse Lights square</p> <p>1 Headlight Assemblies X2</p> <p>1 Chrome Group Package Heated and Led Light Mirrors (Driver/ Passenger)</p> <p>1 Window Trim/ Weather Strip Moldings</p> <p>Service Report 10/21/24</p> <p>2011 Ram 5500HD</p> <p>Vin: 3D6WU7CL4BG614393</p> <p>Mileage: 161,108</p> <p>Truck in shop for update on lighting to all led. Replaced all bed led marker lights. Removed and replaced rear bed turn signal/brake light assemblies. Removed and installed rear most back up lights with LED Units. Removed and installed new weatherstripping. Removed and installed new cab clearance lights. Installed new LED Lights in headache rack- installed 4 turn/brake lights, and two reverse</p> <p>Removed and installed new power/ heated/ led turn signal mirrors.</p> <p>Removed bumper/grill guard for access to headlight assy, removed and replaced headlights with new units. Aimed lights in same location as factory. Installed all removed during disassembly.</p> <p>Sales Tax</p>		
		Total	\$1,733.34

Invoice

Date	Invoice #
10/21/2024	552g

P.O. No.	Terms	Project
R5500 Exterior Up...	Net 7	

Quantity	Description	Rate	Amount
6.25	<p>Shop Rate Labor</p> <p>1 Black 5500 Emblem Package</p> <p>1 Gooseneck Ball Replacement</p> <p>1 Gooseneck Trailer Wiring Connector Hopkins</p> <p>1 Bumper Trailer Wiring Connector Hopkins</p> <p>Service Report 10/21/24</p> <p>2011 Ram 5500 HD</p> <p>Vin: 3D6WU7CL4BG614393</p> <p>Mileage: 161109</p> <p>Replace both trailer wiring connectors with updated Hopkins weatherproof units.</p> <p>Replace gooseneck hitch in bed and torque to spec. Test all wiring functions on trailer to verify.</p> <p>Remove old chrome emblem package and replace with black. Clean and buff area under. Center and apply new emblems.</p> <p>Cut and Remove all non need service racks and extras from bed, lube all locks. Flush grind all areas. Prime surfaces</p> <p>Sales Tax</p>		
Total			\$1,103.46

Invoice Date: Dec 9, 2024
Due Date: Dec 9, 2024

BILL TO
hendersonequipmentservices@outlook.com

#	ITEMS & DESCRIPTION	QTY/HRS	
1	Ceramic Coating - Car/Sedan Ceramic Coating Buff/Polish	3	
2	Full Interior Detail - Truck	3	
3	Window Ceramic Coating	1	
		Subtotal	
		TOTAL	\$2,350.00 USD