

					VIN
2006	Peterbilt	379			1XP5DB9X56D898245

QTY	DESCRIPTION	LINE TOTAL
	Pulled Motor Out Did front and rear Structure Took head to machine shop to get rebuilt Outer Frame Over Haul Machine Shop Out Of Frame Gasket Customer Provided Overhaul Kit Labor	
	TOTAL	\$ 9,650.00

Invoice INV-7405
Date: 3/29/2024

no # 13

Purchase Order

Line	Part #	Description	Quantity	UOM	Rate	Amount
1	C15103-010	KIT, ENG, INFRAME acert	1	ea		

Total \$4,044.71

Customer Signature: _____

Printed Name: _____ Date: _____

Invoice

INV-7575

Date:

4/11/2024

Truck #13

Purchase Order

Line	Part #	Description	Quantity	UOM	Rate	Amount
1	390091X	REMANUFACTURED FUEL INJECTOR ASSEMBLY	6			
2	Inherent Core for 390091X	Inherent Core for REMANUFACTURED FUEL INJECTOR ASSEMBLY	6			
Total						\$6,336.12

Customer Signature: _____