

Invoice

Date	Invoice #
12/13/2024	9302



P.O. Number

Due Date

Project

mack

12/13/2024

Quantity

Item Code

Description

Price Each

Amount

1 computer charge
12 Labor

diagnose ABS
Found Bad wire to left front modulator valve and repaired,
rewired load sensors for hill assist to get rid of codes,
recalibrate all modules for Abs
harnesses and sensors from Mack

100.00T
1,344.00T

1 parts
1 Freight

Sales Tax

425.00T
80.00T
136.43

Total

\$2,085.43