

| CUSTOMER NUMBER | | CUSTOMER PO NUMBER | | JOB NAME / RELEASE NUMBER | | SALESPERSON | | |
|-----------------|----------|--|----------|---------------------------|-------|-------------|------------|------------|
| | | | | | | | | |
| WRITER | | | SHIP VIA | | TERMS | | SHIP DATE | ORDER DATE |
| | | | SERVICE | | | | 03/07/2024 | 12/14/2023 |
| ORDER QTY | SHIP QTY | DESCRIPTION | | | TC | UNIT PRICE | EXT PRICE | |
| 1ea | 1ea | N/A ^1674-0868 Service Work TruckMount PROCHEM PEAK TM ----- SER#:1000114162 HOURS:3758.1 - HOSE SPLIT - MACHINE FROZE - GO OVER MACHINE ----- ****NOTE: TO OWNER/OPERATOR**** CHECK ENGINE OIL AND OTHER FLUID LEVELS DAILY. ADJUST TO PROPER LEVELS AS NEEDED. Serial #: 1000114162 | | | T | | | |
| 1ea | 1ea | N/A ^1687-1459 HOSE, HIGH PSI 17" | | | T | | | |
| 1ea | 1ea | 1687-1459 Miscellaneous Hardware / Shop Supplies for Sales ONLY | | | T | | | |
| 1hr | 1hr | N/A ^1617-3700 LABOR BRIAN H - LABOR TO SETUP AND INSPECT - CONFIRM HOSE SPLIT FROM PUMP TO MANIFOLD - REMOVE AND REPLACE BAD HOSE - TEST AFTER | | | T | | | |

| CUSTOMER NUMBER | | CUSTOMER PO NUMBER | | JOB NAME / RELEASE NUMBER | | SALESPERSON | | |
|-----------------|----------|--|----------|---------------------------|-------|-------------|------------|------------|
| | | | | | | | | |
| WRITER | | | SHIP VIA | | TERMS | | SHIP DATE | ORDER DATE |
| | | | SERVICE | | | | 03/07/2024 | 12/14/2023 |
| ORDER QTY | SHIP QTY | DESCRIPTION | | | TC | UNIT PRICE | EXT PRICE | |
| 2ea | 2ea | 1667-2329 SPARK PLUG - RC14YC 25HP KOHLER AEGIS **** Item Not Returnable **** | | | T | | | |
| 1ea | 1ea | 1687-1459 Miscellaneous Hardware / Shop Supplies for Sales ONLY | | | T | | | |
| 2hr | 2hr | N/A ^1617-3700 LABOR BRIAN H - LABOR TO SETUP AND TEST - ENGINE RUNS ROUGH - CHECK PLUGS - WRONG SPARK PLUGS IN ENGINE - INSTALL NEW PLUGS - WITH WRONG PLUGS INSTALLED - THREADS CLOGGED WITH CARBON AND SOOT FROM COMBUSTION - CHASE THREADS ON ENGINE TO ALLOW FOR SPARK PLUGS TO SEAT - SETUP AND TEST AGAIN - ENGINE RUNS BETTER BUT MANY ISSUES WITH MACHINE - HEAT EXCHANGER LEAKS WATER BAD - ENGINE LEAKING OIL VERY BAD FROM BACK - NO PSI GUAGE OPERATIRON | | | T | | | |

| CUSTOMER NUMBER | | CUSTOMER PO NUMBER | | JOB NAME / RELEASE NUMBER | | SALESPERSON | | |
|-----------------|----------|---|----------|---------------------------|-------|-------------|------------|------------|
| | | | | | | | | |
| WRITER | | | SHIP VIA | | TERMS | | SHIP DATE | ORDER DATE |
| | | | SERVICE | | | | 03/07/2024 | 12/14/2023 |
| ORDER QTY | SHIP QTY | DESCRIPTION | | | | TC | UNIT PRICE | EXT PRICE |
| 1ea | 1ea | 1694-2625 GASKET HEAT EXCHANGE COVER, NEW GEN FITS ALL NEW GENERATION PROCHEM 117170 **** Item Not Returnable **** | | | | T | | |
| 1ea | 1ea | 1696-2829 ASSY, HEATER CORE COPPER, GT 100900 FOR BLAZER GT, LEGEND GT, PEAK GT AND APEX GT | | | | T | | |
| 1ea | 1ea | 1687-1459 Miscellaneous Hardware / Shop Supplies for Sales ONLY | | | | T | | |
| 2hr | 2hr | N/A ^1617-3700 LABOR BRIAN H - LABOR TO REMOVE AND TEST HEAT EXCHANGERS - CONFIRM THAT FRONT COPPER HEAT EXCHANGER WAS SHOT - REMOVE AND REPLACE BAD HEAT EXCHANGER. ALSO CLEAN FRONT SS HEAT EXCHANGER AS WELL - REINSTALL AND TEST - NO MORE LEAKS FROM MACHINE AT THIS TIME | | | | T | | |
| 1ea | 1ea | 1648-0079 STARTER SHIFT KOHLER **** Item Not Returnable **** | | | | T | | |
| 1ea | 1ea | 1687-1459 Miscellaneous Hardware / Shop Supplies for Sales ONLY | | | | T | | |

| CUSTOMER NUMBER | | CUSTOMER PO NUMBER | | JOB NAME / RELEASE NUMBER | | SALESPERSON | | |
|---|----------|--|----------|---------------------------|-------|-------------|------------|------------|
| | | | | | | | | |
| WRITER | | | SHIP VIA | | TERMS | | SHIP DATE | ORDER DATE |
| | | | SERVICE | | | | 03/07/2024 | 12/14/2023 |
| ORDER QTY | SHIP QTY | DESCRIPTION | | | | TC | UNIT PRICE | EXT PRICE |
| 1hr | 1hr | N/A | | | | T | | |
| | | ^1617-3700 LABOR BRIAN H | | | | | | |
| | | - LABOR TO REMOVE AND REPLACE BAD STARTER | | | | | | |
| | | - BEFORE TESTING TO FIND ANY MORE LEAKS AFTER PREVIOUS REPAIRS - | | | | | | |
| | | UNIT WOULD NOT START - INSPECT | | | | | | |
| | | - FOUND STARTER SHOT | | | | | | |
| | | - REMOVE AND REPLACE BAD STARTER | | | | | | |
| 1ea | 1ea | 1628-2131 | | | | T | | |
| | | SAPPHIRE 117185 GAUGE WATER | | | | | | |
| | | PRESSURE 1500PSI | | | | | | |
| 15mn | 15mn | N/A | | | | T | | |
| | | ^1617-3700 LABOR BRIAN H | | | | | | |
| | | - LABOR TO REPLACE BAD PSI GUAGE | | | | | | |
| Prior Deposit on 03/07/2024 | | | | | | | -1852.10 | |
| Signature: _____ I agree to pay above total amount according to card issuer agreement. | | | | | | | | |

| | |
|-------------|----------|
| Subtotal | |
| S&H Charges | |
| Tax | |
| Pay/Adj | -1852.10 |
| Amount Due | - - - |

** REPRINT ** REPRINT ** REPRINT **