

DATE	02/26/2025	TOTAL PAGES	3	INCLUDING COVER
TO				
EMAIL				
FROM				
SUBJECT	INVOICE			

Invoice Reprint

INVOICE #	05306437
LOCATION	05
DATE	08/06/24
PAGE	1 OF 2
ACCOUNT#	



ORDER NUMBER 05353905	ORDER DATE 07/05/24	JOB NUMBER	CUSTOMER P/O NUMBER	FREIGHT TERMS Allow
WRITTEN BY			CONTACT	SHIP VIA Customer Pickup
PAYMENT TERMS Cash, Check, or Bank Card				F.O.B.

PRODUCT/DESCRIPTION	QUANTITY OPEN	QUANTITY SHIPPED	QUANTITY BACKORDERED	PRICE	U/M	EXTENSION
---------------------	---------------	------------------	----------------------	-------	-----	-----------

Model : E32-M
 BOBCAT COMPACT EXCAVATOR
 Ein: 1037698 Serial#: A94H13700 Meter: 6898

-----> Description Of Repair Job A <-----
 Customer purchased the machine from Purple Wave.

Machine came into Tulsa shop prior to auction with complaint of no drive power on the RH side. Drive motor was disassembled and found a crack - unsure of where. Customer claims the drive motor has since been disassembled and repaired. Machine was noted to have a leak at the swivel and due for a full service.

Customer had the machine running and driving, but it now will not unlock any of the functions. The machine will start, but will not move.

Check over and quote all repairs.

\$5500 FOR PUMP REPLACEMENT APPROVED BY JONNY

-----> Solution Of Repair Job A <-----
 Checked over the machine and found active hydraulic filter plugged codes. The filter was leaking around the head seal, but did not appear to be plugged. Removed and replaced the filter and tested. Technician found roughly 10psi coming from the pump to the controls, little to no pressure was found going to any of the functions of the machine. Direct tested the pump and found around 300psi coming from the pump. Removed the counterweight from the machine and began removing the hydraulic pump. Removed the pump from the machine and found a grinding noise when rotating the pump by hand. Installed a new pump and refilled with

Continued

Invoice Reprint

INVOICE #	
LOCATION	05
DATE	08/06/24
PAGE	2 OF 2
ACCOUNT#	



ORDER NUMBER	ORDER DATE 07/05/24	JOB NUMBER	CUSTOMER P/O NUMBER	FREIGHT TERMS Allow
WRITTEN BY			CONTACT	SHIP VIA Customer Pickup
PAYMENT TERMS Cash, Check, or Bank Card				F.O.B.

PRODUCT/DESCRIPTION	QUANTITY OPEN	QUANTITY SHIPPED	QUANTITY BACKORDERED	PRICE	U/M	EXTENSION
---------------------	---------------	------------------	----------------------	-------	-----	-----------

hydraulic oil. Completed a pump test with the new pump, adjusting the load sense and main relief pressure. Tested all functions, finding no further issues at this time. Reinstalled counterweight and washed the machine.

Swivel is still leaking at this time, a small but fairly steady leak. The blade cylinder is leaking and will need resealed in the future. Customer ok@d taking the machine as is and running it, addressing the leaks at a later date.

7025227	1	1	0			
PUMP, HYD PISTO						
6670757	1	1	0			
COUPLER, FLANGE						
6668819	1	1	0			
HYDRAULIC FILTER HI-FLOW						
PTS-FREIGHT	1	1	0			
FREIGHT						
LABOR						
Check Tendered # 1110						5778.99

PAID

MERCHANDISE TOTAL	FREIGHT & MISC	TAX	TOTAL CHARGES	DEPOSIT BALANCE	DEPOSIT APPLIED	DEPOSIT AMOUNT	INVOICE TOTAL
							5,778.99
					KANSAS - KANSAS - SEDGWICK - SEDGWICK -		

Returns for credit of parts and supplies must be returned with invoice copy within 15 days of purchase, must be in new and salable condition and will be subject to a restocking charge. Special order, special use, and non-stocking items may be deemed non-returnable. Electrical components are not returnable if package is opened.