Sales Ticket

SO#

Date 01/03/2025

Writer

Page 1 of 2

Invt:Cust 15:15

Cust acct#

Cust PO#

Sold

to:

Ship to:

Vehicle info: Year/Make/Model 2015 / OTHER / T880 Cust Unit # VIN/Short VIN 1XKZDP9X6FJ443135 / FJ443135 Miles/Hours 486016 / 0 Repair Order no. RO - RO-0305783 Operation # 1 TRANSMISSION DOES NOT HAVE HIGH RANGE - SEE NOTES ON HARDCARD PULL TRUCK INTO SHOP, RAISE TRUCK (SAVED OIL), DRAIN TRANSMISSION, REMOVE DRIVELINE, HYD PUMP, COOLER & LINE, CLUTCH SLAVE CYLINDER, DISCONNECT AIR LINES, SHIFT LEVER & TOWER ASSY, REMOVE TRANSMISSION FROM TRUCK & TAKE TO GEAR SHOP FOR INSPECTION & REPAIR. NOTE: CUSTOMER JUST INSTALL NEW CLUTCH (MANUAL ADJUST CLUTCH). REINSTALL REPAIRED TRANSMISSION WITH NEW BOLTS, REINSTALL SHIFT LEVER & TOWER ASSY, RECONNECT AIR LINES, REINSTALL CLUTCH SLAVE CYLINDER, COOLER & LINES, HYD PUMP, & DRIVELINE WITH NEW U-	Contact		Payment terms Due on the 10th	Ship via	None Specified46
VIN/Short VIN 1XKZDP9X6FJ443135 / FJ443135 Miles/Hours	Contact phone		Primary phone		Prepay and Add
Repair Order no. RO - RO-0305783 Operation # 1 Condition TRANSMISSION DOES NOT HAVE HIGH RANGE - SEE NOTES ON HARDCARD Correction PULL TRUCK INTO SHOP, RAISE TRUCK (SAVED OIL), DRAIN TRANSMISSION, REMOVE DRIVELINE, HYD PUMP, COOLER & LINE, CLUTCH SLAVE CYLINDER, DISCONNECT AIR LINES, SHIFT LEVER & TOWER ASSY, REMOVE TRANSMISSION FROM TRUCK & TAKE TO GEAR SHOP FOR INSPECTION & REPAIR. NOTE: CUSTOMER JUST INSTALL NEW CLUTCH (MANUAL ADJUST CLUTCH). REINSTALL REPAIRED TRANSMISSION WITH NEW BOLTS, REINSTALLS SHIFT LEVER & TOWER ASSY, RECONNECT AIR LINES, REINSTALL CLUTCH SLAVE CYLINDER, COOLER & LINES, HYD PUMP, & DRIVELINE WITH NEW UJOINT STRAP KIT, REFILL TRANSMISSION WITH FLUID THAT WAS DRAINED. INSTALL FLOOR COVER PANEL THAT CUSTOMER HAD REMOVED PREVIOUSLY, TEST DRIVE, CHECK FOR LEAKS, ALL CHECKS GOOD AT THIS TIME. NOTE: CLUTCH HAS APPROX 2" OF FREE TRAVEL. WO-0402518:BEARINGS IN PTO FELL APART INSTALLED SEAL KIT REPLACED DAMAGED BEARINGS REPLACED DEAKING AIR INPUT FITTING WO-0402028:REPLACED DAMAGED BEARINGS REPLACED DAMAGED SYNCHRO INSPECTED LID ASSEMBLY TO SEE IF THERE WAS DAMAGE CAUSING HI/LO SHIFTING ISSUE (NONE FOUND). REPLACED SEVERELY DAMAGED MAID DRIVE/OVERDRIVE GEARS & CLUTCH REPLACED SEVERELY DAMAGED MAID DRIVE/OVERDRIVE GEARS & CLUTCH REPLACED SEVERELY DAMAGED MAID DRIVE/OVERDRIVE GEARS IN BOTH HIGH & LOW RANGES.	Vehicle info:	Year/Make/Model	2015 / OTHER / T880	Cust Unit #	
Condition TRANSMISSION DOES NOT HAVE HIGH RANGE - SEE NOTES ON HARDCARD PULL TRUCK INTO SHOP, RAISE TRUCK (SAVED OIL), DRAIN TRANSMISSION, REMOVE DRIVELINE, HYD PUMP, COOLER & LINE, CLUTCH SLAVE CYLINDER, DISCONNECT AIR LINES, SHIFT LEVER & TOWER ASSY, REMOVE TRANSMISSION FROM TRUCK & TAKE TO GEAR SHOP FOR INSPECTION & REPAIR. NOTE: CUSTOMER JUST INSTALL NEW CLUTCH (MANUAL ADJUST CLUTCH). REINSTALL REPAIRED TRANSMISSION WITH NEW BOLTS, REINSTALL SHIFT LEVER & TOWER ASSY, RECONNECT AIR LINES, REINSTALL CLUTCH SLAVE CYLINDER, COOLER & LINES, HYD PUMP, & DRIVELINE WITH NEW UJOINT STRAP KIT, REFILL TRANSMISSION WITH FLUID THAT WAS DRAINED. INSTALL FLOOR COVER PANEL THAT CUSTOMER HAD REMOVED PREVIOUSLY, TEST DRIVE, CHECK FOR LEAKS, ALL CHECKS GOOD AT THIS TIME. NOTE: CLUTCH HAS APPROX 2" OF FREE TRAVEL. WO-0402518:BEARINGS IN PTO FELL APART INSTALLED SEAL KIT REPLACED DAMAGED BEARINGS REPLACED LEAKING AIR INPUT FITTING WO-0402028:REPLACED DAMAGED REDUCTION GEAR REPLACED DAMAGED SYNCHRO INSPECTED LID ASSEMBLY TO SEE IF THERE WAS DAMAGE CAUSING HI/LO SHIFTING ISSUE (NONE FOUND). REPLACED SEVERELY DAMAGED MAID DRIVE/OVERDRIVE GEARS & CLUTCH REPLACED SEVERELY DAMAGED INPUT SHAFT RAN UNIT IN DYNO, UNIT SHIFTED GOOD THROUGH ALL GEARS IN BOTH HIGH & LOW RANGES.		VIN/Short VIN	1XKZDP9X6FJ443135 / FJ443135	Miles/Hours 48601	6/0
PULL TRUCK INTO SHOP, RAISE TRUCK (SAVED OIL), DRAIN TRANSMISSION, REMOVE DRIVELINE, HYD PUMP, COOLER & LINE, CLUTCH SLAVE CYLINDER, DISCONNECT AIR LINES, SHIFT LEVER & TOWER ASSY, REMOVE TRANSMISSION FROM TRUCK & TAKE TO GEAR SHOP FOR INSPECTION & REPAIR. NOTE: CUSTOMER JUST INSTALL NEW CLUTCH (MANUAL ADJUST CLUTCH). REINSTALL REPAIRED TRANSMISSION WITH NEW BOLTS, REINSTALL SHIFT LEVER & TOWER ASSY, RECONNECT AIR LINES, REINSTALL CLUTCH SLAVE CYLINDER, COOLER & LINES, HYD PUMP, & DRIVELINE WITH NEW UJOINT STRAP KIT, REFILL TRANSMISSION WITH FLUID THAT WAS DRAINED. INSTALL FLOOR COVER PANEL THAT CUSTOMER HAD REMOVED PREVIOUSLY, TEST DRIVE, CHECK FOR LEAKS, ALL CHECKS GOOD AT THIS TIME. NOTE: CLUTCH HAS APPROX 2" OF FREE TRAVEL. WO-0402518:BEARINGS IN PTO FELL APART INSTALLED SEAL KIT REPLACED DAMAGED BEARINGS REPLACED DAMAGED BEARINGS REPLACED LEAKING AIR INPUT FITTING WO-0402028:REPLACED DAMAGED REDUCTION GEAR REPLACED DAMAGED SYNCHRO INSPECTED LID ASSEMBLY TO SEE IF THERE WAS DAMAGE CAUSING HI/LO SHIFTING ISSUE (NONE FOUND). REPLACED SEVERELY DAMAGED MAIN DRIVE/OVERDRIVE GEARS & CLUTCH REPLACED SEVERELY DAMAGED INPUT SHAFT RAN UNIT IN DYNO, UNIT SHIFTED GOOD THROUGH ALL GEARS IN BOTH HIGH & LOW RANGES.	Repair Order no.	RO - RO-0305783	Operation # 1		
COOLER & LINE, CLUTCH SLAVE CYLINDER, DISCONNECT AIR LINES, SHIFT LEVER & TOWER ASSY, REMOVE TRANSMISSION FROM TRUCK & TAKE TO GEAR SHOP FOR INSPECTION & REPAIR. NOTE: CUSTOMER JUST INSTALL NEW CLUTCH (MANUAL ADJUST CLUTCH). REINSTALL REPAIRED TRANSMISSION WITH NEW BOLTS, REINSTALL SHIFT LEVER & TOWER ASSY, RECONNECT AIR LINES, REINSTALL CLUTCH SLAVE CYLINDER, COOLER & LINES, HYD PUMP, & DRIVELINE WITH NEW UJOINT STRAP KIT, REFILL TRANSMISSION WITH FLUID THAT WAS DRAINED. INSTALL FLOOR COVER PANEL THAT CUSTOMER HAD REMOVED PREVIOUSLY, TEST DRIVE, CHECK FOR LEAKS, ALL CHECKS GOOD AT THIS TIME. NOTE: CLUTCH HAS APPROX 2" OF FREE TRAVEL. WO-0402518:BEARINGS IN PTO FELL APART INSTALLED SEAL KIT REPLACED DAMAGED BEARINGS REPLACED DAMAGED BEARINGS REPLACED LEAKING AIR INPUT FITTING WO-0402028:REPLACED DAMAGED REDUCTION GEAR REPLACED DAMAGED SYNCHRO INSPECTED LID ASSEMBLY TO SEE IF THERE WAS DAMAGE CAUSING HI/LO SHIFTING ISSUE (NONE FOUND). REPLACED SEVERELY DAMAGED MAIN DRIVE/OVERDRIVE GEARS & CLUTCH REPLACED SEVERELY DAMAGED MAIN DRIVE/OVERDRIVE GEARS & CLUTCH REPLACED SEVERELY DAMAGED INPUT SHAFT RAN UNIT IN DYNO, UNIT SHIFTED GOOD THROUGH ALL GEARS IN BOTH HIGH & LOW RANGES.	Condition	TRANSMISSION DOE	S NOT HAVE HIGH RANGE - SEE NOTES	ON HARDCARD	
	Correction	COOLER & LINE, CLU TRANSMISSION FROM NOTE: CUSTOMER JU REINSTALL REPAIRED AIR LINES, REINSTALL JOINT STRAP KIT, REI CUSTOMER HAD REM NOTE: CLUTCH HAS A WO-0402518:BEARIM INSTALLED SEAL KIT REPLACED DAMAGEN REPLACED LEAKING A WO-0402028:REPLAC REPLACED DAMAGEN INSPECTED LID ASSEN CAUSING HI/LO SHIF REPLACED SEVERELY REPLACED SEVERELY RAN UNIT IN DYNO, IN BOTH HIGH & LON	TICH SLAVE CYLINDER, DISCONNECT AIR M TRUCK & TAKE TO GEAR SHOP FOR IN JST INSTALL NEW CLUTCH (MANUAL AID D TRANSMISSION WITH NEW BOLTS, RE L CLUTCH SLAVE CYLINDER, COOLER & FILL TRANSMISSION WITH FLUID THAT IN MOVED PREVIOUSLY, TEST DRIVE, CHECK APPROX 2" OF FREE TRAVEL. NGS IN PTO FELL APART D BEARINGS AIR INPUT FITTING CED DAMAGED REDUCTION GEAR D SYNCHRO MBLY TO SEE IF THERE WAS DAMAGE TING ISSUE (NONE FOUND). T DAMAGED MAIN DRIVE/OVERDRIVE OF D DAMAGED INPUT SHAFT UNIT SHIFTED GOOD THROUGH ALL GE W RANGES.	R LINES, SHIFT LEVER & TO NSPECTION & REPAIR. DJUST CLUTCH). IINSTALL SHIFT LEVER & TO LINES, HYD PUMP, & DRIV WAS DRAINED. INSTALL FL CK FOR LEAKS, ALL CHECKS	OWER ASSY, REMOVE OWER ASSY, RECONNECT ELINE WITH NEW U- OOR COVER PANEL THAT

Part number	Description	Ord	Del	B/O	List Price	Unit price	Ext. price
110_4305294	GSKT SHIFT LEVER	1	1	0			
110_WA4302427	PREMIUM AUX REDUCTION GEAR	1	1	0			
110_K3420	UPDATE KIT INPUT & M D GEAR	1	1	0			

Sales Ticket

SO#

Date 01/03/2025

Writer

Invt:Cust 15:15	Cust acct# Cu	ist PO#				Page	
029_BS226539V	ROLLER BEARING		1	1	0		
110_K2921	GASKET KIT		1	1	0		
110_4306650B	SLIDING CLUTCH		1	1	0		
110_4302082	SNAP RING		1	1	0		
17_N6.5-4-4631-1	END YOKE (2.794-54SP	L)	1	1	0		
abor							
ported labor from	WO-0402028						
5_30305	TAPER ROLLER BEARIN	G ASSY	1	1	0		
5_30307	TAPER ROLLER BEARIN	G ASSY	1	1	0		
Z_PTSK2000RA	RA-SEAL KIT FOR 2000	SERIES	1	1	0		
oor							
ported labor from	WO-0402518						
0_6.5-70-18X	1710,1760,1810 STRAP	KIT	1	1	0		
3_19162	BOLT - FLNG 7/16-14 X GR8	1-1/2	12	12	0		
RX_665005002080	MYSTIK JT 6 HI-TEMP C GREASE	ART	1	1	0		
bor							

Shop supplies

Total merchandise Total cores

Total labor

Tax amount

Invoice total

\$5,686.14

Received by