

Due Date P.O. No./Mileage

Yr & Make

Eng./Hub Hrs.

Unit/License#

3/10/2025

208,973

MACK

VB2441

Description	Qty.	Rate	List
TMR556 HENDRICKSON TORQUE ROD 14.47 (#844)	2		
TMR545A HENDRICKSON TORQUE ROD 14.41 (#844)	2		
4537-210 MACK SEALED TORQUE ROD 21" OA (#844)	2		
463.DS9829 MACK STEERING CROSS TUBE 60" (#844)	1		
THREADED SPRING EYE BUSHING 3.5" TB69	4		
6M - 90 DEGREE METRIC GREASE FITTING	4		
M5266 SPRING PIN	4		
5/8-11X4-1/2 GRADE 8 HEX HD C/S	12		
5/8" LOCK NUT	12		
5/8" FLAT WASHER	12		
FIR297780 385/65R22.5 FIRESTONE FS818 J/18	2		
WHEEL WEIGHT, PER OUNCE	20		
Subtotal Parts			
REPLACED FRONT SPRING PINS & BUSHINGS.	6		
REPLACED ALL FOUR TRAILING ARMS & BOTH TRACK	6		
BAR ON TANDEMS.			
CHECKED REAR ALIGNMENT & MOVED BOTH AXLES.	1		
ALIGNED FRONT END.	1		
DISMOUNT & REMOUNT TIRE	2		
Subtotal Labor			
Subtotal Parts and Labor			
Shop Supplies & Environmental Fees			

Total

\$5,537.02