

INV-164

9/13/2024

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
SO-1215	COD	9/13/2024				2699
Item	Description	Quantity	Rate	Amount	Boom Truck	
Complaint: Repair crane						
Cause: boom crowd cylinder is bent at pin						
Labor	Correction: Lift / Hydraulic / Resealed winch, removed and installed new hydraulic cylinder, reassembled. Verified crane operable at this time. - Completed: 9/13/2024					
Parts	VB 4 sect w/prop Deltrol 8gpm series - 132279	1.00000				
Parts	Freight - Freight	1.00000				
Parts	Misc - REP	1.00000				
Parts	ATB Cord Reel - 72602	1.00000				
Parts	Freight - Freight	1.00000				
Parts	Cylinder Ext ASM 6620 2.0/2.0 - 49316	1.00000				
Parts	Freight - Freight	1.00000				
Parts	Wear Pad - 9363	2.00000				
Parts	Wear Pad - 6252	4.00000				
Parts	Freight - Freight	1.00000				
Parts	Washer - 0425	2.00000				
Parts	Misc - Misc	1.00000				
Parts	Frght - Rep	1.00000				
				Subtotal	\$12,143.50	