Quantity	Description	Cost	Date: Aug 11, 2023		
1	DDE A4720160121 COVER GASKET		UNIT NUMBER: 1062N		
6	DDE RA4600701087 INJECTOR KIT		ODOMETER READING: 526096		
6	CORE		ENGINE HOURS: 21330		
3	DDE A4700781710 HIGH PRESSURE LINES		Complaint	Tech	
3	DDE A4700781810 HIGH PRESSURE		Replaced all 6 injectors, both injector harnesses, high pressure lines&seals, and the cover gasket		
1	DDE A4721506333 REAR HARNESS		Insert new part#'s and injector codes into the MCM		
1	DDE A4721506233 FRONT HARNES		Replaced the DOC and DPF, along with the stainless steel		İ
6	DDE A4720780273 INJECTOR CUPS		tubes, and rubber hoses		1
6	DDE A0319977345 CUP SEALS		After trying to regen and the doser not kicking in. I replaced		1
4	DDE N00000001068 SEAL RINGS		the doser fuel block, after checking the doser injector		1
1	DDE RA471070055 DOSER METERI		I can perform a doser purge but the doser still wont kick in		1
1	DDE EA0014904092 DPF & CLAMP		during a regen, Salina truck center said the MCM, ACM, and		1
1	CORE		CPC need updated to fix the issue		
1	DDE EA0004900836 DOC & CLAMP		*DOSER CORE		
	CORE				
1	DDE A6804912237&A6804912337				

Quantity	Description	Cost	Date: Oct 11, 2023	
4	ATR PB46 26268 BUSHING		UNIT NUMBER: 1062 C	
8	11-23853-000 U-BOLT KIT		ODOMETER READING:	
4	65148 SHOCK		ENGINE HOURS:	
40	AMN2013014PS WHEEL NUT		Complaint	Tech
	FOLIO# 13-000-888		INSTALL NEW LEAF SPRING BUSHINGS AND SHOCKS ON DRIVE AXLES	
		1	INSTALLED NEW WHEEL NUTS	
			ALIGN TRUCK	
				ł
				+
				+
				ł
10000	Total Parts	724.32	Total	i .
		-		100

Quantity	Description	Cost
1	A4722004251 coolant hose	
1	A4721506333 Injector wire harness	
1	04-29741-000 Fitting	
1	A0014462835 MCM	
1	Core	

Unit Number:	1062 N
Odometer Rea	ding: 553354
Engine Hours:	22703

Check Engine light On, Stop Engine Light On. Hook up lap top, chows code SPN 654/FMI 5, Injectors 4,5,6 Needle control valve circuit open Follow diagnostic tree to install a test MCM, install, clear codes, all codes clear except the DPF absorption code, perform Parked Regen to clear DPF code, half way through the Regen the engine starts to miss out and the Check Engine light came on, hook up lap top, set code SPN 654/FMI 5 only #4 cylinder missing out, go back through trouble tree and decide to install Rear engine injector harness, assemble and drain coolant replace plastic coolant hose to air compressor, fill with coolant perform Parked Regen again, during regen this time Blew off a plastic DEF cooler hose, clean coolant up, repair plastic hose and finish Regen, codes cleared. 25.0

Date:

Tech:

2nd Te

Total T

Total Parts:

E

D

.

tion		Cost	
ness			
r			
		1	
400			
	н		
ax:			
arts Cost:			

Unit Number: 1062 N

Odometer Reading: 553352

Engine Hours: 22703

Comments:

Engine Dies, Check Engine light comes on.
Hook up laptop, shows code 2797, 3 and 2798,
3, both injector wire harness shorted to battery
Has new wire harness installed, has also had
MCM previously installed, advised by Truck
Center to replace Engine wire harness.
Drain cooling system, remove coolant line to
air compressor, remove fuel lines to fuel filter
housing, remove radiator support and bracket
to engine, remove trans. cooler line support
brackets, Remove engine wire harness, install
new harness, assemble engine fill with coolant,
purge fuel system and run engine, drive truck,
engine still dies and sets codes, truck needs to
go the Dealer. 25.0

Submit by Email

Date: 3/25/25 - 3/28/25

Tech

2nd

Tota

Total Parts: 618.27

В	Brakes
C	Chassis
D	Drivetrain
E	Electrical
н	Hydraulic
N	Engine
T	Tires
X	Exhaust