DATE 07/09/2025

DUE DATE 07/09/2025

TERMS Due on receipt

SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
Job Labor	Engine pushing coolant, diagnosed and found bubbles coming from overflow on coolant reservoir. Removed cylinder head and found the head cracked on five cylinders. counter bores were leaking on front side of #2 passenger side of #4 and back side of #6. removed oil pan and piston/ rods. removed liners and confirmed counter bore problem. Upon cleaning crank shaft, we found that it had been scared badly in turn we had to pull engine and strip it to the block to change the crank shaft. installed crank shaft and new bearings new 16:1 piston groups. new cylinder head and new spacer and head bolts were also installed along with a good worked camshaft and new rollers on rocker arms	80		
-Sales	used acert cam shaft			
Sales	used cat fuel pump			
Sales	used mxs engine harness	2		
FBC500	CLAMP 5 " STAINLESS STEEL FLAT BAND (EA)	1		
Sales	CLUTCH BRAKE			
Sales	Cat spacer plate			
PROGRAM	ecm parameter modification			
Shop Supplies	brake clean rags etc.	1		

BALANCE DUE

\$12,183.11

DATE 06/25/2025

DUE DATE 07/01/2025

TERMS Due on receipt

SERVICE

DESCRIPTION

OT

RATE

AMOUNT

Sales Sales new cat cylinder head 3406 head gasket set cat head bolt set

BALANCE DUE

\$5,852.16