

Invoice: 8711

Date: 7/18/2022

| Service Order                              | Terms  | Due Date  | Authorizer | Customer PO | Service Writer | Unit #     |
|--|--|-----------|------------|-------------|----------------|------------|
| 167763                                     | COD  | 7/18/2022 | SPENSER    |             | Wood, Les      | 164        |
| Item                                       | Description  |           |            | Quantity    | Rate           | Amount     |
| Drive to unit                              |  |           |            |             |                |            |
| Labor                                      | Drive to unit (Service Call)   |           |            | 0.00000     |                |            |
| Mileage                                    |  |           |            | 202.00000   |                |            |
| Service Call                               |  |           |            | 1.0000      |                |            |
| Complaint: Service Call-hyrdo line leaking |  |           |            |             |                |            |
| Cause: Customer request                    |  |           |            |             |                |            |
| Labor                                      | Correction:  |           |            | 6.70000     |                |            |
|  | Chassis / Chassis / Got to the unit an pulled the hydraulic line off that was leaking an went to get a new line an hydraulic oil an wheels studs an nuts got back to the unit an installed the new hydraulic line an put 15 gallon of oil in the reservoir then started unit an made sure of no leaks then jacked up the left rear axle an took off the wheels an drum an took out the busted lug studs then installed the new ones put the drum back on then both wheels put tools away dc. - 7/18/2022 |           |            |             |                |            |
| Parts                                      | drive wheel stud   |           |            | 10.00000    |                |            |
| Parts                                      | Flange nut m22-1.5   |           |            | 10.00000    |                |            |
| Parts                                      | Hose end   |           |            | 2.00000     |                |            |
| Parts                                      | Otraw32 hydraulic oil 5 g  |           |            | 3.00000     |                |            |
| Parts                                      | HOSE   |           |            | 5.00000     |                |            |
|  |  |           |            |             | Subtotal       | \$1,955.61 |
| Return from unit                           |  |           |            |             |                |            |
| Labor                                      |  |           |            | 0.00000     |                | \$0.00     |
|  |  |           |            |             | Subtotal       | \$0.00     |

| Item | Description | Quantity | Rate | Amount |
|------|-------------|----------|------|--------|
|------|-------------|----------|------|--------|

Unit: 164 VIN: 1NKDX4EX9FJ440973  
License Plate: |  
2015 Kenworth T8 Series  
Chassis: 460,267 Miles

Labor  
Parts  
Service Call  
Mileage  
Shop Supplies  
Pre Tax Total

Total \$2,528.20  
Payments & Credits \$0.00  
Balance Due \$2,528.20

Invoice: 8124

Date: 5/13/2022

| Service Order | Terms | Due Date  | Authorizer | Customer PO | Service Writer | Unit # |
|---------------|-------|-----------|------------|-------------|----------------|--------|
| 167164        | COD   | 5/13/2022 | TODD       |             |                | 164    |

| Item                 | Description                                | Quantity  | Rate            | Amount          |
|----------------------|--|-----------|-----------------|-----------------|
| <b>Drive to unit</b> |  |           |                 |                 |
| Labor                | Drive to unit (Service Call)               | 0.00000   |                 |                 |
| Mileage              | 3007 Bill Robertson Way, Richmond, KY, USA | 210.00000 |                 |                 |
| Service Call         |  | 1.0000    |                 |                 |
|                      |  |           | <b>Subtotal</b> | <b>\$394.50</b> |

**Complaint:** Service Call 2 STUDS GONE OFF RIGHT REAR. REST ARE LOOSE

**Cause:** Customer request

|   |                               |          |    |
|---|-------------------------------|----------|----|
| Labor   | <b>Correction:</b>            | 10.50000 |    |
| <p>Chassis / Chassis / Arrived on site and collected the unit information. Found the right rear drive wheels loose, 2 lug studs broke, and both wheels along with the hub were destroyed. Had to cut the remaining 8 lug nuts off with the torch. Got the wheels off and pulled the brake drum. Brake drum and shoes are also destroyed. Removed the hub and inspected the spindle. Spindle is in good shape. Loaded up all old parts and went on a parts run to the shop. Matched up all old parts.</p> <p>Took the tires off of the damaged wheels and installed the on new wheels. Informed the tech taking over the job of everything he needs to know to complete the job. took over for Dillon arrive on site with job installed hub Assembly put in cone put in out side bearing put on nut torq to 200 spin retorq at 200 spin cleaned up axle sealed and installed put on brakes prime the hub with two bottles of 75/90 went to put drum on was fitting little tight had to clean in side of drum and buff the brake pads then drum went on mounted wheels adjusted brake picked up tools pay out go back to shop ( Chris ) On Site Road Service Call - 5/13/2022</p> |                               |          |    |
| Parts   | 4709 BRAKE KIT                | 1.00000  |    |
| Parts   | SYN 75W90 PER QT*             | 2.00000  | \$ |
| Parts   | BRAKE DRUM                    | 1.00000  |    |
| Parts   | Dirty Core for 4709 BRAKE KIT | -1.00000 |    |

| Item            | Description                      | Quantity | Rate | Amount            |
|-----------------|----------------------------------|----------|------|-------------------|
| Parts           | Inherent Core for 4709 BRAKE KIT | 1.00000  |      |                   |
| Parts           | 33MM FLANGE LUGNUT               | 10.00000 |      |                   |
| Parts           | NYLON LOCKNUT 5/16-18 US         | 8.00000  |      |                   |
| Parts           | 22.5 HUB PILOT WHEEL 5 HOLE      | 2.00000  |      |                   |
| Parts           | Trifecta Hub                     | 1.00000  |      |                   |
| Parts           | ULTRA GREY                       | 1.00000  |      |                   |
| <b>Subtotal</b> |                                  |          |      | <b>\$3,141.23</b> |

**Return from unit**

|                 |  |         |  |               |
|-----------------|--|---------|--|---------------|
| Labor           | Return from unit                           | 0.00000 |  | \$0.00        |
|                 | 3007 Bill Robertson Way, Richmond, KY, USA |         |  |               |
| <b>Subtotal</b> |  |         |  | <b>\$0.00</b> |

Unit: 164 VIN: 1NKDX4EX9FJ440973

License Plate: (

2015 Kenworth T8 Series

Chassis: 234,895 Miles

**Labor****Parts****Service Call****Mileage****Shop Supplies****Pre Tax Total****Kentucky (6.0000% of \$3,141.23)****Total****Payments & Credits****Balance Due \$3,835.08**

21123

|      |        |               |      |
|------|--------|---------------|------|
| DATE | 2/5/23 | DATE PREPARED | AM   |
| TIME | 5:17,8 | TECH          | SHOP |
| DATE | 2/5/23 | DATE PREPARED | AM   |
| TIME | 5:17,8 | TECH          | SHOP |
| DATE | 2/5/23 | DATE PREPARED | AM   |
| TIME | 5:17,8 | TECH          | SHOP |

Labra Recycling

|           |       |        |     |
|-----------|-------|--------|-----|
| STATE     | MD    | ZIP    |     |
| CITY      | Rolla | STREET |     |
| PHONE NO. |       | TECH   | 164 |
| TECH      | 164   | TECH   | 164 |

VEHICLE MAKE AND MODEL

LOCATION

VEHICLE MAKE AND MODEL

LOCATION

VEHICLE MAKE AND MODEL

LOCATION

VEHICLE MAKE AND MODEL

LOCATION

Drain coolant R/R coolant hose on right side  
 R/R front springs rear hangers. Check out front end  
 Clean axle all parts. Installed bushings in rear hangers  
 Lube entire front end. Clean according to front hangers  
 (10.4) 1300.00

TOTAL PARTS

|                         |  |
|-------------------------|--|
| TOTAL LABOR             |  |
| TOTAL PARTS             |  |
| SUBLET TOTAL            |  |
| GAS, OIL & GREASE TOTAL |  |
| EPA TOTAL               |  |
| SHOP SUPPLIES           |  |

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other causes beyond your control.

SIGNATURE

TOTAL 41818.60



20772

|             |               |        |
|-------------|---------------|--------|
| DATE IN     | DATE PROMISED | A.S.E. |
| 9/14/22     |               | P.M.   |
| OWNER #     | TRUCK #       |        |
|             |               |        |
| BUS, PHONE  | EXT.          |        |
|             |               |        |
| A.S.#       | P.A.#         |        |
|             |               |        |
| LICENSE NO. | 482834        |        |
| TRAILER #   | 164           |        |

AMOUNT:SERVICES REQUESTED / DESCRIPTION OF WORKLOCATION *DM*

R/R marker lights  
 Install slack adjuster on dropax (missing)  
 Install missing shoes hardware - Repair id spring  
 We cup, R/R J-gamabushing (4.4)  
 Put damper clamps off and weld on wire  
 cup lacament clean and prep. (2.0)  
 Adjust clutch (1.5)  
 Check A/C fan d low switch by passed-plugged (1.8)  
 back in A/C line, vac chg leak test passed-charge  
 w/c war King  
 R/R restrictor cans on rear suspension (2.3)

|  |                         |  |
|--|-------------------------|--|
|  | TOTAL LABOR             |  |
|  | TOTAL PARTS             |  |
|  | SUBLET TOTAL            |  |
|  | GAS, OIL & GREASE TOTAL |  |
|  | EPA TOTAL               |  |
|  | SHOP SUPPLIES           |  |
|  | FREIGHT                 |  |
|  | SUBTOTAL                |  |
|  | TAX                     |  |
|  | TOTAL                   |  |

[illegible]

# Invoice

| Date      | Invoice # |
|-----------|-----------|
| 4/26/2022 | 51617     |

|         |
|---------|
| Bill To |
|         |

|   |
|---|
| Description of Work   |
| REPAIR EXCESSIVE SMOKING AS NEEDED<br>R&R OIL PAN & FOUND CYL LINER LEAKING<br>PERFORM IN-FRAME OVERHAUL<br>REPLACE CAMSHAFT & TURBO BAD<br>CHANGE OIL, ANTI-FREEZE & ALL FILTERS |

| Yr/Make/Model | Mileage       | Serial #/Motor # |
|---------------|---------------|------------------|
| KW T-800      | 434,659/18087 | 440973/#164      |

| Item        | Description           | Qty | Rate | Amount |
|-------------|-----------------------|-----|------|--------|
| 369504J     | GASKET                | 1   |      |        |
| M12X1.75X30 | BOLT                  | 1   |      |        |
| ATF         | ATF FLUID             | 3   |      |        |
| 22522       | 50/50 RED ANTI-FREEZE | 15  |      |        |
| WIRE TIES   | WIRE TIES             | 10  |      |        |
| FREIGHT     | FREIGHT               | 1   |      |        |

|  |  |                                |
|--|--|--------------------------------|
|  |  | <b>Subtotal</b>                |
|  |  | <b>Sales Tax (6.0%)</b>        |
|  |  | <b>Total</b>                   |
|  |  | <b>Payments/Credits</b>        |
|  |  | <b>Balance Due</b> \$31,133.43 |



6

**Invoice**

| Date      | Invoice # |
|-----------|-----------|
| 4/26/2022 | 51617     |

|                |
|----------------|
| <b>Bill To</b> |
|                |

|  |
|--|
| <b>Description of Work</b>   |
| REPAIR EXCESSIVE SMOKING AS NEEDED<br>R&R OIL PAN & FOUND CYL LINER LEAKING<br>PERFORM IN-FRAME OVERHAUL<br>REPLACE CAMSHAFT & TURBO BAD<br>CHANGE OIL,ANIT-FREEZE & ALL FILTERS |

| Yr/Make/Model | Mileage       | Serial #/Motor # |
|---------------|---------------|------------------|
| KW T-800      | 434,659/18087 | 440973/#164      |

| Item        | Description  | Qty | Rate                    | Amount |
|-------------|--------------|-----|-------------------------|--------|
| LABOR       | SHOP LABOR   |     |                         |        |
| SHOP SUPPLY | SHOP SUPPLY  |     |                         |        |
| ROTELLA OIL | ROTELLA OIL  | 53  |                         |        |
| P616056     | AIR FILTER   | 1   |                         |        |
| 5693737     | OVERHAUL KIT | 1   |                         |        |
| 5394198RX   | CYL HEAD     | 1   |                         |        |
| RHY6351C    | REMAN TURBO  | 1   |                         |        |
| 4298629     | CAMSHAFT     | 1   |                         |        |
| 5484231     | ROCKER ARM   | 1   |                         |        |
| 2894829     | CONNECTOR    | 6   |                         |        |
| 2872317     | RETAINER     | 6   |                         |        |
| 4965698     | SCREW        | 12  |                         |        |
| 4965512     | SPACER       | 12  |                         |        |
|             |              |     | <b>Subtotal</b>         |        |
|             |              |     | <b>Sales Tax (6.0%)</b> |        |
|             |              |     | <b>Total</b>            |        |
|             |              |     | <b>Payments/Credits</b> |        |
|             |              |     | <b>Balance Due</b>      |        |