Work Order #: 10008

Issued:

3/5/2020

Completed:

6/12/2020

Mileage

0/12/2020

Vendor:

Assigned To: ,

Notes:

133 - 2008 freightliner FLD132

Mileage Unit #:

Tag #:

0

e: TRACTOR

Operator:

Serial #: 1FUJAPCK68DY42054

Repair Maintenance	Туре	Cost
ENGINE OVERHAUL		\$0.00
REPLACE CLUTCH		\$0.00
REPLACE FIFTH WHEEL		\$0.00
Total:		60.00

Part	Name	Used	Unit Cost	Cost
CORE DEPOSITS		1		
DIESEL MACHINE#70531	REMAN 60 SERIES BLOCK	1		
FASTENAL# 197933	FIFTH WHEEL BOLTS	1		
FLEET PRIDE# 50709130	FIFTH WHEEL BUSHINGS AND PINS	1		
FLEET PRIDE# 50741275	FIFTH WHEEL AIR HOSE AND FITTINGS	1		
FLEETPRIDE# 50064562	HOSES AND FITTINGS	1		
FLEETPRIDE# 50373085	CLAMPS	1		
NAPA# 5952-95395	COOLANT HOSE	1		
PENLEY# 132412	LUBRIPLATE	1		
PENLEY# 133683	SYN TRANS OIL 50W	1		
PENLEY# 134435	GUARDOL 15/40 BULK	11		
PREMIER# 120488088	REBUILD KIT	1		
PREMIER# 120488188	VARIOUS HOSES AND CLAMPS	1		
PREMIER# 120489373	CAMSHAFT	1		
PREMIER# 120489374	CLUCH ASSEMBLY	1		
PREMIER# 120495361	ENG BUSHINGS AND GASKETS/ O RINGS	1		
PREMIER# 120495490	HOSE AND SENSOR	1		
PREMIER# 120495676	FILTERS AND BELTS	1		
PREMIER# 120495722	TUBE	1		
PREMIER# 120496810	GASKET	1		
PREMIER# 120498136	FUEL PUMP	1		
PREMIER# 120498136	FUEL PUMP	1		
PREMIER# 120498245	WASHERS AND ELBOW HOSE	1		
PREMIER# 120498544	SEALS AND TUBING	1		
PREMIER# 120499022	HOSE/ TUBE	1		
PREMIER# 120499172	A/C HOSE AND SEALS	1		
PREMIER# 120499779	OIL PUMP AND PICKUP TUBE	1		

Total: Labor Description Hours Rate Cost Disassembled accesory engine components. Removed turbo, radiator, hood, oll pan, cam, front cover and valve cover. Pulled liners and pistons. discovered number four rod bearing had failed and caused damage to crank shaft. Dropped driveline and transmission. Removed crank shaft from block. Discovered block was cracked. Removed block. Performed out of frame rebuild, installed block back into chasis and assembled engine. Installed fly wheel, clutch, transmission and driveline. Mounted hood, radiator and all hoses and accesories.