

250.00

				1000000	
I III I			Service Call Date		
ı	1		12/04/2023	1	
Make	Model	Serial Number	Customer Equipment Number	Equipment Number	Last Meter
T7	PB70.3_T7	N4104880		EQN193271	1.00

Inspect - Hard Starting Problems

Customer complaint:

inspect lift 1. hrs.

Workscope

Resultant damage:

inspect lift

Cause of failure:

inspect lift

Repair process comments:

after running engine coolant flows out of overflow combustion gases going into cooling system, operator said unit got overheated ran hot, then helped customer remove forks that were needed for new lift due to top mount instead of under mount for the piggy back system have motor quoted out for replace ment

Replace - Engine

Customer complaint: replace engine 1 hrs.

Resultant damage:

replace engine

Cause of failure:

replace engine

Repair process comments:

replace engine unhook battery, remove side panels, hood, radiator, overhead guard, and top panel containing hydraulic control valve for access to remove engine out the top, note: aproximatly 8 broken bolts had to be drilled extracted and or nut serts ground off due to bolts broke due to rust and salt spray: replace ecm, filter housing, and catalytic converter that came with engine package, swapped over components, install new engine re connect components, fill with oil and coolant, top off hydraulic level, repalce air filter, start lift, operate lift ok hour meter reset to 1 hrs. ok

Parts

1.00 MMH076.100.0501

ENGINE ASSY.

2.00 MCFVAL15W40G

Valvoline 15

2.00 PRI076.99.0007

MOUNTING, RADIATOR

8,538.31

Extended Price