

Invoice No.

111519

INVOICE**Customer**Name
Address
City
Phone**Misc**Date 11/15/2019
Order No.
Rep
FOB**Qty****Description****Unit Price****TOTAL**1
1Parts
Labor

Sort out partially disassembled transmission components and new parts provided. Sourced needed new, used, and obsolete parts as necessary. Rebuild clutch packs, brake packs, planetary carrier, reduction shaft, pressure regulating valve, transmission/shift control valve, transfer drive gearbox assembly. Reduction shaft preload will need to be set up in transmission case prior to assembly. Pressure regulating valve appears to have excess shims, pressure setting is most likely too high, will have to be checked. Transmission housing passages will need to be cleaned thoroughly, metal from failure was found in components. All clutches and brake packs have been pressure tested.

SubTotal \$
Shipping \$

Tax Rate(s)

6.25% \$

Payment

Select One...

Comments

Name

CC #

Expires

TOTAL \$ 5,202.50

Office Use Only