

Posted Date: 10/29/24 at 01:33 PM CDT

Vehicle: 2017 GMC Sierra 1500 Denali

Time-In: 10/16/24 at 03:22 PM CDT
Save Parts: No

Client concerns:

- TRANSMISSION
- PO-HAYDEN

1 - Remove & Replace Transmission Assembly

Tech: B Wehner

Labor:	Remove & Replace Transmission Assembly With Skid Plate	
	Remove & Replace Rear Crankshaft Oil Seal	
	Flush Trans Oil Cooler Line	
	Programming	
Parts:	TRANSMISSION,AUTOMATIC	1
	GASKET,TRANSFER CASE ADAPTER	1
	SEAL,EXHAUST SYSTEM - RH	1
	SEAL,EXHAUST SYSTEM - LH	1
	Low Vis Automatic Transmission Fluid	10
	Transmission Cooler Flush	1
Fees:	Hazmat	
	Shop Supplies	

✓ Approved on 10/28/24 at 07:56 AM CDT

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Total Repair Order & Signature:

Total Jobs:

Total Fees:

Subtotal:

Taxes:

Grand Total: \$7,259.13

BALANCE DUE:

Completed Transactions