

*** PROFORMA INVOICE ***

Invoice To Account No: 17002072

Deliver To:

SERVICE INVOICE

	{	Invoice Number: Invoice Date: 10/17/2025 Location: Work Order Number: Payment Type: Page: 1 of 4
	{	
	{	
	{	
	{	

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 310TJ	1441	T0310TJ178937	54697W	

/Diagn - 1 Retail

COMPLAINT:

01 DIAG WONT START

CORRECTION:

DIAG -

MACHINE WILL CRANK BUT WILL NOT START .
 I HOOKED UP TO MACHINE WITH SA AND CHECKED CODES AND PULLED UP READINGS AND SAW THAT THE LOW PRESSURE PUMP IS NOT CREATING ANY PRESSURE .
 I INSPECTED THE PUMP AND IT IS NOT RUNNING .
 I CHECKED POWER AND GROUND AT THE PUMP AND I HAVE THAT .
 THE PUMP IS BECOMING HOT WHILE POWER IS ON TO IT.
 THE PUMP HAS FAILED .
 WHEN INSTALLING THE NEW FUEL PUMP I FOUND THAT THE FUEL LINES HAD A THICK VARNISH IN THEM SO I INSPECTED THE FUEL TANK AND FOUND THAT IT ALSO HAD A THICK LAYER OF VARNISH AND DEBRIS IN THE BOTTOM OF IT .
 DRAINED AND REMOVED THE FUEL TANK TO BRING TO THE SHOP FOR CLEANING .
 PULLED THE FUEL SENDER UNIT AND IT WAS PLUGGED WITH THE VARNISH AN TUBES WERE RUSTED OUT

Labor:	Sub-Total: \$440.00
--------	---------------------

/Travel - 1 Retail

COMPLAINT:

CORRECTION:

Miscellaneous	Description	Quantity	Net Price	Extended Price	Taxed Ind
SVCTRUCK	MILEAGE CHARGE	32.00	0.00	\$0.00	Y

Labor:	Sub-Total: \$330.00
--------	---------------------

310TJF919719 Retail

COMPLAINT:

CONTINUED ON NEXT PAGE->

*** PROFORMA INVOICE ***

Invoice To Account No: 17002072

Deliver To:

SERVICE INVOICE

		Invoice Number:	
		Invoice Date	10/17/2025
		Location:	
		Work Order Number:	
		Payment Type:	
	Prv Phone:	Page:	2 of 4
Make/Model:	Meter	Serial Number:	EQ Id: Fleet No:
JOHN DEERE 310TJ	1441	T0310TJ178937	54697W

03 FUEL TANK, REMOVE AND CLEAN

CAUSE:

FUEL PUMP FAILURE

CORRECTION:

KEY PART - AT300958
 MACHINE STATUS - SOLD
 FAILURE TYPE - LOW PRESSURE FUEL PUMP FAILED
 AREA OF REPAIR - ENGINE
 DOWN TIME - NONE
 DTAC/SOLUTION - NONE

REMOVED FUEL PUMP
 INSTALLED NEW FUEL PUMP
 REMOVED FUEL TANK TOOK TO SHOP AND CLEANED OUT
 INSTALLED FUEL SENDING UNIT
 INSTALLED FUEL TANK
 INSTALLED NEW FUEL FEED LINE FROM TANK TO PUMP
 REMOVED AND REPLACED BOTH FUEL FILTERS
 PUT 5 GALLONS OF FUEL IN IT
 PRIMED FUEL SYSTEM
 STARTED AND RAN MACHINE
 MACHINE WORKED AS IT SHOULD

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AT300958	FUEL SENDE	1.00			Y
AT335148	Hydraulic Hose	1.00			Y
RE522878	FILTER ELE	1.00			Y
RE569926	FUEL FILTE	1.00			Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>			<u>Taxed Ind</u>
FREIGHT	FREIGHT & SHIPPING	1.00			N
FUEL	FUEL	5.00			Y

Labor: \$

Sub-Total: \$2,502.77

EXPERT-1000000244022 Retail

COMPLAINT:

04 56 Point Inspection

CONTINUED ON NEXT PAGE->

*** PROFORMA INVOICE ***

Invoice To Account No: 17002072

Deliver To:

SERVICE INVOICE

Prv Phone:	Prv Phone:	Invoice Number:	
		Invoice Date	10/17/2025
		Location:	
		Work Order Number:	
		Payment Type:	
		Page:	3 of 4
Make/Model:	Meter	Serial Number:	EQ Id:
JOHN DEERE 310TJ	1441	T0310TJ178937	54697W
	Fleet No:		

CORRECTION:

56 POINT INSPECTION COMPLETED

Seat Belt, Inspect
 Horn, Inspect
 Glass, Inspect
 Windshield Wipers, Inspect
 Mirrors, Inspect
 Travel Alarm, Inspect
 HVAC Operation, Inspect
 Cab Air Filters, Inspect
 Cab Monitor, Inspect
 Active and Stored Codes, Inspect
 Software Updates, Inspect
 Product Improvement Programs (PIPs), Check
 Expert Alerts, Check
 Service Brake Operation, Inspect
 Park Brake Operation, Inspect
 Steering Operation, Inspect
 Engine Operation, Inspect
 Engine Oil, Inspect
 Engine Oil Filter, Inspect
 Pulleys and Belts, Inspect
 Engine Intake System, Inspect
 Engine Exhaust System, Inspect
 Turbocharger, Inspect
 Fuel System, Inspect
 Diesel Exhaust Fluid (DEF) System, Inspect
 Coolant, Inspect
 Cooling Package, Inspect
 Water Pump, Inspect
 Transmission/Hydrostatic Operation, Inspect
 Transmission/Hydrostatic Oil, Inspect
 Transmission/Hydrostatic Filters, Inspect
 Driveshafts and U-Joints, Inspect
 Axles, Inspect
 Final Drives, Inspect
 Hydraulic System Operation, Inspect
 Hydraulic Oil, Inspect
 Hydraulic Oil Filters, Inspect
 Hydraulic Hoses and Lines, Inspect
 Hydraulic Cylinders, Inspect [Right boom cylinder leaks]
 Neutral Safety Start, Inspect

CONTINUED ON NEXT PAGE->

*** PROFORMA INVOICE ***

Invoice To Account No: 17002072

Deliver To:

SERVICE INVOICE

		Invoice Number:	
		Invoice Date	10/17/2025
		Location:	
		Work Order Number:	
Prv Phone:		Prv Phone:	
		Payment Type:	
		Page:	4 of 4

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 310TJ	1441	T0310TJ178937	54697W	

Starter Motor, Inspect
 Lights and Turn Signals, Inspect
 Charging System, Inspect
 Batteries, Check
 Electrical Cables and Harnesses, Inspect
 Steps, Inspect
 Hand Rails, Inspect
 Safety Bars and Locks, Inspect
 Roll Over Protection Structure (ROPS), Inspect
 Sheet Metal, Shields, and Panels, Inspect
 Signs and Decals, Inspect
 Counterweights, Inspect
 Frames, Inspect
 Tires, Inspect
 Tracks, Inspect
 Attachment, Inspect

Miscellaneous Charges:

Service Accessories	\$146.30
---------------------	----------

Labor:	Sub-Total: \$146.30
--------	---------------------

Please remit payments to Murphy Tractor at the address shown on your monthly statement.

Customer PO No: Tax Exempt No: Advisor:

Labor:	
Parts:	
OL&M:	
Misc:	
Sales Tax:	
Total:	\$3,656.70

Received by:

Date: