

Sales Ticket

SO # SO-2643404

Date 10/20/2025

Vehicle Info: Year/Make/Model 2008 / GMC / C5500 Topkick Cust Unit # 774
VIN/Short VIN 1GDE5C3988F408009 / 8F408009 Miles/Hours 187813 / 0
Repair Order no. RO-RO-0331127 Operation # 1
Condition NO BOOST
Correction PULLED TRUCK INTO SHOP, DIAGED THE NO BOOST ISSUE, PULLED CODES, REMOVED HEAT SHIELD FROM THE TURBO, AND FOUND THAT THE CENTER CLAMP HAD BROKEN AND LET THE TURBO SEPERATE. REMOVED THE EXHAUST SIDE OF THE TURBO FROM THE TRUCK, AND CLEANED. CHECKED THE VEINS AND RE-ALIGNED THE VEINS. INSTALLED THE TURBO WITH A NEW CLAMP. SENT THE TRUCK ON A TEST DRIVE. STILL HAD THE SAME CODE AND WAS STILL LEAKING FROM THE CENTER OF THE TURBO. DRAINED THE COOLANT, AND REMOVED THE OIL SUPPLY AND OIL DRAIN. REMOVED THE CHARGE PIPE AND FRESH AIR PIPE. REMOVED BOTH UP PIPES AND THE DOWN PIPE. REMOVED THE TURBO FROM THE TRUCK, AND TRANSFERRED BOTH COOLANT LINES TO THE NEW TURBO. TRANSFERRED THE OIL DRAIN PIPE TO THE NEW TURBO. REPLACED ALL GASKETS WITH NEW. RE-INSTALLED THE TURBO INTO THE TRUCK. RE-CONNECTED BOTH SENSORS AND THE CHARGE PIPE, THE FRESH AIR PIPE, THE UP PIPES, AND THE DOWN PIPE ASSEMBLY. RE-FILLED THE COOLANT WITH CUSTOMERS COOLANT THAT WAS DRAINED. HAD TO USE OUR COOLANT TO TOP OFF THE SYSTEM COMPLETELY. HAD A SMALL COOLANT LEAK. FIXED THE LEAK AT THE TURBO. STARTED THE TRUCK AND LET IDLE FOR 10 MINS THEN DROVE THE TRUCK AND INSPECTED FOR LEAKS. NONE WERE FOUND. RE-INSTALLED THE DOG HOUSE COVER AND BURPED THE COOLANT SYSTEM. TOOK THE TRUCK ON A TEST DRIVE TO NORTHVIEW AND BACK. TRUCK HAD ZERO ISSUES. INSPECTED ALL COMPONENTS AFTER RETURNING. CLEANED THE DOORS, HOOD, AND THE STEERING WHEEL WITH SHOP WIPES TO REMOVE ANY GREASE MARKS FROM BEING ON THE TRUCK. NO FURTHER REPAIRS NEEDED ON THIS STEP

Part number	Description	Ord	Del	B/O
120_97192618	97192618	2	2	0
GASKET				
120_97188685	TURBO GASKET	2	2	0
120_98054444	GASKET	1	1	0
120_PART_NC	GM PART - NO CORE	1	1	0
97354769 V-BAND CLAMP				
120_PART_NC	GM PART - NO CORE	3	3	0
11515776 BOLT				
120_97372002	GASKET	1	1	0

Sales Ticket

SO # SO-2643404

Date 10/20/2025

001_PART	PART	1	1	0
848212-9001s Turbo				
Core exchange				
120_97227012	TURBO GASKET	1	1	0
120_97208191	TURBO GASKET	1	1	0
120_97331137	GASKET	2	2	0
120_97373522	TURBOGASKET	2	2	0
455_EC3501	EXTENDED LIFE ANTIFREEZE/COOLANT	2	2	0

Labor

UPS Charge UPS Charge

Shop supplies

Paid CC
m
10-20-25
E.P.

Received by

See warranties on reverse side

Invoice total

\$5,862.52