

Due upon receipt

3/21/2023

DATE	DESCRIPTION	AMOUNT
COMPLAINT:	Towed here, lost upint cap, hydra locked.	
INVESTIGATION:	Low coolant; checked egr cooler, drained some off of bottom of oil pan, straight antifreeze. Give customer a quote; pulled head off and found 3 filters dropped. Liner protrusion too low causing head gasket to blow. Austin said truck has a lot of steering wheel play. Found king pins worn out. Give a quote for that too.	
		Engine ON quote
CORRECTION:	Cleaned all parts up and cut counterbores. Installed new pistons, then, rod and main bearings. Customer provided oil and antifreeze. Bolts in oil pump broke off and had to replace. Overhaul kit provides secondary fuel filter and oil filter. Purchased primary fuel filter. Replaced upint and water hose to reservoir. Replaced king pins, bushings. Test drive	kingpin quote
		oil, antifreeze
	VIN 1X09049X3CD160136 MILES 617431 HOURS 22340	FF, hose, ujolet
		extm labor
		shims

THANK YOU FOR YOUR BUSINESS!

TOTAL \$ 27,200.00