

2014 PETERBUILT 389

VIN: 1NPXGGGG1OD247888

Engine:

Trans:

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty
------------------	----------------------	--------------------	-----	-----

Customer states that: CHECK ENGINE LIGHT

Labor Service - THIS IS A GLIDER KIT - NO GAUGES ARE WORKING IN THE DASH - SPOKE WITH _____ AND THEY ADVISED TO CHANGE THE CECU, VERIFIED CECU WAS NOT COMMUNICATING, REPLACED CECU, WE CANNOT TALK TO IT BUT STILL NO GAUGES, FOUND J1939 WITH 80 PLUS OHMS WHEN IT SHOULD BE 60 OR LESS, UNPLUG 1939 AND OHMS GO TO NORMAL - PLUGGED IN A TEST ECM AND THE DASH CAME ALIVE - REPLACED ECM, PROGRAMMED AND TEST DROVE, EVERYTHING IS WORKING NOW EXCEPT FOR THE INTAKE AIR TEMP SENSOR - REPLACED SENSOR WITH ONE WE HAD AND NO CODES - LEFT QTR FENDER GOT RIPPED OFF DUE TO THE AIR LINES GETTING WRAPPED INTO THE TIRE, \$300 CREDIT APPLIED TO PARTS -

New	Q2110762100	CTRL CECU
New	R23519307	DDEC 4 PROGRAMMED
Core	R23519307	Core Received
Sublet	ECM PROGRAMMING	ECM PROGRAMMING
New	23515250	SENSOR