Invoice #:

1293536 CL

Sold by:

SHREE SAYE

Cust PO:

Job Desc:

Cust Fleet#:

BADGE 670 S/N:98071 - MAIN

EXTEND CYLINDER INSIDE BOOM

LEAKING

Make:

Tag:

AG COMPONENT

Model: AGC


Serial #: MISC 2777599

Meter:

Service Order Summary

WO#

2237590 SV REPAIR LEAK IN BOOM CYLINDER \$4,442.85



# WO#: 2237590 SV REPAIR LEAK IN BOOM CYLINDER

### Comments:

Complaint: Oil leaking out of boom arm.

#### Correction:

Unit would not start.

Removed and tested starter.

Found starter had open feild winding.

Extend boom arm arm.

Inspect boom arm.

Found oil leaking from boom extend cylinder.

Unhook lines and start removing cylinder.

Had to use boom truck and fork lift to lift out cylinder.

Disassemble and reseal cylinder.

Reinstall cylinder and connect lines.

## Labor:

#### Description

Labor

Shop Supplies

## **Total Labor**

С	20	*	٠	0	
Е	а	L	<u>.</u>	<u> </u>	

Qty	Vendor	Part Number	Description	Bin
1.00	NAP	6371N	STARTER	
1.00	CAS	ZQC4020005N	2/0 NEG CLAMP CRIMP	V4D2
1.00	CAS	ZQC6420005H	2/0 GA. 1/2 IN MAGNA LUG	V4D2
2.00	NHL	ZQC566270650B	NH BLACK HEAT SHRINK CASE	V4D1
5.00	CAS	ZQC200107100	2/0 BLACK BATTERY CABLE	BATWAL
2.00	CAS	73344270	OIL HYDRAULIC	BULK OIL
1.00	BAD	7613-5748	SEAL KIT	
1.00	CAS	ZRG017BRC	BRAKE AND PARTS CLNR 17 OZ.	PC6B
1.00	NHL	272380	O-RING	ORC6
1.00	MIS	FITTING	FITTING	
1.00		FREIGHT	FREIGHT TRAUSCH	
17.00	CAS	73344270	OIL HYDRAULIC 9/30 RDD	BULK OIL
1.00	One	FREIGHT	FRT BADGER	
1.00				Total Parts
				Tax
				Total WO

\$4,442.85

