

					Invoice Number:	
					Invoice Date:	6/30/2023
					Location:	
					Work Order Number:	
					Payment Type:	
					Page:	
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:		
JOHN DEERE 8330	7494	RW9330P010089	2247MON	58		

EXPERT-1000000085736 Retail
COMPLAINT:
03 Turbocharger, Remove and Replace

CORRECTION:

Part Number	Description
DZ108095	Turbo Actuator
DZ108095-CR	CORE for Actuator
DZ122254	Sensor
DZ122255	Sensor

Labor:	
Parts:	
OL&M:	
Misc:	
Sales Tax:	
Grand Total:	\$3,656.58

SERVICE INVOICE

Invoice Number: [REDACTED]
 Invoice Date: 8/23/2021
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: [REDACTED]

Eq ID: [REDACTED] Fleet: [REDACTED]

JOHN DEERE 9330

6565

RW9330P010089

2247MON

58

/Gen-Engine Retail
 COMPLAINT:
 01 Engine Repairs

CORRECTION:

Engine Repairs

CUSTOMER STATED THAT THERE WAS HYD LEAK ON FAN DRIVE. REMOVED AND REPLACED STEEL BRAIDED SUPPLY HOSE TO FAN DRIVE. FOUND THAT HYD LEAK WAS ALSO COMING FROM FAN SHEAVES. RETURNED TO MACHINE AND REMOVED FAN DRIVE UNIT AND REPLACED SEALS AND WEAR RINGS. INSTALLED ON MACHINE AND THERE WAS STILL A SMALL LEAK FROM SHEAVES. CUSTOMER WENT TO ELKHART TO GET COMPLETE FAN UNIT. REMOVED AND REPLACED FAN UNIT ON MACHINE AND CHECKED FOR LEAKS.

Part Number	Description
R239551	V-BELT
R246193	WEAR RING
R246194	WEAR RING
RE264238	SEAL
RE264239	SEAL
RE313900	SEAL
RE313901	SEAL
RE588803	FAN DRIVER - DRIVER ASSY. 13.5L
RE592556	Fan Drive - Rotary Union Service Kit
TY26101	Brake & Parts Cleaner

Miscellaneous Description

CONTINUED ON NEXT PAGE->

SERVICE INVOICE

Invoice Number: [REDACTED]
Invoice Date: 1/29/2024
Location: [REDACTED]
Work Order Number: [REDACTED]
Payment Type: [REDACTED]

Page

PTV Phone:

Make/Model:

Meter:

Serial Number:

Eq ID:

Fleet No:

JOHN DEERE 9330

8096

RW9330P010089

2247MON

58

EXPERT-1000000026849 Retail
AT350320 PAD

EXPERT-1000000131451 Retail

COMPLAINT:

05 STEERING CYLINDER PINS & BUSHINGS. (BOTH SIDES)
Right side is worse than left

CAUSE:

WEAR ON STEERING CYLINDER BUSHINGS

CORRECTION:

1. REMOVE STEERING CYLINDER HOSES
2. REMOVE THE STEERING CYLINDERS
3. REMOVE THE OLD BUSHINGS
4. INSTALL THE NEW BUSHINGS
5. REINSTALL THE STEERING CYLINDER WITH NEW SEALS
6. & PINS.
7. REINSTALL THE STEERING CYLINDER HOSES
8. TIME DOES NOT INCLUDE FROZEN PINS OR BUSHINGS

HAD TO TORCH OUT REAR PINS TO REMOVE FROM HOUSING.

Part Number	Description
R247735	SEAL
R259142	BUSHING
R568621	PIN
R93633	O-RING
Miscellaneous 5324	Policy Adj - SVC

L

CONTINUED ON NEXT PAGE->

SERVICE INVOICE

Invoice Number: [REDACTED]
Invoice Date: 1/29/2024
Location: [REDACTED]
Work Order Number: [REDACTED]
Payment Type: [REDACTED]
Page

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9330	8096	RW9330P010089	2247MON	58

EXPERT-1000000073143 Retail
RE577560 BREAKAWAY COUPLER - SCV

EXPERT-1000000070801 Retail
COMPLAINT:
08 Diag Hyd
Return line from scv stack to filler housing leaking

CAUSE:
FAILED CRIMP ON HOSE

CORRECTION:
1. Diagnose Hydraulic System

REMOVED COVERS AND SHIELDS TO ACCESS HOSE. REMOVED AND REPLACED HOSE. REINSTALLED COVERS THAT WERE REMOVED. FILLED HYD RESERVOIR TO SPEC. RAN MACHINE TO CHECK FOR LEAKS.

Part Number	Description
RE281109	Hydraulic Hose
TY26625B	HYD BULK QT

EXPERT-1000000154126 Retail
COMPLAINT:
09 ENGINE OIL COOLER, R&R.
Oil cooler leaking

CAUSE:
FAILED GASKETS ON COOLER

CORRECTION:

CONTINUED ON NEXT PAGE->

SERVICE INVOICE

Invoice Number: [REDACTED]
Invoice Date: 1/29/2024
Location: 04
Work Order Number: [REDACTED]
Payment Type: [REDACTED]
Page: [REDACTED]

JOHN DEERE 9330	Meter:	Serial Number:	Eq ID:	Fleet No:
	8096	RW9330P010089	2247MON	58

EXPERT-1000000071317 Retail

Labor: [REDACTED]
Parts: [REDACTED]
OL&M: [REDACTED]
Misc: [REDACTED]

Sales Tax: [REDACTED]
Grand Total: \$9,485.16

*** DOCUMENT COPY ***

Book your Tried & True Inspections by Dec. 31 for service perks like 12-mo parts warranty & deferred payments! See Service for details.





SERVICE INVOICE

Invoice Number: [REDACTED]
 Invoice Date: 5/2/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: [REDACTED]

Make/Model	Meter	Serial Number	Eq ID	Fleet No
JOHN DEERE 9330	8148	RW9330P010089	2247MON	56

EXPERT-1000000070800 Retail
 COMPLAINT:
 01 Diagnose Engine

COMPLICATIONS—
 KEPT FINDING LEAKS LOCATED ON RIGHT SIDE
 COOLANT HOSE FROM TANK, INNER THERMOSTAT GASKET, THEN OUTER THERMOSTAT GASKET STARTED
 LEAKING

OIL PAN WAS ALOT HARDER DUE TO STALK STOMPER KEPT HITTING FRONT FRAME HAD TO REMOVED FEED LINE
 TO HYD TANK AND CAP IT OFF AND REMOVE SOME CLAMPS AND CLAMPS AND HOUSING FOR ETHER CANISTER.

CRANK GEAR TOOK EXCESSIVE TIME DUE TO IT BEING RECOMMENDED FOR ENGINE TO BE REMOVED AND CRANK
 BUT I WAS ABLE TO GET CRANK GEAR OFF BUT NO PULLER WOULD FIT THAT WE HAD SO HAD TO KEEP WORKING
 ON GETTING GEAR TO MOVE TO GET ONE PULLER THAT WOULD FIT WAS ABLE TO CRANK GEAR AND USE PRY BARS
 WEDGED IT THERE AND WORKED IT OUT VERY SMALL AMOUNT AND GOT PULLER ON IT AND IT CAME OFF.
 AFTER REMOVE ALE INSTALL IT DIDNT SHOW INSTALLER SO USED HUB INSTALLER AND HEATED IT UP BUT IT GOT
 STUCK HALF WAY DUE TO IT BOTTOMING OUT SO HAD TO GET OLD GEAR AND CUT IT ALL THE WAY THREW AND
 USED IT TO HELP PUSH IT ALL THE WAY TILL IT STOPPED BUT KEPT GETTING STUCK DUE TO HEAT WEARING OFF
 GOT IT ON ALL CHECKED GOOD

CAUSE:
 WATER PUMP FAILED AND BROKE ALL TIMING GEAR TEETH

CORRECTION:



CONTINUED ON NEXT PAGE->

SERVICE INVOICE

Invoice Number: [REDACTED]
 Invoice Date: 5/2/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: [REDACTED]

Make/Model:	Make:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9330	8148	RW9330P010089	2247MON	58

DRIVELINES

FRONT AND REAR U JOINTS WERE REMOVED TO PUSH TRACTOR INTO SHOP
 INSTALLED REAR U JOINT HAD TO MOVE TRACTOR SLIGHTLY TO GET DRIVE LINE TO LINE UP.
 FRONT U JOINT HAD CAPS MISSING AND BROKE OFF SO HAD TO INSTALL NEW U JOINT FOR FRONT DRIVE LINE.
 INSTALLED ALL NEW BOLTS ON BOTH DUE TO THEM MISSING AND BEING REMOVED ANYWAYS

COOLANT LEAKS

LEAKS IT HAD BEFORE BUT COOLANT WAS EMPTY WHEN IT ARRIVED.
 FILLED WITH COOLANT AND PRESSURE TESTED COOLANT SYSTEM.
 COOLANT HOSE THAT GOES DOWN FROM TANK LEAKING.
 DRAINED COOLANT REPLACED HOSE
 PRESSURED UP COOLANT AGAIN AND FOUND LEAK DRIPPING BEHIND THERMOSTAT HOUSING RIGHT FRONT.
 REMOVED RIGHT SIDE SHIELD, COOLANT TUBE THAT GOES IN SIDE BLOCK FOR COOLER TUBE, AND COUPLE LINES
 REMOVED THERMOSTAT HOUSING AND INNER HOUSING.
 REPLACED INNER AND OUTER THERMOSTAT GASKET.
 RAN MACHINE AND LEAK WAS FIXED BUT FOUND IT VERY VERY SMALL DRIP ON THERMOSTAT FRONT GASKET
 DRIPPING WITH SYSTEM PRESSURED UP.
 DRAINED COOLANT AGAIN AND REMOVED HOUSING CHECKED GASKET NO TEAR MOST HAVE SMALL WARP IN
 HOUSING, PUT SMALL AMOUNT OF SILICONE ON END OF GASKET.
 INSTALLED IN REVERSE ORDER AND RAN MACHINE AND PRESSURED UP TO SPEC ON SYSTEM.

Part Number	Description
19M8088	CAP SCREW
19M8508	SCREW
26M4224	SHAFT KEY
34M7129	SPRING PIN
40M7076	Snap Ring
A4730R	O-RING
DZ103630	HOSE
DZ120103	Gasket Kit
DZ127964	SEAL
R100357	M13 X 51mm Flanged Head Bolt
R114083	SCREW

CONTINUED ON NEXT PAGE ->

Model:		Meter:		Serial Number:	Eq ID:	First H:
JOHN DEERE 9330		8148		RW9330P010089	2247MON	58

Invoice Number:	Invoice Date:	Location:	Work Order Number:	Payment Type:	Page:

EXPERT-1000000070800	Retail
R122377	
R231549	WHEEL SPEE
R239551	RADIATOR H
R241746	V-BELT
R500387	V-BELT
R501292	GASKET
R519752	GROMMET
R521189	Oil Pan Gasket
R523989	Front Timing Cover
R524334	GASKET
R524335	V-RING SEA
R524618	V-RING SEA
R525760	Gasket
R529655	HUB
R529684	GEAR
R535377	Gear
R548117	SCREW
R63185	O-RING
R98527	O-RING
RE174130	FILTER
RE40112	OIL FILTER
RE519144	CROSS AND BEARING
RE527102	SENSOR
RE527611	SEAL
RE527612	Thermostat
	Thermostat

SERVICE INVOICE

Invoice Number: [REDACTED]
 Invoice Date: 5/2/2024
 Location: [REDACTED]
 Work Order Number: [REDACTED]
 Payment Type: [REDACTED]
 Page: [REDACTED]

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9330	8148	RW9330P010089	2247MON	58

EXPERT-1000000070800 Retail
 RE527614 Seal
 RE527933 OIL PUMP
 RE527933-CR CORE for Oil Pump
 RE529871 ELBOW FITT
 RE530733 Torsional Damper
 RE53654 GEAR
 RE548049 IDLER GEAR
 RE549117 Water Pump
 RE572785 Engine Oil Filter
 RE588903 FAN DRIVER - DRIVER ASSY 13.5L
 RE592550 SEAL KIT
 TY22062 2.5 GAL HY-GARD OIL
 TY22467 CLAMP
 TY26576 2.5 GAL COOL-GARD II PRE-MIX
 TY26673 1-Gal 15W-40 PLUS 50 II CJ-4/SN OIL
 TY26675 2.5 GAL 15W-40 PLUS 50 II CJ-4/SN
 Miscellaneous
 3750 JD FREIGHT
 5324 POLICY ADJ - SVC

Sub-Total: \$22,958.07

EXPERT-1000000071317 Retail

COMPLAINT:

02 AIQC Basic walk around to identify any issues, check lights, safety equipment, all fluid levels, and basic operations

CORRECTION:

SERVICE INVOICE

Invoice Number: [REDACTED]
Invoice Date: 5/31/2024
Location: [REDACTED]
Work Order Number: [REDACTED]
Payment Type: [REDACTED]
Page: [REDACTED]

Make/Model:	Motor:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9330	8309	RW9330P010089	2247MON	56

EXPERT-1000000182610 Retail
COMPLAINT:
Remove and recondition final drives.

CAUSE:
Failed final drives.

CORRECTION:
Supported tractor and removed duals.
Drained oil from axle.
Removed driveshaft and hydraulic lines.
Dropped axle and removed.
Removed final drives from differential case.
Replaced brake disks and piston packings.
Reinstalled final drives after reconditioning.
Ran machine and topped off transmission oil.
Installed rear axle installed rear duals replaced transmission oil.

Part Number	Description
R111434	CAP SCREW
R52006	WASHER

EXPERT-1000000210554 Retail
COMPLAINT:
Recondition final drives.

CAUSE:
Failed final drive bearings.

CORRECTION:

CONTINUED ON NEXT PAGE →

Invoice Number:

Invoice Date:

Location:

Work Order Number:

Payment Type:

Page:

Make/Model:

JOHN DEERE 9330

Meter:

8309

Serial Number:

RW9330P010089

Eq ID:

2247MON

Fleet No:

58

EXPERT-1000000210554 Retail
 Disassembled final drive
 Installed new bushing and outer bearing
 Installed housing and inner bearing
 Checked rolling drag
 Installed lead balls and checked end play
 Installed correct shim pack and assembled final drive

Part Number:

14M7452

Description:

LOCK NUT

AN400251

Axle Bearing Kit

DRC4901

56 Count, Single Roll - Shop Towels

F3171R

O-RING

PM38655

GASKET MAKER

R100357

M13 X 51mm Flanged Head Bolt

R111904

BUSHING

R125666

RING

R125667

RING

R153620

PLANET PIN

R160837

SPACER

R174212

SHAFT

R182695

BOLT

R268521

THRUST WAS

R314670

SHAFT

R560122

PLANET PIN

R560525

PINION SHA

R63237

SHIM

R63575

NEEDLE ROL

R69549

PLATE, LOC

CONTINUED ON NEXT PAGE->

SERVICE INVOICE

Invoice Number: [REDACTED]
Invoice Date: 5/31/2024
Location: [REDACTED]
Work Order Number: [REDACTED]
Payment Type: [REDACTED]
Page: [REDACTED]

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9330	8309	RW9330P010089	2247MON	58

EXPERT-1000000210554	Retail
R72232	BALL
R79989	SHIM
R81162	BOLT
RE168841	SEAL
RE174130	OIL FILTER
RE292439	BRAKE DISK
RE293316	TAPERED RO
TY22062	2.5 GAL HY-GARD OIL
TY26101	Brake & Parts Cleaner
TY26625	BULK HY-GARD OIL

Grand Total: \$20,997.34

*** DOCUMENT COPY ***

Book your Tried & True Inspections by Dec. 31 for service perks like 12-mo parts warranty & deferred payments! See Service for details.