

Invoice

Date	Invoice #
4/5/2022	3843

Bill To	Vehicle Information
	3D7MX48C37G753567 2007 Dodge 3500 5.9L Mileage: 181,356

PAID
04/07/2022

P.O. No.	Terms
	Due on Receipt

Item	Quantity	Description	Rate	Amount
Labor #2 Diesel	11	Customer states the transmission will not shift. Checked codes and found several shift solenoid codes and force motor codes. Checked transmission fluid and found the fluid level is correct but the fluid is burned. Checked connectors at the transmission and found several wires on 2 of the 3 connectors are bare and shorted together. Removed transmission pan and found a large amount of metal and clutch material in the pan. Removed transmission and found the left top portion of the bell housing has been broken off and put back in place with silicone. Installed new pigtales on damaged wiring harness. Removed transmission cooler and flushed transmission lines. Installed new Mopar transmission cooler and reman 48RE transmission. Shift cable was broken and had been taped on the shift arm. Installed new shift cable and filled transmission with fluid. Started pickup and the intake air heater shorted out melting the power cable. Disabled the intake air heater and test drove vehicle.		1,045.00T
Parts	1	Reman 48RE transmission Ser# 098FTD3049		6,500.00T
Core	1	Partial core charge		750.00T
Parts	1	Wiring harness		72.45T
Parts	1	Wiring harness		104.08T
Parts	1	Mopar transmission cooler		260.00T
Parts	1	Shift cable		169.00T
Misc Mat Oil Cha...	1	Misc fluids and materials		25.00T

			Sales Tax (9.0%)	
			Total	\$9,728.83
			Payments/Credits	
			Balance Due	\$0.00