

INVOICE NO F6-76834

PAGE 1 OF 4

*** CHARGE ***

0613

PUMP NO. EQUIPMENT MAKE **ENGINE MODEL** DATE IN SERVICE CUSTOMER ORDER NO. DATE ISL9 CM2350 L101 UNIT 60 28-MAR-2013 20-JUN-2024 EQUIPMENT MODEL CPL NO. FAIL DATE ENGINE SERIAL NO. SHIP VIA CUSTOMER NO. 3664.000 03-JUN-2024 73491881 MILEAGE/HOURS PUMP CODE UNIT NO. SALES PERSON PARTS DISP. REF. NO. SJ486 211052

OUANTITY BACK ORDERED SHIPPED PART NUMBER	DESCRIPTION	UNIT PRICE	AMOUNT
---	-------------	------------	--------

COMPLAINT CAUSE CORRECTION CHECK ENGINE LIGHT, LOSING POWER, SMOKING WHITE, RUNS ROUGH

TAPPET FAILURE RESULTING IN CAMSHAFT FAILURE.

TECHNICIAN ADMINISTRATIVE TIME - NON-FIELD ACTION SERVICE EVENT

JOB SAFETY ASSESSMENT

DRIVELINE - RECONNECT (AUTOMOTIVE ONLY)

DISABLED VEHICLE - MOVE INTO SHOP (AUTOMOTIVE ONLY)

COURTESY VISUAL INSPECTION NO ISSUES NOTED AT THIS TIME

ELECTRONIC SERVICE TOOL - OPERATE

OVERHEAD SET - ADJUST, FIRST CYLINDER

FOUND #1 INTAKE TO HAVE EXCESSIVE PLAY. REMOVED ROCKERS AND PUSH RODS, BOROSCOPED TAPPETS FROM TOP SIDE, NO DAMAGE. INSPECTED ROCKERS, PUSH RODS, AND VALVE SPRINGS. NO DAMGAE. REINSTALLED PUSH RODS AND ROCKERS, ADJUSTED OVERHEAD, #1 INTAKE PUSH

ROD IS SITTING VERY LOW COMPARED TO OTHERS.

LUBRICATING OIL PAN - REMOVE

DRAINED OIL, TOOK SAMPLE DUE TO OIL HAVING METAL IN IT, HAD TO REMOVE 2 BRACES FOR PTO LINES UNDER TRUCK. REMOVED OIL PAN, FOUND METAL PIECES IN BOTTOM. LOOKS LIKE ROLLER TAPPET PIN.

CAMSHAFT - INSPECT FOR REUSE

INSPECTED CAMSHAFT, FOUND #1 INTAKE LOBE TO BE GROUND DOWN. TAPPET FAILURE

RESULTING IN CAMSHAFT FAILURE.

FOR ACCESS:

AIR CLEANER ASSEMBLY (INCLUDING BRACKET) - REMOVE AND INSTALL

CRANKCASE BREATHER TUBE(S) - REMOVE AND INSTALL

CRANKCASE BREATHER - REMOVE AND INSTALL COOLANT RESERVOIR - REMOVE AND INSTALL

COOLANT VENT HOSES - REMOVE AND INSTALL, (WITH EGR)

HYDRAULIC OIL COOLER OR TRANSMISSION OIL COOLER - REMOVE AND INSTALL

RADIATOR, CHARGE AIR COOLER, AIR CONDITIONER CONDENSER ASSEMBLY - REMOVE AND

INSTALL (PART OF ANOTHER REPAIR)

FAN, COOLING - REMOVE AND INSTALL

FAN, COOLING - CLEAN AND VISUALLY CHECK FOR REUSE

EGR CONNECTION TUBE - REMOVE AND INSTALL

EGR COOLER COOLANT TUBES - REMOVE AND INSTALL

THERE ARE ADDITIONAL CONTRACT TERMS ON THE REVERSE SIDE OF THIS DOCUMENT, INCLUDING LIMITATION ON WARRANTIES AND REMEDIES, WHICH ARE EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ AND FULLY UNDERSTOOD.

Jax externit

DATE



40	INVOICE NO	
	F6-76834	

PAGE 2 OF 4

*** CHARGE ***

	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT M.	AKE
DATE		00 MAD 2013	ISL9 CM2350 L101			
20-JUN-2024	UNIT 60	28-MAR-2013		CPL NO.	EQUIPMENT MO	ODEL
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.			
CUSTOMER NO.		03-JUN-2024	73491881	3664.000		
50078			MILEAGE/HOURS	PUMP CODE	UNIT NO.	
REF. NO.	SALES PERSON	PARTS DISP.	MILLEMOLT			
211052	SJ486					
211002		The state of the s	A CONTRACTOR OF THE PARTY OF TH	PRODUCT CODE	UNIT PRICE	MOUNT
DUANTITY BACK ORDERED ORDERED	QUANTITY PART NUMBER		DESCRIPTION		UNIT PRICE	IIIOOI41

CHARGE AIR PIPE - REMOVE AND INSTALL, EACH
LUBRICATING OIL COOLER ASSEMBLY - REMOVE AND INSTALL, (WITH EGR)
CAMSHAFT GEAR - REMOVE AND INSTALL (WITH SERVICE TOOL PART NO. 3823589)
CAMSHAFT - REMOVE AND INSTALL (WITH EGR)
CAMSHAFT GEAR AND THRUST PLATE - INSPECT FOR REUSE, BOTH
TAPPET - REMOVE AND INSTALL, ALL (WITH SERVICE TOOL PART NO. 3163468) (CAMSHAFT
REMOVED)
CRANKSHAFT SEAL, FRONT - REPLACE
OVERHEAD SET - ADJUST, ALL
LUBRICATING OIL AND FILTER(S) - CHANGE
COOLING SYSTEM DEAERATION (WITH EGR)
STEAM CLEAN - SINGLE COMPONENT REPAIR
FAULT FOR NOX SENSOR
REPAIR
AFTERTREATMENT INTAKE NOX SENSOR HEAT SHIELD- REMOVE AND INSTALL
AFTERTREATMENT INTAKE NOX SENSOR-REMOVE AND INSTALL
RUN UNIT TO VERIFY REPAIR
THANK YOU FOR YOUR BUSINESS AND HAVE A WONDERFUL DAY

COVERAGE REMARK	BILLABLE 6/5: BRIAN PROVIDED RE	0.00		
1 1 1 12 1 1	GUARDIAN INSP 1 BMPKB 1 3164067 12 3965966 1 3944001 1 2892779 1 3918174	COURTESY INSPECTION BASIC W/BAG OIL SAMP KIT SEALANT TAPPET, VALVE SUPPORT, CAMSHAFT THRUST DOWEL, PIN GASKET, OIL COOLER CORE	CHEM CECO CECO CECO CECO	20.97 27.25 1,444.56 15.34 11.92 24.96

THERE ARE ADDITIONAL CONTRACT TERMS ON THE REVERSE SIDE OF THIS DOCUMENT, INCLUDING LIMITATION ON WARRANTIES AND REMEDIES, WHICH ARE EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ AND FULLY UNDERSTOOD.

AUTHORIZED BY (print name)

SIGNATURE

DATE

INVOICE NO F6-76834 TO PAY ONLINE LOGON TO customerpayment.cummins.com

PAGE 3 OF 4

PUMP NO.

ENGINE MODEL

*** CHARGE ***

EQUIPMENT MAKE

DATE						
20-JUN-2024		UNIT 60	28-MAR-2013	ISL9 CM2350 L101		
CUSTOMER NO.		SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
50078			03-JUN-2024	73491881	3664.000	
REF. NO.	S.	ALES PERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
211052		SJ486				
DUANTITY BACK ORDERED ORDERED	QUANTITY	PART NUMBER	DE	SCRIPTION	PRODUCT CODE	NIT PRICE. AMOUNT
1	1	3929011	GASKET,LUB C	DIL CLR COVER	CECO	31.24
1	1	5284362	CORE,COOLER	3	CECO	301.36
1	1	LF9009	PAC, LF		FLG	59.54
1	1	5332563	GASKET,OIL PA	AN	CECO	77.16
1	1	4024883	KIT,SEAL		CECO	96.55
1	1	3966430	CAMSHAFT		NSPART4	1,181.33
1	1	3944293	GASKET,GEAR	HOUSING	CECO	130.10
1	1	5440813	GASKET,ACC I	DRIVE SUPPORT	CECO	20.76
1	1	3899283	SEAL,O RING		CECO	13.52
1	1	5272819	SEAL, RECTAN	GULAR RING	CECO	2.75
1	1	4326873RX	SENSOR,NITRO	OGEN OXIDE	DRC	684.97
1	1	4326872D	SENSOR, NITRO	OGEN OXIDE	CLEAN	229.50
-1	-1	4326872D	SENSOR,NITRO	OGEN OXIDE	DIRTY	-229.50
			PARTS: PARTS COVERAGE TOTAL PARTS: SURCHARGE TOTAL		4,144.28 0.00 C	
			LABOR:		6,626.70	
				LABOR COVERAGE TOTAL LABOR:	CREDIT:	0.00 C
				MISC.:		-280.15
				MISC. COVERAGE O	REDIT:	0.00 C
				DISCOUNT PARTS-E	BRANCH	-280.15

DATE IN SERVICE

THERE ARE ADDITIONAL CONTRACT TERMS ON THE REVERSE SIDE OF THIS DOCUMENT, INCLUDING LIMITATION ON WARRANTIES AND REMEDIES, WHICH ARE EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ AND FULLY UNDERSTOOD.

E

DATE

CUSTOMER ORDER NO.