

INVOICE

440

Org. Est. # 020405

Printed Date: 09/25/2023 Work Completed: 09/25/2023
#650 Super Duty - 6.4L V8 (391Ch) VMRR
Odometer In: 143475
Odometer Out: 143475

2008
Lic # [REDACTED]
VIN #: 1FDAF57R0 8ED31417

Ext Labor Description
Hours Ext

Qty Sale
Number

Remaining Balance by Payment

Sub Total: \$7,353.06

Labor:
Parts:

SubTotal: \$

Tax:

Total:

Bal Due: \$7,353.06

Customer Number: 158

Org. Estimate

Revisions

Current Estimate

[Payments -]

Vehicle Received: 9/23/2023
Terms: Payment due on receipt.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

LATE FEES WILL BE APPLIED TO ALL OVER DUE INVOICES
INVOICES DUE UPON RECEIPT

Signature

Visit us on the web: www.
Service Advisor: Geiger, Cody

Discard old parts

Original Estimate

Email Address
Page 2 of 2

Total

Repair Information Company, LLC. Intra 51224r

INVOICE

440

Org. Est. # 000458

INVOICE

Printed Date: 09/25/2023

Work Completed: 09/25/2023

2008 Ford - F550 Super Duty - 6.4L, V8 (391Ci) VIN(R)

Lic # :

Odometer In : 143475

Odometer Out : 143475

VIN # : 1FDAF57R0 8ED31417

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Fel-Pro Exhaust Manifold Gasket Set MS96833	1			Truck pulls to the right, find oil leak and exhaust leak, check codes		nc
MAHLE Turbocharger Mounting Gasket Set GS33566A	1			Symptom: Truck pulls to the right, find oil leak and exhaust leak, check codes		
Cab Mount KF0460BK	1			BRAKE SHOES &/OR PADS - Remove & Replace - All Both Axes - [Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable). Includes: Repack Wheel Bearings (where applicable). DOES NOT include refinishing.]	2	
turbo up pipes 1234	1			(Combination) - DISC ROTOR - Burnish Brake Rotors While Driving Vehicle	1	
PerfectStop Semi-Metallic Brake Pads by Bosch Disc PS1066M	2			TURBOCHARGER - Remove & Replace - 4WD, Automatic Trans w/Cab Removal, w/Air Conditioning	13	
Perfect Stop Winhere Gray Armor-Plate, Premium Dis 6620813	2			EXHAUST MANIFOLD - Remove & Replace - Diesel Both	7	
Perfect Stop Winhere Gray Armor-Plate, Premium Dis 6620511	2			All 4 pads and rotors, front shocks, exhaust leak looks like broken manifold bolt on drivers side, oil leak looks like turbo oil drain oring is leaking, codes are cyl 5 and 8 glow plug, p0703 brake switch input fault and turbo boost performance, dont see anything loose in front end to make it pull RF tire is chopped		
Motorcraft Diesel Glow Plug ZD-15	8					
Wix Air Filter 49886	1					
Dorman - OE Solutions Exhaust Manifold 674970	2					
Fel-Pro Engine Valve Cover Gasket Set VS50894R	1					
Dorman - OE Solutions HVAC Heater Pipe 626-582	1					
Exhaust Manifold Hardware Kit DMN03419	2					
Rotomaster Turbocharger - Remanufactured S8640103R	1					
Shop Supplies						

Email Address:

Copyright (c) 2023 Microstar Repair Information Company, LLC Inv#rs 5.12.21r

Page 1 of 2

Visit us on the web

Service Advisor :