

Invoice To Account No: 341028

Deliver To:

SERVICE INVOICE

| | | | |
|-----------------|----------------|--------------------|------------|
| Bus Phone: | Bus Phone: | Invoice Number: | 5049651 |
| Prv Phone: | Prv Phone: | Invoice Date | 06/21/2023 |
| | | Location: | 14 |
| Make/Model: | Meter | Work Order Number: | 1119832 |
| JOHN DEERE 6405 | Serial Number: | Payment Type: | Cash |
| | EQ Id: | Page: | 1 of 5 |
| | L06405H299416 | Fleet No: | |
| | | SANDOVAL6405 | |

Gen- Retail

COMPLAINT:

CUSTOMER SAID TRACTOR FEELS AS THO IT IS LIMITED ON POWER- ADVISE AND QUOTE
 CUSTOMER APPROVED 4 HRS DIAGNOSTIC AND FUEL FILTER

CORRECTION:

Drive tractor around lot.
 Bring machine into shop.
 Remove fuel filter.
 Drain filter into clean bucket.
 Contents of fuel filter seem to be free of contaminants.
 Refill fuel filter install.
 KEy on let fuel filter prime.
 Start tractor.
 Tractor did not start.
 Found that accessory 12v pump has gone out.
 Remove and install new fuel sender with pump.
 Cut spliced wires out and return to factory.
 Reinstall fuel check valve on supply side of tank.
 Start tractor let run.
 Tractor runs fine sitting still.
 Drive tractor on dirt road behind shop.

| PartNumber | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-----------------|-----------------|--------------|--------------|------------|----------------|-----------|
| AL113125 | FUEL PUMP | 1.00 | | | \$161.81 | Y |
| RE62419 | FILTER ELE | 1.00 | | | \$28.75 | Y |
| Labor: \$768.00 | Parts: \$190.56 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: | \$958.56 | |

Gen1- Retail

COMPLAINT:

CUSTOMER POSSIBLY HEARS A SQUEAL IN THE REAR END - ADVISE AND QUOTE
 NOTHING TO REPAIR

CORRECTION:

CONTINUED ON NEXT PAGE->

Invoice To Account No: 341028

Deliver To:

SERVICE INVOICE

| | | | |
|-----------------|----------------|--------------------|------------|
| Bus Phone: | Bus Phone: | Invoice Number: | 5049651 |
| Prv Phone: | Prv Phone: | Invoice Date | 06/21/2023 |
| | | Location: | 14 |
| Make/Model: | Meter | Work Order Number: | 1119832 |
| JOHN DEERE 6405 | Serial Number: | Payment Type: | Cash |
| | EQ Id: | Page: | 1 of 5 |
| | L06405H299416 | Fleet No: | |
| | | SANDOVAL6405 | |

Gen- Retail

COMPLAINT:

CUSTOMER SAID TRACTOR FEELS AS THO IT IS LIMITED ON POWER- ADVISE AND QUOTE
 CUSTOMER APPROVED 4 HRS DIAGNOSTIC AND FUEL FILTER

CORRECTION:

Drive tractor around lot.
 Bring machine into shop.
 Remove fuel filter.
 Drain filter into clean bucket.
 Contents of fuel filter seem to be free of contaminants.
 Refill fuel filter install.
 KEy on let fuel filter prime.
 Start tractor.
 Tractor did not start.
 Found that accessory 12v pump has gone out.
 Remove and install new fuel sender with pump.
 Cut spliced wires out and return to factory.
 Reinstall fuel check valve on supply side of tank.
 Start tractor let run.
 Tractor runs fine sitting still.
 Drive tractor on dirt road behind shop.

| PartNumber | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|------------|--------------|----------|------------|------------|----------------|-----------|
| AL113125 | FUEL PUMP | 1.00 | | | \$161.81 | Y |
| RE62419 | FILTER ELE | 1.00 | | | \$28.75 | Y |
| Labor: | OL&M: \$0.00 | Misc: | \$0.00 | Sub-Total: | \$958.56 | |

Gen1- Retail

COMPLAINT:

CUSTOMER POSSIBLY HEARS A SQUEAL IN THE REAR END - ADVISE AND QUOTE
 NOTHING TO REPAIR

CORRECTION:

CONTINUED ON NEXT PAGE->

Invoice To Account No: 341028

Deliver To:

SERVICE INVOICE

| | | | |
|-----------------|----------------|--------------------|------------|
| Bus Phone: | Bus Phone: | Invoice Number: | 5049651 |
| Prv Phone: | Prv Phone: | Invoice Date | 06/21/2023 |
| | | Location: | 14 |
| Make/Model: | Meter | Work Order Number: | 1119832 |
| JOHN DEERE 6405 | Serial Number: | Payment Type: | Cash |
| | | Page: | 2 of 5 |
| | | | |
| | | EQ Id: | Fleet No: |
| | LO6405H299416 | | |

Labor: \$0.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$0.00

Gen2- Retail

COMPLAINT:

CHECK AC CUSTOMER SAID THAT THE AC IS ICING OVER - ADVISE AND QUOTE
 CUSTOMER APPROVED 1 HOUR DIAGNOSTIC

CORRECTION:

Connect manifold gages.
 Check static pressures.
 No refrigerant in lines.
 Disconnect manifold gages,
 Connect nitrogen.
 Pressurize system with nitrogen check for leaks.
 large leak present at rear r.h a/c line from low side service port to cab roof.
 Quote customer replacement of line and sealing o-rings.
 Remove cab roof mounting hardware.
 raise and block rear of cab roof up.
 Remove line hold down clamps and line.
 Install new line and o-rings
 Reinstall line clamps.
 Reinstall cab roof mounting hardware.
 Re-pressurize a/c system with 300 psi of nitrogen, system held over night.
 Connect a/c machine.
 pull vacuum on a/c system for 45 min and 10 minute vacuum test.
 Both completed successfully.
 Charge a/c system.
 Start engine turn on a/c connect manifold gages.
 a/c clutch not operating.
 Check power to a/c compressor clutch.
 12 v + wire broke at connector.
 Install new connector end.
 A.c compressor operating properly.
 LET tractor run at 1200 rpm for period of time.
 Low side pressure reading 20 psi
 High side pressure reading 150 psi
 Vent temp reading 35 degree F
 Ambient air temp 64 degreeF @ 90% humidity.

| PartNumber | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|------------|-------------|----------|------------|-----------|----------------|-----------|
| AL117189 | CHECK VALV | 1.00 | | | \$38.79 | Y |

CONTINUED ON NEXT PAGE->

Invoice To Account No: 341028

Deliver To:

SERVICE INVOICE

| | | | |
|-----------------|------------|--------------------|------------|
| Bus Phone: | Bus Phone: | Invoice Number: | 5049651 |
| Prv Phone: | Prv Phone: | Invoice Date | 06/21/2023 |
| | | Location: | 14 |
| | | Work Order Number: | 1119832 |
| | | Payment Type: | Cash |
| | | Page: | 3 of 5 |
| Make/Model: | Meter | Serial Number: | EQ Id: |
| JOHN DEERE 6405 | | L06405H299416 | Fleet No: |

| | | | | |
|---------------|-------------------------|---------------------|----------------------------|---|
| AL158926 | Oil Line | 1.00 | \$117.76 | Y |
| R33259 | O-RING | 2.00 | \$3.80 | Y |
| TY22462 | CLAMP | 2.00 | \$2.18 | Y |
| Labor: | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$418.53 | |

Gen3- Retail

COMPLAINT:

QUOTE REPAIRING WORK LIGHTS.
CUSTOMER REFUSED

CORRECTION:

| | | | | |
|----------------------|----------------------|-------------------------|---------------------|--------------------------|
| Labor: \$0.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$0.00 |
|----------------------|----------------------|-------------------------|---------------------|--------------------------|

Gen4- Retail

COMPLAINT:

INSPECT HYDRAULIC FILTERS - QUOTE
REPLACING HYDRAULIC FILTERS AND NEW HOUSING

CORRECTION:

Remove and replace hydraulic and transmission filter.
Hyd filter replacement also replaces outside canister.
Start tractor check for leaks no leaks present.

| | | | | |
|---------------|----------------------|-------------------------|---------------------|----------------------------|
| Labor: | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$128.00 |
|---------------|----------------------|-------------------------|---------------------|----------------------------|

Gen5- Retail

COMPLAINT:

DISPLAY DOES NOT WORK, CONNECT COMPUTER AND SEE WHAT CODES OR INFORMATION IS STORED - QUOTE
REPAIRING/REPLACING DISPLAY
CUSTOMER REFUSED REPAIRED

CONTINUED ON NEXT PAGE->

Invoice To Account No: 341028

Deliver To:

SERVICE INVOICE

| | | | |
|-----------------|------------|--------------------|--------------|
| Bus Phone: | Bus Phone: | Invoice Number: | 5049651 |
| Prv Phone: | Prv Phone: | Invoice Date | 06/21/2023 |
| | | Location: | 14 |
| | | Work Order Number: | 1119832 |
| | | Payment Type: | Cash |
| Make/Model: | Meter | Serial Number: | Page: 4 of 5 |
| JOHN DEERE 6405 | | L06405H299416 | |

CORRECTION:

| | | | | |
|---------------|---------------|--------------|--------------|-------------------|
| Labor: \$0.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$0.00 |
|---------------|---------------|--------------|--------------|-------------------|

Gen6- Retail

COMPLAINT:

REBUILD BOTH REAR LIFT CYLINDERS

CORRECTION:

Remove hitch arm pins and keepers.
 Raise hitch to allow cylinder rod to clear.
 Disassemble cylinder.
 remove and replace seals.
 Reassemble cylinder.
 Reinstall hyd hose.
 Reinstall pin and keeper.
 Repeat process on remaining side.
 Start tractor check for leaks.
 No leaks present.
 Raise and lower lift multiple times to remove air from system.

| PartNumber | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|---------------|----------------|----------|------------|-----------|----------------|-----------|
| | | | | | | |
| AL112922 | Filter Housing | 1.00 | ' | | \$313.99 | Y |
| AL203060 | OIL FILTER | 1.00 | ' | | \$120.96 | Y |
| AL207999 | SEAL KIT | 2.00 | ' | | \$254.24 | Y |
| AL221066 | OIL FILTER | 1.00 | | | \$54.87 | Y |
| Miscellaneous | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
| 3750 | FREIGHT | 1.00 | | | \$50.00 | N |

Miscellaneous Charges:

| | |
|---------------------|--------------|
| Service Accessories | \$50.00 |
| Labor: | OL&M: \$0.00 |

CONTINUED ON NEXT PAGE->

Invoice To Account No: 341028

Deliver To:

SERVICE INVOICE

| | | | |
|-----------------|---------------|--------------------|------------|
| Bus Phone: | Bus Phone: | Invoice Number: | 5049651 |
| Prv Phone: | Prv Phone: | Invoice Date | 06/21/2023 |
| Make/Model: | Meter | Location: | 14 |
| JOHN DEERE 6405 | LO6405H299416 | Work Order Number: | 1119832 |
| | | Payment Type: | Cash |
| | | Page: | 5 of 5 |

Customer PO No:

Tax Exempt No:

Advisor:

TANYA SNIDER

Labor:

Parts:

OL&M:

Misc:

Sales Tax:

Total: \$2,778.13

TERMS AND CONDITIONS

Purchasers certify under penalty of perjury their engagement in farming or ranching, and that the farm machinery and farm equipment parts described hereon will be used only in the purchasers' farming or ranching operations.

Received by:

Date: