

JOB #2 433

SERVICE - REPLACE TIRES

COMPLAINT

REPLACE TIRES

Parts: \$0.00 Labor: \$1,824.00 FRT: \$0.00

JOB #3 723

SERVICE - REPLACE BATTERY

C
C
C

CT -

INVOICE

JOB #1 800

SERVICE - GENERAL MISC REPAIR

COMPLAINT

PERFORM VEHICLE INSPECTION FOR ROAD WORTHY OPERATIONS -

CAUSE

PERFORM INSPECTION

CORRECTION

2854 - PERFORMED A COMPLETE VEHICLE INSPECTION AND LISTED ALL ISSUES FOUND.

- * Front suspension needs greased
- * Oil filter base leaking oil
- * Alternator belt worn almost in half, fan belt worn
- * Transmission sight glass has a chip in it
- * Battery box cover is very damaged
- * DOT out of date
- * Rear engine mounts are very worn out
- * Drive line is removed
- * Passenger side mud flap damaged
- * Rear drive axle temp sensor broke off
- * Rear bed light wiring damaged with exposed wires
- * Rear tag axle vertical shock leaking on driver side
- * Drive axle brake pads are low
- * Driver side windshield chipped
- * Passenger side windshield cracked
- * Passenger side front bed marker light out
- * Passenger side rear upper bed lights are out

Level is high and DPF needs removed and cleaned(Likely cause by the turbo failure)

DESCRIPTION	
999-000-000	
U-JOINT KIT	
SPACER SLEEVE	
FLANGE SCREW	
PERFORM VEHICLE INSPECTION FOR ROAD WORTHY	

INVOICE REPRINT



	EST
LABOR	
PARTS	
MISC	
FREIGHT	
SUBLET	
PREPAY	
SUBTOTAL	
SHOP SUPPLIES	
MISC SUPPLIES	
TAX	
TOTAL	\$27,924.97



2854 - REMOVED BOTH SIDE CAC PIPES AND FOUND OIL AND DIRT ON THE OUTLET SIDE OF THE CAC TO THE ENIGNE. REMOVED ALL COMPONENTS AND REMOVED THE VALVE COVER. REMOVED ALL RELATED PARTS AND ROCKER SHAFT AND REMOVED ALL 6 INJECTORS. INSTALLED 6 COMPRESSION TEST FITTINGS IN ALL CYLINDERS. THEN REINSTALLED THE ROCKER SHAFT AND ALL RELATED COMPONENTS. PERFORMED A COMPRESSION TEST ON ALL 6 CYLINDERS AND FOUND ALL TO BE WITHIN SPEC. WILL NEED TO REPLACE THE TURBO, CHARGE AIR COOLER, INJECTOR CUPS, ALL ONE TIME USE PARTS FOR INJECTOR CUPS, AND DISASSEMBLE THE ENTIRE INTAKE SYSTEM AND CLEAN THOROUGHLY TO REPAIR THIS UNIT. REPAIRS HAVE BEEN QUOTED.

INVOICE REPRINT

CYLINDER 1 - 369 PSI

CYLINDER 2 - 390 PSI

CYLINDER 3 - 339 PSI

CYLINDER 4 - 369 PSI


CYLINDER 5 - 386 PSI

CYLINDER 6 - 427 PSI. REPLACED CAC

& CLEANED OUT INTAKE SYSTEM. REMOVED AND INSTALLED NEW TURBO WITH ALL NEW SEALS/ GASKETS AND CLAMPS. REMOVED ROCKERSHAFT. REMOVED INJECTORS & FOUND SEVERE PITTING IN



PRESSURE SENSOR	
WIRES	
PIPE	
PIPE	
O-RING	
THROTTLE	
SENSOR	
SEALING RING	
FLANGE SCREW	
CHARGE AIR COOLER	
TURBO KIT	
TURBO KIT	
OIL FILTER	
OIL FILTER	
FUEL FILTER	
FUEL FILTER	
PLUG KIT	
HIGH STRENGTH RED THREADLOCKER	
CABLE TIE	
CABLE TIE	
14 OZ PENRAY NC VOC BRAKE	
MACK ENGINE OIL EOS-4.5 1	
263 PRIMERLESS THREADLOCKER	
FLANGE SCREW	
HIGH TEMP ANAEROBIC SEALANT	



Sold Operations (Cont.)

DESCRIPTION	
FLANGE SCREW	
CYLINDER HEAD, REMAN	
CYLINDER HEAD, REMAN	
DE-CARBONIZING KIT	
SURF.COND.DISC, 2" DIA COARSE	
SURF. COND DISC, 2" DIA MEDIUM	
FREIGHT	
THERMOSTAT	
FLANGE SCREW	
CAMSHAFT BEARING KIT	
CAMSHAFT BEARING KIT	
FLANGE SCREW	
LUBRIPLATE 105 GREASE	
O-RING KIT	
FLANGE SCREW	
ANTI-FREEZE - NITRATE FREE	
COOLANT FILTER	
AIR FILTER, PRIMARY RADIA	
INDICATOR	
TURBO KIT	
CYLINDER HEAD, REMAN	

Prepay: \$-11,357.70 Parts: \$15,254.12 Labor: \$8,800.00 FRT: \$125.00 Misc: \$0.00 Sublet: \$0.00 \$12,821.42

JOB #5 213

SERVICE - REPLACE FUEL FILTERS

COMPLAINT
CAUSE
CORRECTION

PERFORM FUEL SYSTEM FLUSH -
FUEL SYSTEM CONTAMIANED WITH BAD FUEL FROM SITTING AS WELL AS
FLUSHED COMPLETE FUEL SYSTEM WITH FRESH FUEL AND REPLACED THE
D.

DESCRIPTION	
113 - FUEL	
PERFORM FUEL SYSTEM FLUSH	
044-000-000	
FUEL FILTER HOUSING	
FUEL FILTER	
FUEL FILTER	

Prepay: \$0.00 Parts: \$774.63 Labor: \$1,824.00 FRT: \$0.00 Misc: \$0.00 Sublet: \$196.00 \$2,794.63

JOB #6 258

SERVICE - AFTERTREATMENT SYSTEMS & FAULT TRACING

COMPLAINT
CAUSE
CORRECTION

REPLACE DPF FOUND DAMAGED -
INSTALLED NEW DPF. FOUND DPF COVER TO HAVE 2 GOUGES ON THE MATING SURFACE, HAD TO GRIND
DOWN TO ENSURE PROPER SEAL. INSTALLED REMAINING SENSORS, HARDWARE AND FENDER WELL. HAD
REPLACE MISSING HARDWARE. CLEARED CODES, RESET SOOT LEVEL. PERFORMED TEST DRIVE. REPAIR
PLETED.

Prepa

Sold Operations Totals

\$25,680.74