



01/24/2023 01:33 PM

Owner

Owner: [Redacted]

Inspection

Inspection Date: 01/24/2023 01:35 PM Inspection Type:

Repairer

Repairer Address City State Zip Email

Contact Work/Day FAX

Target Complete Date/Time: Days To Repair: 7

Vehicle

OEM Part Price Quote ID: 118071667

2017 Ford F-150 Raptor 4 DR Crew Cab Extra Short Bed
6cyl Gasoline Turbo 3.5
10 Speed Automatic

Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

VIN: 1FTFW1RG7HFA46304
Mileage Type: Actual
Code: P8554A
Int. Refinish: Two-Stage

Options

- | | | |
|--------------------------|-------------------------|--------------------------|
| 1st Row LCD Monitor(s) | 2nd Row Head Airbags | AM/FM CD Player |
| Air Conditioning | Aluminum/Alloy Wheels | Anti-Lock Brakes |
| Armrest(s) | Auto Locking Hubs (4WD) | Automatic Dimming Mirror |
| Black Bumper(s) | Black Grille | Bucket Seats |
| Carpeting | Center Console | Cruise Control |
| Daytime Running Lights | Dual Airbags | Dual Power Seats |
| Dual Pwr Lumbar Supports | Dual Zone Auto A/C | Elect. Stability Control |
| Electric Parking Brake | Electric Steering | Electronic Transfer Case |
| Floor Mats | Fog Lights | Full Size Spare Tire |
| Head Airbags | Intermittent Wipers | Keyless Entry Keypad |
| Keyless Entry System | LED Brake Lights | LED Headlamps |
| Leather Shift Knob | Leather Steering Wheel | Mirror(s) Memory |
| Overhead Console | Perimeter Alarm System | Power Door Locks |
| Power Mirrors | Power Windows | Pwr Accessory Outlet(s) |
| Pwr Driver Lumbar Supp | Rear View Camera | Rear Window Defroster |
| Reverse Sensing System | Side Airbags | Side Steps |
| SiriusXM Satellite Radio | Skid Plates | Tilt Steering Wheel |
| Tinted Glass | Tire Pressure Monitor | Tow Hooks |
| Traction Control System | Trailer Hitch | Trip Computer |

Wheel Lip Moldings

Wireless Audio Streaming

Wireless Phone Connect

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Stripes And Mouldings									
1	E	134		Flare,Wheel Opening LT	HL3Z16039AB			INC	SM
Front Bumper									
2	E	35		Filler,Front Bumper	HL3Z17D957AAPT			1.2	SM
3	L	35	13	Filler,Front Bumper	Refinish			1.2	RF
					0.5 Surface				
					0.6 Two-stage setup				
					0.1 Two-stage				
4	I	350		Brkt,Front Bumper Mtg LT	Repair			2.0*	SM
				High Strength Steel					
Front End Panel And Lamps									
5	E	29		Grille Assembly	HL3Z8200BB			1.0	SM
6	E	49		Filler,Grille LT	HL3Z8348C			INC	SM
7	E	41		Headlamp Assy,Led LT	HL3Z13008M			0.2	SM
8	E	71		Mldg,Headlamp Outer LT	HL3Z17C755BPTM			INC	SM
9	L	71		Mldg,Headlamp Outer LT	Refinish			0.6	RF
					0.5 Surface				
					0.1 Two-stage				
10	E	72		Mldg,Headlamp Outer RT	HL3Z17C754BPTM			0.2	SM
11	L	72		Mldg,Headlamp Outer RT	Refinish			0.6	RF
					0.5 Surface				
					0.1 Two-stage				
12	E	43		Brkt,Headlamp Mtg LT	HL3Z17C947G			INC	SM
13	E	1137		Brkt,Headlamp Mtg LT	FL3Z17C973A			INC	SM
Radiator Support									
14	E	99	01	Grille,Active	FL3Z8475F			1.0	SM
Front Body And Windshield									
15	E	103		Fender,Front LT	HL3Z16006A			2.4	SM
16	L	103		Fender,Front LT	Refinish			3.6	RF
					2.5 Surface				
					0.5 Edge				
					0.6 Two-stage				
Front Body Interior Sheetmetal									
17	E	111		Skirt,Inner Fender LT	JL3Z16103B			INC	SM
Front Doors									
18	E	207		Door Shell,Front LT	FL3Z1620125B			4.9	SM
				Aluminum					
19	L	207		Door Shell,Front LT	Refinish			4.4	RF
					2.7 Surface				
					1.0 Edge				
					0.7 Two-stage				
20	E	269		Rod,Front Door Check LT	FL3Z1623552A			INC	SM
Manual Entries									
21	EC			FRONT BUMPER	Replace Economy				SM*
				>> FAB FOUR AERO AFTERMARKET BUMPER					
21	Items								

2017 Ford F-150 Regular Cab Extra Short Bed
Claim #:

MC	Message
01	CALL DEALER FOR EXACT PART # / PRICE
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts
 Other Parts
 Paint & Materials
 Parts & Material Total

Labor

Rate	Replace	Repair Hrs	Total Hrs
------	---------	------------	-----------

Sheet Metal (SM)
 Mech/Elec (ME)
 Frame (FR)
 Refinish (RF)

Labor Total
 Gross Total
 Net Total (Final Bill)

\$10,700.01

Alternate Parts Y/10/00/00/10/10 Cumulative 10/00/00/10/10 Zip Code: 66434 Default
 OEM Part Prices DT 01/24/2023 01:34 PM EstimateID 1047235250695970816 QuoteID 118071667
 SPPL Yes Zip Code: 66434 Default
 Rate Name Default

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE AFTER MARKET PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE PARTS ARE PROVIDED BY THE PARTS MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

Op Codes

- * = User-Entered Value
- NG = Replace NAGS
- UE = Replace OE Surplus
- EU = Replace Recycled
- UM = Replace Reman/Rebuilt
- UC = Replace Reconditioned
- N = Additional Labor
- IT = Partial Repair
- ^ = Labor Matches System Assigned Rates
- EC = Replace Economy
- ET = Partial Replace Labor
- TE = Partial Replace Price
- L = Refinish
- TT = Two-Tone
- BR = Blend Refinish
- CG = Chippguard
- E = Replace OEM
- OE = Replace PXN OE Srpis
- EP = Replace PXN
- PM = Replace PXN Reman/RebIt
- PC = Replace PXN Reconditioned
- SB = Sublet Repair
- I = Repair
- RI = R & I Assembly