

Invoice

Date Invoice #
 1/22/2025 1996

Mileage/Hours	Equipment	Terms	Service Date	VIN	ESN
604,951	Unit 9	Due on receipt	1/22/2025	1XKDD49X1FJ43271	
MPN	Description	Quantity	Amount		
05-16401	Rubber Engine Mount	2	86.58		
07-03286RUB	Radiator Rubber Mount	4	303.00		
D84-1000-6122180	Poly 12 Rib Belt	1	138.49		
D84-1000-6061620	Poly 6 Rib Belt	1	70.98		
79A9782	Fan Clutch	1	1,189.88		
108925-25AM	2050 Clutch	1	918.85		
67428-435	Torque Rod	2	433.00		
67428-475	Torque Rod	2	379.34		
8240-0000-560	Torque Rod	2	409.34		
Q347367FLG	Power Steering Cap	1	30.03		
F50-6242-1275	AC Hardline	1	388.78		
3690067CUM	Belt Tensioner	1	363.99		
3689465CUM	Idler Pulley	1	140.53		
3691282CUM	Belt Tensioner	1	457.64		
U30026	Rear Engine Mount	2	1,029.10		
F34-1019	Receiver Dryer	1	150.15		
V50-1041-190140	90 Deg Coolant Hose	1	142.76		
RF87K214934	Clutch Release Shaft	1	49.46		
106C1498	Clutch Release Shaft	1	26.33		
2866636CUM	Exhaust Gasket	1	21.97		
K3600CL	Clutch Install Kit	1	473.45		
K160-2380	Clutch Control Lever	1	205.94		
F50-2351-0450	AC Hose	1	105.03		
FREIGHT	Freight	1	20.00		
E55-1116	Lever Assy	1	180.76		
E21-1003	Bell Crank	1	374.30		
PROGRAM	ECM Programming	1	550.00		
3102802CUM	O Ring	1	7.43		
3033247CUM	O Ring Seal	1	14.24		
V46-1000-25-0200	Heat Shield Wrap	2	91.00		
12110293	Connector 3 Way	1	5.91		
CN26400	Spade Terminal	3	4.71		
CLT012P	Tube Assy Lube	1	25.92		
4305230	Cover Clutch Housing	1	16.35		
63307	12-1.75 X 25MM	4	3.88		

Subtotal
Sales Tax (7.5%)
Total
Payments
Balance Due

Invoice

Date Invoice #
 1/22/2025 1996

Mileage/Hours	Equipment	Terms	Service Date	VIN	ESN
604,951	Unit 9	Due on receipt	1/22/2025	1XKDD49X1FJ43271	
MPN	Description			Quantity	Amount
67912	12mm Lock Washer			4	0.44
CC36077FLG	Fleetguard ELC Gal			18	244.80
202032	Penray Power Plus			2	16.86
202132PN	Penray Winter Thaw Treat			4	39.00
56864B	Webb Brake Drum			4	508.80
XKOTR4709E2GRN	23K Brake Shoe Kit			4	242.52
92424	5/8 x 4			4	11.96
92440	5/8 x 6			4	15.80
04461X	Cynex 15W40 Gal			12	189.24
D1030-3628	5/8 Sil Heater Hose			4	39.28
D1030-3758	3/4 Silicone Radiator Hose ft			7	67.76
40510	#10 Liner Clamp			4	13.48
40512	#12 Hose Clamp			4	13.72
HH038X25	3/8 Silicone Hose Ft			3	2.67
40506	#6 Liner Clamp			2	6.18
04998X	Dex Merc III qt			2	12.16
601925	Maxtron 75W90 Gal			0.5	18.43
92448	5/8 X 8			8	48.80
92446	5/8 X 7 1/2			8	43.76
94412	5/8 Crown Lock Nut			8	6.48
94584	5/8 Lock Nut			16	14.72
SP9-95121T	5/8 SAE Flat Washer Thick			48	36.48
94586	3/4 Nylon Lock Nut			2	4.24
0509121SPL	3/4 x 3 Washer Snubbing Engine Mount			2	20.24
0509057SPL	3/4 x 2 Washer Snubbing Engine Mount			2	26.52
66252	8 MM Nylon Lock Nut			5	1.10
67108	8mm Flat Washer			10	1.30
63171	6 x 25MM Bolt			5	0.90
67106	6MM Flat Washer			10	0.70
66250	6 MM Nylon Lock Nut			5	0.50
HWC01045	Spacer Round 5/8 x 3 x 0.12			4	17.28
70167	1/4 x 1/8 SAE Flare 90			1	3.16
WTLG	Wire Ties Large			24	5.76
WTSM	Wire Ties Small			20	3.20
HE27141	#12 Push On Power Steer Hose Ft			1	8.08

Subtotal
Sales Tax (7.5%)
Total
Payments
Balance Due

Invoice

Date Invoice #
 1/22/2025 1996

Mileage/Hours	Equipment	Terms	Service Date	VIN	ESN
604,951	Unit 9	Due on receipt	1/22/2025	1XKDD49X1FJ43271	
MPN	Description			Quantity	Amount
40510	#10 Liner Clamp			2	6.74
92200	7/16 x 2 1/2 bolt			8	7.20
95353	7/16 Lock Washer			8	0.56
71502	1/4 Brass Sleeve			1	0.24
63196	8 x 20mm Bolt			1	0.24
32172	Butterfly Wire Tie			8	34.24
D1030-2650	2 1/2 Silicone Radiator Hose ft			1	43.90
502620	#20 Clamp			4	9.96
F1842300	2 1/4 x 3 1/8 Constant Torque Clamp			6	51.42
92254	1/2 x 1 3/4			8	6.16
94580	1/2 Nylon Lock Nut			8	3.36
95159	1/2 SAE Flat Extra Thick			16	9.60
92064	5/16 x 3/4			2	0.32
95351	5/16 Lock Washer			2	0.08
TT3680922	ISX15 Flywheel			1	306.82
EC40PLS	Clamp Exhaust			1	15.22
44660	Cynex 15W40 Gal Jug			2	34.10
32106	7/8 Tubing Clamp			3	3.24
32141	1" Insulated Tube Clamp 1/4" hole			3	9.27
92008	1/4 x 1			1	0.11
94572	1/4 Lock Nut			1	0.23
95151	1/4 SAE Flat Washer ET			2	0.48
66250	6 MM Nylon Lock Nut			2	0.20
67108	8mm Flat Washer			2	0.26
63318	12 x 80MM Bolt			1	1.37
67112	12mm Flat Washer			2	0.58
66257	12MM Nylon Lock Nut			1	0.49
04998X	Dex Merc III qt			2	12.16
BRKCLN	Brake Clean			10	40.20
95408	7/16 External Tooth Washer			2	0.26
W346021	Clutch Washer			1	10.38
92792	7/16 x 1 1/2			12	6.72
95157	7/16 SAE ET Flat Washer			12	4.20
4988280CUM	Power Steering Gasket			1	4.96
3D2824	Cat O Ring			1	2.15

Subtotal
Sales Tax (7.5%)
Total
Payments
Balance Due

Invoice

Date Invoice #
 1/22/2025 1996

Mileage/Hours	Equipment	Terms	Service Date	VIN	ESN
604,951	Unit 9	Due on receipt	1/22/2025	1XKDD49X1FJ43271	
MPN	Description			Quantity	Amount
92008	1/4 x 1			1	0.11
94572	1/4 Lock Nut			1	0.23
95151	1/4 SAE Flat Washer ET			2	0.48
63196	8 x 20mm Bolt			1	0.24
67108	8mm Flat Washer			1	0.13
92508	3/4 x 5			2	9.32
95164	3/4 ET Flat Washer			4	6.12
DIESEL	Diesel Gal			47.483	150.00
24710N-610WHD	#10 Straight			4	79.16
24708N-608WHD	#8 Straight Female			2	27.94
H06908-250RWHD	#8 Stratflex Hose Ft			7	40.81
H06910-250RWHD	#10 Stratflex Hose Ft			10	64.80
R134A-30	R134A lb			4.5	56.52
LM11500	AC Oil Castrol			4	10.28
CB127760	Clutch Brake			1	36.73
786692	Maxtron 50W Synthetic			4.5	178.11
	SUBTOTAL				11,783.84
Labor	Troubleshoot low fuel pressure; found contaminants in fuel system. Run test on fuel; came back with high metal content & antifreeze in fuel system. Further diagnostics found fuel in cooling system. Remove valve cover, inspect top end, pressure test cooling system. Found when engine off and pressure on cooling system there was traces of coolant coming out of the return fuel line on the cylinder head. This indicated either a cracked cylinder head or injector cups leaking. Also when top end was off found issues with the camshaft. Entire fuel system needs replaced due to the amount of metal contaminants. Customer decided to replace engine with complete reman unit.			6.75	992.25T

Subtotal
Sales Tax (7.5%)
Total
Payments
Balance Due

Invoice

Date Invoice #
 1/22/2025 1996

Mileage/Hours	Equipment	Terms	Service Date	VIN	ESN
604,951	Unit 9	Due on receipt	1/22/2025	1XKDD49X1FJ43271	
MPN	Description			Quantity	Amount
Labor	Remove hood, cooling package, disconnect engine components, air intake tubing, fuel system, transmission, electrical, remove engine, clean frame rails, replace all fuel lines, flush tanks. Replace transmission head shaft, transmission fluid, clutch brake, clutch, clutch linkage, & pitman arms. Transfer all necessary components from original engine to reman engine. Install new flywheel, pressure test fan hub; fan hub was leaking. Install new fan hub, new engine & radiator mounts, new reman engine, hook up electrical & fuel system. Clean all air intake tubing & reinstall. Separate cooling package, flush radiator & wash radiator & air to air. Reassemble cooling package & reinstall with all new lines. Reinstall hood, rewire headlights, fill fuel tanks with fuel & winter treat. Have ECM recalibrated, fill with new extended life coolant, pressure lube with new oil. Run & test.			68.75	10,106.25T
Labor	Replace drive axle brakes and drums, rotate tires. Remove front and rear drive axle upper and lower torque arms. Cut out frozen hardware and replace. Adjust brakes, grease truck and check all fluids.			11.5	1,690.50T
Labor	Replace two worn AC lines from AC Compressor, replace leaking AC o rings & receiver dryer, recharge system. Run & test			3.25	477.75T
	SUBTOTAL				13,266.75
	Shop Supplies				453.30

Subtotal
Sales Tax (7.5%)
Total \$26,498.90
Payments -\$26,498.90
Balance Due \$0.00

Invoice

Date Invoice #
10/24/2024 1998

Mileage/Hours	Equipment	Terms	Service Date	VIN	ESN
	Unit 9	Due on receipt	10/24/2024		
MPN	Description			Quantity	Amount
DR7046RXCM WARRANTY	ISX15 Complete Engine w/ 2 year 200,000 mile factory warranty Additional 1 year warranty			1 1	44,000.00 2,000.00T

Subtotal
Sales Tax (7.5%)
Total \$46,150.00
Payments -\$46,150.00
Balance Due \$0.00