

Unit 2015 POLARIS R15RTE87AK RANGER XP 900
 EPS BLACK PEARL
 VIN/HIN/Serial No:4XARTE874FB937757

Color:
 Plate:

Keyboard:27
 Odom/Hrs In:18,095 Out:18,095

UTV REPAIR

Description:* Runs rough - Check codes
 * Sounds like brakes are metal on metal
 * Drivetrain noise

Resolution:* Diagnosed CEL and running rough issue - Low fuel pressure after driving for extended time
 - Replaced fuel pump asm.
 * Diagnosed brake issue - Rear calipers pushed pistons out due to extreme brake pad wear - Calipers were leaking
 - Replaced rear brake calipers and rotors
 - Replaced front brake pads and rotors
 * Replaced U-joints and rear slip yoke
 * Inspected CVT system - Worn belt and secondary rollers
 - Replaced worn drive belt and secondary rollers
 * Replaced RR CV shaft
 * Replaced leaking exhaust donut

Parts

Part #	Qty	Description	Price	Discount	Total
2872189	1.00	BRAKE FLUID			
1912136	1.00	ASM-BRK-CAL-RL-SB1.5"-GROOVED			
1912137	1.00	ASM-BRK-CAL-RR-SB1.5"-GROOVED			
2205949	2.00	K-asm pad Brake dB 1.375			
5248250	2.00	Disc-Brake Rear 8.625x.188			
5254999	2.00	DISC-BRAKE, FRONT			
5-170X	2.00	U-JOINT KIT			
7661913	1.00	Pin - Spring			
3235402	1.00	Yoke-Slip (6272008)			
HFP-A3961	1.00	Fuel Pump Assembly for RGR 900 / 800 / 570			
3610204	1.00	Exhaust seal/donut			
7041789	2.00	SPRING			
5413212	4.00	Seal Washer			
5439874	12.00	Bushing-Standard, ORV			
5138797	4.00	Shaft-pivot			
5138791	2.00	Pivot Bushing			
3514699	2.00	Bearing - Sealed			
3211149	1.00	Belt - Drive Rgr 900			
5439831	2.00	Roller-Clutch, 955 ODX.450			
201-338R	1.00	ASSY- HALF SHAFT, REAR (900/1000 RANGER)			

Parts Subtotal _____

Labor

Description	Technician	Hours
Repairs		5.5

Labor Subtotal _____

Job Subtotal _____

Approve: De _____

All Jobs Subtotal: _____

Shop Supplies: _____

Tax: _____

Total: _____

Less Deposits: _____

Total Due: _____

Charge on Account - Stelbar Oil: **\$2,977.39**

Your business is important to us! We greatly appreciate the opportunity to serve you.

All parts returns subject to 15% restocking fee and must be unused. No returns after 30 days. No returns on fuel or electrical parts.

Signature: _____

UTV REPAIR

Description:* Comes out of high gear in high speeds
 * Multi-point Inspection

Resolution:* Diagnosed - Worn engagement dogs in transmission
 - Removed transmission and rebuilt with all new engagement dogs, drive gears, bearings, differential asm. - Reinstalled transmission

Parts

Part #	Qty	Description	Price	Discount	Total
3235373	1.00	DIFF-LOCKING (411600)			
3234205	2.00	RING,RETAINING			
3235214	2.00	RING, RETAINING, EXTERNAL			
3235396	1.00	GEAR-49T (352231)			
3235233	1.00	DOG, ENGAGEMENT, 6-FACE			
3235231	1.00	SPROCKET-48T,6-FACE(352854)			
3235232	1.00	GEAR-67T LOW,(352856)			
3235457	1.00	SHIFT DOG, PARK/LOW (353357)			
3235216	1.00	RETAINING RING			
3233364	1.00	RING,RETAINING			
3233106	2.00	RING, SNAP			
3234269	1.00	RING,RETAININGBASICINTRN L2.047			
1205-0398	1.00	Transaxle Bearing/Seal Kit - MOOSE RACING			
3234851	1.00	Seal			
2878068S	1.50	AGL Fluid in QUART for shop use only			

Parts Subtotal _____

Labor

Description	Technician	Hours
Overhauled transmission		8.25

Labor Subtotal _____

Job Subtotal _____

Approve: _____

All Jobs Subtotal: _____

Shop Supplies: _____

Tax: _____

Total: _____

Less Deposits: _____

Total Due: _____

Charge on Account - Stelbar Oil: \$3,028.00

Your business is important to us! We greatly appreciate the opportunity to serve you.

All parts returns subject to 15% restocking fee and must be unused. No returns after 30 days. No returns on fuel or electrical parts.

Signature: _____