

INVOICE

1342

Org. Est. # 000317

INVOICE

Printed Date: 11/13/2025

Work Completed: 11/07/2025

2013 Freightliner - M2 Series - M2-106 - Cummins ISB6.7 CM22

Lic # : IAT219

Odometer In : 295122

Odometer Out : 295122

VIN # : 1FVACWDT4 DHB5140

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
BATTERY Size: 31-MHD 31-MHD	2.00			front main or oil pan is leaking- rear carrier bearing rubber is cracking- lift gate has broken lines- top center marker lights are broke and dont work- missing drivers side mud flap- both fuel tank caps are leaking- DEF pump housing is rusted out and hanging- serpentine belt is starting to crack-- reefer is throwing codes and wont start- needs fan pulley bearing customer wanted the truck to be inspected inspected truck truck wouldn't start found the batteries to be bad and the fuel system needed to be primed	

Org. Estimate

Labor:	
Parts:	
SubTotal:	
Tax:	
Total:	758.07
Bal Due:	

[Payments -]

Vehicle Received: 9/10/2025

Customer Number : 5

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Email Address:

INVOICE

1351

Org. Est. # 000316

INVOICE

Printed Date: 11/13/2025

Work Completed: 09/11/2025

0 -

Lic # :

Odometer In : 1

Odometer Out : 2

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
battery 1231mf	2.00			<p>needs turbo/ missing bolts and the seals are leaking oil, turbo oil supply lines are kinked-turbo has play in the bearings and will need replaced - turbo keeps falling off the truck so there is an issue with the manifold and will need to be replaced - rear main seal is leaking- hydro pump is leaking- blow off valve on the air tank is leaking and the air tank itself is only held onto the truck with one strap and is dangling from the truck- drivers side rear wheel seal is leaking- cross member bolts are all loose and have worn oval holes through the frame-</p> <p>both rear axle needs the dog bone springs rebuilt. it has so much play the two drive axles are walking side to side- needs all new tires on the drive axles- cords showing- king pins are starting to have play and eat the steer tires- grease fitting lines by the orange hose real are broke off</p> <p>customer wanted the truck inspected inspected the truck</p> <p>truck wouldn't start found the truck to have bad batteries</p>	

Org. Estimal

Labor:

Parts:

SubTotal:

Tax:

Total: 732.39

Bal Due:

[Payments -]

Vehicle Received: 9/11/2025

Customer Number : 132

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Email Address: