



MODEL/SER#  
C15/6NZ

MAKE/MODEL  
KENWORTH/W900

ACTIVITY	QTY
Parts	1
GOLD KIT	1
Parts	1
CYLINDER HEAD	1
Parts	6
OIL PUMP	6
Parts	1
INJECTOR ROCKER ARM	1
Parts	6
CAM SHAFT	6
Parts	6
EXHAUST ROCKER ARM	6
Parts	6
INTAKE ROCKER ARM	6
Parts	10
INSERT	10
Parts	1
OIL	1
Parts	1
TEMPERATURE SENSOR	1
Disposal	1
OIL AND FILTER DISPOSAL FEE.	1
SHOP SUPPLIES	1
Labor	1
ENGINE OVERHAUL	1
Labor	1
CUT ALL UPPER COUNTER BOARDS TO .032 THOUSANDS.	1



TOTAL	17,152.54
PAYMENT	17,152.54

Customer Signature






MODEL/SER#  
C15/6NZ **2001**

MAKE/MODEL  
KENWORTH/W900

ACTIVITY	QTY
Parts	1
TRUCK HARNESS	1
Parts	1
OIL COOLER	1
Parts	1
FLYWHEEL	1
Parts	1
MAIN BEARING KIT	1
Parts	1
FRONT COVER GASKET KIT	1
Parts	1
ENGINE HARNESS	1
Parts	1
SEAL	1
Parts	1
OIL COOLER GASKET KIT	1
Parts	6
REAR GASKET KIT	1
Parts	1
INSERT	1
Parts	1
ENGINE MOTOR MOUNT KIT	1
Parts	5
AC LINE #12	6
Parts	6
SLEEVE	4
Parts	1
ROD BEARING	1
Parts	1
HOOD BUSHING PIVOT	1
Parts	1
AC LINE #8	1
Parts	



Customer Signature



MODEL/SER#  
C15/6NZ

MAKE/MODEL  
FREIGHTLINER/

ACTIVITY

QTY

Parts  
ECM

1

Parts  
FREON

1

Parts  
OIL

10

Parts  
OIL FILTER

1

Parts  
FUEL FILTER

1

Disposal  
OIL AND FILTER DISPOSAL FEE.

1

SHOP SUPPLIES

1

Labor  
REMOVED AND INSTALLED NEW AC CONDENSER,  
CHARGED AC SYSTEM. FINAL CHECK OK.

1


Labor  
CHANGED OIL, REPLACED OIL FILTER AND FUEL FILTERS.  
FINAL CHECK OK.

1

SUBTOTAL  
TAX (4.75%)  
TOTAL  
BALANCE DUE

2,457.75

**\$2,457.75**



Customer Signature




Chrysler Financial LLC

Estimate: SO-1117

Quantity      Rate      Amount

cyliner head reseal, oil filter housing reseal	LABOR	18	
head gasket kit with head bolts included		1	
oil filter housing seal		1	
spacer plate under the head		1	



Total \$12,957.33




Customer Signature: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Date: \_\_\_\_\_

5/16/25, 3:40 PM

Estimate: SO-1117



Description	Quantity	Rate	Amount
-------------	----------	------	--------

Radiator change out with installation of new a/c condenser (does not include new hoses)	LABOR 2.5		
radiator assembly	1		
coolant	10		




A/C Condenser change out and recharged (installation is included with radiator bill)	LABOR .75		
Ac condenser	1		
freon	5		



hood repair	LABOR 2.5		
hood bushings	4		
hood bushings	4		
hood cables	2		



rear axle front drive out put seal	LABOR 1		
out put seal	1		
rear end oil	1		



Transmission swap, clutch and flywheel	LABOR 8		
50w oil (fleet pride)	1		