

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
	21	FORD EXPLORER	1FMSK8FH3MGA84421		125816/125844	T2163

PROD. DATE	WARR. EXP.	PO NO.	RATE	PAYMENT
				CASH

OPTIONS: DLR:F53493 ENG:2.3_Liter_TIVCT

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL	
A	C/S:	CUSTOMER STATES TRANSMISSION SHIFTS POORLY. SEEMS TO BUCK AND JERK WHILE ACCELERATING. CHECKING ADVISE DIAGAT AUTOMATIC TRANSMISSION CONCERN						

125816 diag trans 1.50 verified customer concern found vehicle to have harsh engagement and slam into gear failed cdf leakage test and has metal in the fluid recommend replacing unit due to being more cost affective

B MULTI POINT INSPECTION
99P 99P

(N/C)

C** REPAIR
CAUSE: verified customer concern found vehicle to have harsh engagement and slam into gear failed cdf leakage test and has metal in the fluid recommend replacing unit due to being more cost affective

REPAIR REPAIR

- CFLT
- 8 *W716375*S900 BOLT
- 6 *W719511*S439 BOLT
- 6 *W715618*S437 NUT

1 L1MZ*7000*R AUTOMATIC TRANSMISSION ASY
125844 transmission 11.10 installed new transmission replaced all one time use parts hardware gaskets and seals programmed the transmission then topped fluid off to specification then completed adaptive drive cycle and everything is running and driving as it should be and is good at this time.

D** 3/4 CYL DOUBLE PLATINUM

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	