

Job #1 - External

COMPLAINT: NEEDS ESTIMATE FOR ROOF DAMAGE. PICS ON FILE. SEE W/O 1534 FOR ADDITIONAL PICS. CUSTOMER HAS PAID THE ADMIN FEE FOR ESTIMATE. WAS PAID ON

*****NOTE PICTURES ON FILE. THIS IS ONLY AN ESTIMATE FOR REPAIRS. WE MAY ENCOUNTER SOME UNFORESEEN ITEMS THAT CANNOT BE DETERMINED DURING THE INITIAL ESTIMATE. SUPPLEMENTAL REQUEST MAY BE REQUESTED ONCE WORK HAS BEEN STARTED. SOME ITEMS MAYBE ON BACK ORDER WITH MANUFACTURE AND ETA CAN NOT BE DETERMINED AT THIS TIME. **** drop off on 09/07/2023 customer requested us to check all systems to confirm working prop

CAUSE: AC install

CORRECTION: Installed new AC from the unit that was missing from roof. Had to cut old holding bolts out as they were to bent to unscrew from ceiling assembly. Wired up new unit and tested operation. Unit works as intended.

Labor

Job #	Description
1	AVC INSTALL PREWIRED

Parts

Part #	Description	Qty
310208	DOMETIC M FRESH 15K-MECH VAL, BLK-AM, A/C	1.00
62-1032	DOMETIC RELAY BOARD	1.00

Other Services

Code	Description	Qty
SS	SHOP SUPPLIES	1.00
FRT	FREIGHT	1.00

Subtotal for Job #1:

Job #2 - External

COMPLAINT: R&R VENT COVER TIMES 2

CAUSE: R&r vents

Printed On: 9/28/2023 12:33:52PM

CORRECTION: Removed and replaced old vents and replaced with new units. Also replaced the old power fan unit in kitchen as it was destroyed. And resealed the power fan to prevent any leaks.

Labor

Job #
2 Description
VENT R&R COMPLETE

Parts

Part #	Description	Qty
520170	VENT LID SMOKE DOME ASSEMBLY	2.00
410196	F LAP SEALANT WHITE, SELF LEVEL	3.00

Subtotal for Job #2:

Job #3 - External

COMPLAINT: R&R MAXXAIR COVER IN WHITE

CAUSE: Install new maxx air cover

CORRECTION: Installed new maxx air cover on vent with existing holes drilled in it. Which was the unit over the bedroom. The front cabin area unit does not have one nor did it have holes pre installed on it.

Labor

Job #
3 Description
VENT COVER INSTALL FIRST ONE MAXXAIR TYPE

Parts

Part #	Description	Qty
520282	MAXXAIR VENT COVER TRANSLUCENT	1.00
520335	FAN-TASTIC VENT 12V WITH TSTAT	1.00

Subtotal for Job #3:

Job #4 - External

COMPLAINT: NOTE UNIT HAS AN OLD STYLE SATELLITE SYTEM THAT IS NO LONGER AVAILABLE. HAVE LISTED THE OPTION BELOW FOR REPLACEMENT OR CAN BE REMOVED AND NOTHING INSTALLED. NOTE CUSTOMER WILL HAVE TO SUBSCRIBE TO NETWORK TO MAKE WORK.

CAUSE: Installed satellite dish

CORRECTION: Installed new satellite dish and awaiting customer to purchase a dish box to finish up install. CUSTOMER WILL NEED TO PURCHASE A SAT PLAN AND GET THE RECEIVER.

Labor

Job #
4 Description
SATELLITE DISH INSTALL WINEGARD AUTOMATIC

Parts

Part #	Description	Qty
020061	CARRYOUT G3 WHITE	1.00
020020	WINEGARD ROOF KIT SECOND GENER	1.00

Other Services

Code	Description	Qty
M	ROOF MOUNT KIT FOR SAT SYSTEM-020020	0.00

Subtotal for Job #4:

Job #5 - External

COMPLAINT: NEED TO RESEAL THE ROOF. THE COMPLETE ROOF IS MADE OF METAL AND SHOWS NO SIGN OF DAMAGE. NEEDS TO BE RESEALED WITH DICOR.

CAUSE: Roof reseal

CORRECTION: Resealed the roof around the power fan unit as well as both vents and the skylight. Minor spots on roof around AC unit and a little spot on the back portion of roof.

Labor

Job #	Description
5	ROOF RESEAL

Subtotal for Job #5:

Job #6 - External

COMPLAINT: CUSTOMER REQUESTED THAT WE TEST AND MAKE SURE ALL ITEMS ARE FUNCTIONABLE AS DESIGNED. WATER PUMP, HEAT, DRAIN VALVES, A/C, ETC.

CAUSE: Inspection of all operating systems

CORRECTION: Inspected all operating systems to make sure everything worked. Tested water system, heat, water heater, AC, slides, and all faucets for leaks and operation. Everything works as intended.

Unit is not winterized

Labor

Job #	Description
6	INSPECT ALL OPERATING SYSTEMS

Subtotal for Job #6:

Job #7 - External

CAUSE: NONE

CORRECTION: COMPLETE

Other Services

Code	Description	Qty
M	DEDUCT PER FARM BUREAU	1.00

Subtotal for Job #7:

Parts Total:	
Labour Total:	
Sublet Total:	
Extras Total:	
MISSOURI STATE TAX:	
WORK ORDER TOTAL:	6,227.48

Customer Signature : _____

Date: 28 Sep 2023