

Invoice: INV-S-859

Invoice Date: Jun 22, 2026

Due date: Jun 22, 2026

:

Remit payment to

Unit	VIN/Serial #	Asset	Mileage	Eng Hrs
	60751	Yanmar VI050-6A	10	0

Service Order	Terms	Due date	Customer PO	Authorizer
S-859	Due on Receipt	Jun 22, 2026		

Description		Quantity	Rate	Amount
Full service, all fluids all filters, grease all				
Labor	Changed engine oil, engine oil filter, fuel filters, air filters, hydraulic filter, and final drive oil.	3.5		
Parts	Air filter, HD	1		
Parts	Air filter, HD	1		
Parts	15/40 Engine oil	1.5		
Parts	Gear Oil 80W-90	0.5		
Parts	Oil filter	1		
Parts	Fuel filter	1		
Make house routing improvements to reduce snags in woods. Bucket coupler hoses are the worst				
Labor	Re-routed and secured quicktach hoses and light wiring all the way up the boom. Diagnosed non working quick tach, electronic solenoid works when pulled from the valve block but will not actuate under hydraulic pressure when in the valve block, repaired and wired up a good switch.	14		
Parts	Switch, covered	1		
Make a sturdy thumb retract stop so the cylinder barrel does not become damaged				
Labor	Cut steel. Weld rest to stick. Ensure sturdy thumb retract stop. Verify cylinder barrel clearance. Test functionality. Job complete.	2.5		

Description		Quantity
See that the bucket fits,		
Labor	Put pins in bucket and made sure it fits the coupler correctly.	2
Test unit to ensure satisfactory performance		
Labor	Tested unit.	1
Install and adjust a relief valve on the thumb to prevent damage from the bucket curl		
Labor	Install relief valve and adjust so the bucket curl does not destroy the thumb	3
Parts	Relief Valve	1
Parts	Hydraulic oil	1.25
Parts	-8 fjc	2
Parts	-6 1/2npt	2
Parts	-8 fjc	1
Parts	-6 425 hose	0.7
Parts	-8 425 hose	6
Modify thumb to make it useable.		
Labor	Make thumb tines longer	2.5

Total	\$4,400.22
Payments	

Printed Name: _____ Date: _____