

# EQUIPMENT DETAIL REPORT

Print Date: 09/08/2026  
Print Time: 02:21:32 PM

## Identification

Equipment ID: SS3  
Equipment Name: 259D Skid Steer  
Equipment Class: 150  
Make: Cat  
Model: 259D  
Year: 2018  
VIN: FTL21094  
Tag Number:  
Notes: BR Const Equipment

## Status and Last Location

Equipment Status: Temporarily Out Of Service  
Purchase Date:  
In-Active Date: 01/01/9999  
Last Location: 1  
Last Reported Date: 08/14/2026

## EQUIPMENT WORK ORDER DETAILS

| WO Number | Work Type   | Maintenance Item Description                                                                                                                                                                                                                                | Mechanic      | Status    | Created On | Completed On | Total Cost |
|-----------|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----------|------------|--------------|------------|
| 3403      | Repair      | Failure to Start<br><b>Notes:</b> Won't start, may have bad alternator. Found the alternator bolt was loose and missing washer and had widened the hole. Shimmed it up and had the alternator tested and the wire on the back of the terminal had broken so | TJ Vanhuls    | Completed | 08/14/2026 | 08/14/2026   | 0.00       |
| 2183      | Repair      | Misc<br><b>Notes:</b> Pin plate needs replaced. Going to bring this unit back to shop in Tulsa. Installed new arm pins from the old style to the new style. Installed new tracks. Work done on 5/6/26 at 5243hrs                                            | Bobby Traster | Completed | 04/23/2026 | 05/06/2026   | 0.00       |
| 2182      | Maintenance | Tracks<br><b>Notes:</b> Tracks need replaced. Broken track arm pin on left side. Parts on order from Cat.                                                                                                                                                   | Bobby Traster | Completed | 04/23/2026 | 05/06/2026   | 0.00       |
| 2118      | Maintenance | Codes / Warning Lights / Alarms<br><b>Notes:</b> Code: Aftertreatment #1 DPF Outlet Gas Temp High. Found has bad differential pressure switch. ordered part from Cat. Code has not shown back up.                                                           | Taylor Howell | Completed | 03/13/2026 | 03/18/2026   | 0.00       |
| 2117      | Repair      | Misc<br><b>Notes:</b> Ordered new cab shocks, being installed; needs new sprockets-will install once parts on hand. Has hydraulic leak on bottom hose on right side down by idler. Found hose was loose at fitting, put new sprockets on and tight          | Taylor Howell | Completed | 03/12/2026 | 03/13/2026   | 0.00       |