

HEINEN REPAIR SERVICE, INC.
13424 EDWARDS ROAD
VALLEY FALLS, KS 66088

PHONE: 785/945-6711

PAGE 1

**
** I N V O I C E **
**

ACCOUNT CODE: PINBR

=====

PINE FAMILY LANDSCAPE
BRIAN PINE
1783 E. 1500 RD
LAWRENCE, KS. 66044

=====

T H A N K Y O U
For Letting Us Serve You.

Accounts Not Paid by 10th of month following service are subject to finance charge of 1.5% per month, annual percentage rate 18%; \$2.50 minimum charge.

DATE	SERVICE	PAYMENT	ITEM PRICE	CHARGE
=====				
PREVIOUS BALANCE ----->				445.07
02/11/2014 PAYMENT (CHECK #-->) 10063		445.07		

02/20/14	158 FORD F600			
1.00	586 CARB KIT	0.00	24.96	
2.00	BF-QT BRAKE FLUID (QT)	4.36	8.72	
1.25	27002 1/4 FUEL LINE (FT.)	1.14	1.42	
1.00	PF827 FUEL FILTER	0.00	3.70	
10.00	GAS GALLON	3.45	34.50	
1.00	750-7127 ALTERNATOR	0.00	53.30	
1.00	B2 FILTER	0.00	4.40	
5.00	4232H SYNCLEAN 10/30 QT	3.50	17.50	
1.00	36044 WHEEL CYLINDER	0.00	56.93	
1.00	36043NAPA CYLINDER	0.00	56.93	
1.00	TS-72 BRAKE SHOES	0.00	69.08	
2.00	22483 SEALS	10.06	20.12	
1.00	31155 STARTER	0.00	82.86	
2.00	28850NAPA WHEEL CYLINDER	66.25	132.50	
2.00	28851NAPA CYLINDER	58.67	117.34	
1.00	3982 BEARING CUP	0.00	40.78	
1.00	3920 BEARING CUP	0.00	12.12	
1.00	7440 BELT	0.00	89.12	
1.00	53-16970 DIMMER	0.00	18.21	
2.00	34387 CR SCOTSEAL	35.04	70.08	
2.00	1157 MINI BULB	1.00	2.00	
1.00	PARTS WIRE CONNECTORS	0.00	4.00	
17.00	80/90 GEAR LUBE (QT.)	4.62	78.54	
4.00	CBR88 RELINE REAR SHOES	40.09	160.36	
1.00	FRT FREIGHT	0.00	38.00	
1.00	MACHINE ALT MOUNT & ADJUSTER	0.00	140.00	
1.00	53-7547 TEMP SENDER	0.00	9.79	
1.00	SUPPLY CHG SHOP SUPPLIES	0.00	15.00	
1.00	P23527 BRAKE MASTER CYL-REMFD	0.00	81.63	
1.00	FRT FREIGHT	0.00	9.50	
1.00	M0735 MASTER CYLINDER	0.00	115.43	

HEINEN REPAIR SERVICE, INC.
13424 EDWARDS ROAD
VALLEY FALLS, KS 66088

PAGE 2

STATEMENT DATE: 02/26/2014
ACCOUNT CODE: PINBR

DATE	SERVICE	PAYMENT	ITEM PRICE	CHARGE
BALANCE CARRIED OVER ----->				3380.36
CHECKED SPARK & ADJUSTED POINTS. CLEANED PLUGS (SOME SEIZED). REPLACED LEAKING FUEL HOSES. TRY TO START - RAN SHORT TIME. R & I CARB & REBUILT. ADDED GAS. CHECKED GEAR OILS. FRONT BRAKES AND LEFT REAR LEAKING FLUID. DISASSEMBLED WHEELS & BRAKES. REPLACED ALL BRAKE WHEEL CYL- INDERS & SHOES, LEFT REAR OUTER BEARING, AND STARTER. SERVICE, GREASE, & CHECK FLUIDS. ADD REAR DIFFERENTIAL OIL. CHECKED TEMP GAUGE. REPLACED CONNECTOR & SENDER. CHECK OIL PRESSURE (40 PSI @ IDLE). REPLACED CLUTCH MASTER CYLINDER CAP. REPAIRED LIGHTS AS NEEDED. REPLACED HEADLIGHT DIMMER SWITCH. CHECK GENERATOR & REGULATOR. INSTALL ALTERNATOR & WIRING AS NEEDED. BRAKE MASTER CYLINDER LEAKING - REPLACED. CLUTCH MASTER CYLINDER LEAKING PAST PISTON - REPLACED.				
1.00	BF-QT BRAKE FLUID (QT)		0.00	4.36
	INSTALL CLUTCH & BRAKE MASTER CYL. BLED.			
	24.40 LABOR			1586.00
SUBTOTAL ** LABOR 1586.00 PARTS--> 1573.18 TAX--> 225.85 TOTAL-->				3385.03

```
=====
TOTAL PARTS--> 1573.18
TOTAL SERVICE--> 1586.00
TAX AMOUNT --> 225.85
=====
AMOUNT PAID --> 445.07
=====
PLEASE PAY THIS AMOUNT -----> 3385.03
=====
```