

Invoice

Date
11/17/2014

Invoice #
[REDACTED]

Bill To

Allen Thompson
105 East 1st Ave
Stockholm SD 57264

VIN

Trailer

P.O. No.

Reference #

Unit #

#51

Item	Description	Qu...	Rate	Amount
PROBK4707Q23PR	2 Brake Shoes & 1 4515kit	4	57.07	228.28T
3600AX	Balanced Brake Drum	4	125.94	503.76T
BRE11897	Cam tube 16.5 brake	4	29.97	119.88T
BRE11867	S cam shaft right	2	30.16	60.32T
BRE11866	S cam shaft left	2	30.16	60.32T
AS1140	Slack adjuster	4	91.46	365.84T
BWSR955335	ABS Sensor	3	55.08	165.24T
BWSRS4497130180	ABS Cable Ext.	2	13.72	27.44T
BWSR4497130500	ABS cable 16 foot	1	25.79	25.79T
GS 30	Type 30 Service Chamber	1	53.77	53.77T
Clamp	type 30	1	9.98	9.98T
Type 30	Pancake	1	5.02	5.02T
859	wheel seal	1	28.34	28.34T
330-3067	Large steering axle gasket	1	1.68	1.68T
Mobilith SHVC 0...	Mobilith SHVC 007 Grease for hubs	1	7.61	7.61T
5/16x1	Bolt	6	0.24	1.44T
5/16 Washer	Washer	6	0.13	0.78T
Labor/Hrs	Trailer brake job, with drums, slack adjusters, S cam bushings, S cam shafts, R&R bad ABS sensors, wheel seal on RRTA, R&R brake service chamber, clamp, pancake	15	59.00	885.00T
	Subtotal of Parts and Labor			2,550.49
Shop Supplies	Shop Supplies		1.50%	38.26T
	Subtotal of Parts and Labor			2,588.75

Total

Invoice

Date
11/17/2014

Invoice #
[Redacted]

Bill To

Allen Thompson
105 East 1st Ave
Stockholm SD 57264

VIN
Trailer

P.O. No.

Reference #

Unit #

#51

Item

Description

Qu...

Rate

Amount

0.00

155.33

Total

\$2,744.08