

Asset Name	Description	Date Completed	Completion Notes	Total All Costs
320-005 FLATBED [52-05]	Handle broken	26/06/2014 07.09.59	Street replaced door handle	14.08
320-005 FLATBED [52-05]	Won't start intermittently	06/08/2014 12.31.31	Replace fuel shut-off solenoid and fuel pump	170.15
320-005 FLATBED [52-05]	No crank No start	06/10/2014 10.42.30	Charged batteries, no help, replaced batteries,	191.48
320-005 FLATBED [52-05]	Fuel leak	24/01/2014 14.11.38	Fuel leak at rear of intake. Have to pull plenum to see injector lines to pump. Found leaking o'rings under fuel filter housing and leaking rubber lines. Replaced all.	40.19
320-005 FLATBED [52-05]	Fuel leak	24/02/2015 09.49.42	Replaced fuel filter	25.03
320-005 FLATBED [52-05]	Noise / Smoke from carrier bearing	10/03/2015 11.46.45	Replace bearing	64.02
320-005 FLATBED [52-05]	Headlamp out	09/04/2014 12.37.20	Replaced bulb	17.99
320-005 FLATBED [52-05]	Replace tires @ Kansasland	25/04/2014 16.36.24	Kansasland Invoice #145803	811.20
320-005 FLATBED [52-05]	Oil leak	13/01/2014 10.39.30	Replaced rear main seal, Trans output shaft seal and torque converter seal, fuel line	88.34
				1422.48

#4

TAKES 8 QUARTS OIL

UNIT NO 52-5

1GBJC34F9YF471492

(STREET
FLAT Bed)

[illegible]