

336-002
UNIT NO. 73-32

2001 S-10 4x4
4.3L W
1GCDT19W418227507

#8

(Jim)

SERVICE
OWN

DATE	LUB.	OIL CHANGE	OIL	FILTERS FUEL	AIR	TRANS.	DIFF.	BRAKES	MISC. REPAIRS	EQUIP. HOURS OR MILEAGE	NA
2-17-09									NEW FUEL PUMP RELAY	86758	Rob
3-12-09									NOTE: WORKING ✓ FUEL PUMP CIRCUIT AGAIN		Rob
4-30-09									PRESSURE TESTED NOTIFREEZE DOOR D/EIDE	88186	Rob
3-20-10								NEW FRONT	NEW CAP/ROTOR/PLUGS C/SED NEW REAR SHOCKS PLUG	98496	Rob
4/23/10					Replaced Hood Release Cable					99334	John
7-19-10									INSTALLED NEW BATTERY		Rob/Leo
									REPLACED FRONT REAR PADS, OUTER TIE ROD END, ALL BALL JOINTS, UPPER CONTROL ARM BUSHINGS, FRONT SHOCKS, D/S FRONT AXLE SEAL, D/STRT INNER CV BOOT, FRONT AXLE SHOCK CABLE SEAL @ AXLE	115541	LL
10-11-11									NEW FUEL PUMP RELAY		Rob
10-26-11									NEW SERP. BELT NEW WATER PUMP	116225	Rob
11-2-11								NEW PLUGS CAP/ROTOR	REPAIRED FUEL PUMP NEW FUEL PUMP RELAY	116432	Rob
12-2-11									NEW RH TINTATOR/BATTERY NEW VAC MOD FOR H-WHEEL		Rob
1-19-12									NEW FLASHER UNIT		Rob
8-30-12									A/C LINE - EVAP TO CONDENSOR & RECHARGE SYSTEM		LL
8-3-13									INNER PULLEY OF SERP BELT, A/C LINES (DOUBLE OUT OF COMPRESSOR)	132827	LL
8-3-13									UPPER CONTROL ARM BUSHINGS (BOTH SIDES) NEW FRONT PADS/ROTOR/SHOCKS		
									RETIRED		