

1323

Unit # Search

FIRST

PREV-PAGE

NEXT-PAGE

LAST

SERVICE HISTORY

Customer: 035694 Name: JIM KIDWELL CONST
CO., INC.

To UPDATE, click Item Id.

Prev Component

Select Component

Next Component

Add Service

Cat 953 C

Unit
Id: 1323 Component: GENERALComponent
Total: .00 Uni
Total

UNIT #	YEAR
<u>1323</u>	2005
<u>1401</u>	
<u>1517</u>	
<u>1545</u>	2006
<u>1601</u>	
<u>1701</u>	1966
<u>1702</u>	2000
<u>1805</u>	2005
<u>1806</u>	
<u>1807</u>	
<u>1828</u>	2006
<u>1837</u>	2004
<u>1838</u>	2004

Item Id	Service Date	Description	Meter	Cost	Part Number
<u>&nbsp;02/11/15</u>		replaced fan drive,adjuster,two idler pulleys,surpentine belt,l.h. door latch and striker	8387	.00	
<u>&nbsp;02/04/15</u>		resealed cam follower plates,adjusted valves,replaced speed and timing sensors,replaced crankcase breather,replaced temperature control cable,tightened shanks,washed,and detailed cab	8367	.00	
<u>&nbsp;01/14/14</u>		Replaced undercarriage,new rails,new pads,new wear strips,new carrier rollers,new bottom rollers,new bolts and caps on rollers,new idlers,resealed slack adjusters,replaced pads and pins in hard bar,new sprocket segments,replaced bottom bucket pins and bearings and replaced dog bone pins and bearings,new seals in pivot shaft,adjusted tracks,has 4 year or 4000 hr. warranty.	7417	.00	
<u>&nbsp;07/22/13</u>		Replaced fan motor for AC.Replaced alternator.	6872	.00	
<u>&nbsp;07/15/13</u>		Replaced water pump.	6864	.00	
<u>&nbsp;12/17/12</u>		Repacked tilt cylinder and detailed and washed.	6400	.00	