

1545

Unit # Search

FIRST

PREV-PAGE

NEXT-PAGE

LAST

SERVICE HISTORY

Customer: 035694

Name: JIM KIDWELL CONST CO.,
INC.

To UPDATE, click Item Id.

Prev Component

Select Component

Next Component

Add Service

Unit
Id: 1545 Component: GENERALComponent
Total: .00 Unit
Total: .

UNIT #	YEAR
<u>1545</u>	2006
<u>1601</u>	
<u>1701</u>	1966
<u>1702</u>	2000
<u>1805</u>	2005
<u>1806</u>	
<u>1807</u>	
<u>1828</u>	2006
<u>1837</u>	2004
<u>1838</u>	2004
<u>2001</u>	2013
<u>2013</u>	
<u>2018</u>	2007

Item Id	Service Date	Description	Meter	Cost	Part Number
<u>&nbsp;</u>	01/22/15	replaced both front idlers with new because of bearing failure	6145	.00	
<u>&nbsp;</u>	01/31/14	Replaced undercarriage,new rails,new pads,all new bottom rollers,new carrier rollers,new sprockets,new front idlers,repacked slack adjusters,all new pins and bushings in dozer.	5653	.00	
<u>&nbsp;</u>	03/03/10	Replaced blade angle link on control valve.	3233	.00	

John Deere 650 J