

CURRENT
METER
12,022

SHERWOOD LEASING, INC.
MECHANICS EQUIPMENT REPAIR HISTORY REPORT

05 CAT 330CL QC D TMB HD

Equip Num: **20.58L**

Model: **330CL**

Serial Number: **DKY03714**

Date Purchased: **2005/06/22**

Vendor And Parts Information					Labor Repair Information		
Inv Date	Inv No.	Vendor	Inv Descr	Amount	Date	Mechanic Repair Descr	Hours
					2016/09/14	purple wave prep RR	2.00
					2016/09/13	purple wave prep MB	2.00
					2016/09/13	purple wave prep RR	2.00
					2016/09/08	remove movac cntrls RR	11.00
					2016/09/08	rmv movac harness DS	7.50
					2016/09/07	remove movac sys RR	4.00
2016/08/31	SS100016413	F	REPL MSTR LINK / 2 ROLLER	1,043.66			
2016/08/16	SS000019313	F	2 TRACK BOX LINKS DAC/DI	2,082.13			
					2016/08/16	wash rack MB	4.00
					2016/08/15	wash rack MB	6.00
					2016/07/25	chk engine codes RR	2.00
					2016/07/09	clean, org tools RR	0.50
					2016/07/08	chk ops, eng, hyd leaksRR	3.00
2016/06/29	PS000076684	F	BEARING/SEALS KK	502.44			
2016/06/28	PS000076565	F	COUPLER PIN KK	384.33			
2016/06/22	33906	F	ULTRA CLEAN KK	140.25			
					2016/06/28	rpr linkage, install movax JG	5.00
					2016/06/28	remove link pin RA	1.00
2016/06/13	439801	J	BOLTS SS	9.33			
					2016/06/27	rpr linkage JG	2.00
					2016/06/27	weld repairs RA	4.00

Equip Num: 20.58L**05 CAT 330CL QC D TMB HD**Model: 330CLSerial Number: DKY03714Date Purchased: 2005/06/22

Vendor And Parts Information					Labor Repair Information		
<u>Inv Date</u>	<u>Inv No.</u>	<u>Vendor</u>	<u>Inv Descr</u>	<u>Amount</u>	<u>Date</u>	<u>Mechanic Repair Descr</u>	<u>Hours</u>
2016/03/11	16-231		REBUILD CYL SS	599.79	2016/03/11	assemble q/c EK	6.00
					2016/03/11	put couper on JH	4.00
					2016/03/03	take quik change cyl to bynuJD	1.00
					2016/03/03	cat to order parts JD	1.50
					2016/03/02	tear down quik coupler JD	4.50
					2016/03/02	wash coupler TD	2.00
					2016/03/01	remove quik chg/inst bkt JD	8.50
					2016/03/01	d/o quik chg at shop BB	1.00
2016/02/12	PS100584116		SEAL SS	15.62	2016/02/25	work on hyd coupler JH	2.00
2016/02/11	41344		LINE BORE QUICK COUPL/ST	5,925.50	2016/02/16	put pin back in track JA	4.00
2016/02/01	PS100582639		HOSE SS	243.96	2016/02/15	fix hyd leak JH	2.50
					2016/02/02	heat/beng track pad JH	4.00
					2016/02/01	lower trav hose/hyd cont JH	11.00
2016/01/25	PS100581758		COUPLING/SEAL/HOSE SS	83.48			
2016/01/22	PS100581575		UBOLT/CLAMP/PIPE SS	2,102.80			
2016/01/26	CS100053179		SEAL SS	-15.15			
2016/01/27	PS100582098		CONTROL GROUP SS	645.57			
2016/01/29	252539		HOSE SS	72.65			
2016/01/26	PS100581929		SEAL SS	15.15	2016/01/30	find hyd leak JH	1.50

Equip Num: 20.58L**05 CAT 330CL QC D TMB HD**Model: 330CLSerial Number: DKY03714Date Purchased: 2005/06/22

Vendor And Parts Information					Labor Repair Information		
Inv Date	Inv No.	Vendor	Inv Descr	Amount	Date	Mechanic Repair Descr	Hours
					2016/01/29	chg hyd lines DB	3.50
					2016/01/26	blow out heater core JH	3.50
					2016/01/25	clean work area JH	3.00
					2016/01/23	r/r hose/replace muffler JH	4.50
					2016/01/22	look for hyd leak JH	2.50
2016/01/12	PS100580266		CAP SCREW/NUT/WASHER S	10.03	2016/01/12	put pin back in bucket JH	2.50
					2016/01/11	won't start JH	5.50
2015/12/16	PS100577695		BEARING SS	124.88			
2015/12/15	PS100577633		ROLLER SS	31.60			
2015/12/16	PS100577837		SEAL SS	30.14			
2015/12/15	PS100577634		SET BELT SS	123.62			
2015/12/16	I550025675		GLASS SS	234.94			
					2015/12/16	install seat/front glass RG	10.00
					2015/12/15	r/r bearings/install quik co R	11.00
					2015/12/14	q/c/ bearing/seals RG	3.00
					2015/10/17	drop off parts JD	1.50
2015/09/18	PS110803099		SEALS & BEARINGS SS	521.52			
2015/09/29	29420		R RECOVER SEAT BC	325.00			
2015/09/22	PS110803616		PINS/BEARINGS/LINK & SEA	4,970.05			
					2015/09/17	leak on turntable AC	2.00
					2015/09/16	pin coming out AC	2.00
2015/08/24	WO120023728		SERVICE SS	159.70			
2015/08/24	WO120023728		FILTERS/OIL SS	116.15			

Equip Num: 20.58L**05 CAT 330CL QC D TMB HD**Model: 330CLSerial Number: DKY03714Date Purchased: 2005/06/22

Vendor And Parts Information					Labor Repair Information		
Inv Date	Inv No.	Vendor	Inv Descr	Amount	Date	Mechanic Repair Descr	Hours
2015/08/24	WO120023727		PM1 11417 HR BC	400.00			
2015/08/31	1742294		PM1 11417 HR BC	400.00			
2015/08/20	PS110797906		COUPLER SS	21.85			
2015/08/11	WO110240486		SEALS/PINS/BEARINGS SS	4,522.72			
2015/08/11	WO110240486		REBUILD SWING DRIVE MTI	2,658.60			
2015/08/06	PS100562290		CAP SCREW SS	12.68			
					2015/08/11	fix swing drive AC	3.00
					2015/07/29	pull swing motor AC	2.00
					2015/07/28	pull swing motor AC	1.00
					2015/07/24	swing motor leaking AC	2.00
					2015/07/14	clean breather 4 swing AC	2.00
					2015/07/07	hyd. leak AC	1.00
					2015/07/06	fix hyd. lines AC	2.00
2015/07/28	PS100561001		HOSE/SEAL/COUPLING SS	141.98			
2015/06/06	PS000046808		FREIGHT PARTS IN CS	90.95			
					2015/06/11	hyd hose AC	4.00
					2015/06/10	hyd. hose AC	1.00
					2015/06/09	a/c inop/needs controler AC	2.00
2015/06/10	PS110784939		HYD HOSE SS	256.89			
2015/06/11	PS110785242		CONTROL/CLIP SS	371.00			
2015/05/29	PS000046103		ROLLERS & TRACK BOLTS S	1,458.01			
2015/05/07	CS100050910		PIN SS	-157.84			
2015/04/23	PS110777321		SWITCH SS	141.56			
2015/04/13	PS110775348		CONTROL GROUP SS	3,937.89			

Equip Num: 20.58L**05 CAT 330CL QC D TMB HD**Model: 330CLSerial Number: DKY03714Date Purchased: 2005/06/22

Vendor And Parts Information					Labor Repair Information		
Inv Date	Inv No.	Vendor	Inv Descr	Amount	Date	Mechanic Repair Descr	Hours
2015/01/19	PS100538064		SLEEVE GUIDE SS	40.04			
2015/01/15	PS100537722		FUEL PUMP/GASKETS CS	5,030.09			
2015/01/23	CS100049892		CORE CREDIT SS	-1,093.86			
2015/01/19	PS100538065		DRILL BIT SS	7.83			
2015/01/16	228959		HOSE & FITTING JD	46.90			
					2015/01/16	r/r fuel fltr, cap, hoses JD	5.50
					2015/01/15	cups, injectors JM	11.50
					2015/01/13	chk fuel in coolant JH	4.00
					2015/01/05	chk engine JH	3.00
2014/12/23	OKTU1123356		BOLTS JD	10.67			
2014/12/31	1670807		BOLTS JD	10.67			
2014/12/23	PS100535348		PUMP/ORINGS SS	1,289.42			
2014/12/23	CS100049644		PUMP KIT SS	-211.50			
2014/12/22	PS100535186		PUMP KIT SS	211.50			
					2014/12/23	rpr fuel probs JH	9.00
					2014/12/22	rpr oil leak JH	4.00
					2014/12/17	r/r hoses JD	2.00
2014/11/06	CS100049242		LINLS/BUSHINGS SS	-398.41			
2014/11/17	PS100531309		SCREW SS	5.34			
2014/11/21	PS100532002		ROLLER/SCREW/STRIKER SS	163.75			
2014/11/25	PS100532219		CATCH/ASSEMBLY SS	85.56			
2014/11/25	PS100532221		BRACKET/WASHER SS	133.76			
2014/11/21	2334		WELDING JD	225.00			
2014/11/25	PS100532220		BRACKET/STOPPER SS	38.13			

Equip Num: 20.58L**05 CAT 330CL QC D TMB HD**Model: 330CLSerial Number: DKY03714Date Purchased: 2005/06/22

Vendor And Parts Information					Labor Repair Information		
Inv Date	Inv No.	Vendor	Inv Descr	Amount	Date	Mechanic Repair Descr	Hours
					2014/07/25	chk finals, clean a/c fltrs KM	1.50
					2014/07/15	chk trvl alarm KM	0.50
					2014/07/14	r/r hyd hose, seals KM	1.00
					2014/07/09	apply warn decals KM	0.50
2014/05/27	PS110716549		ROLLER/LINKS/COVER/BRAI	578.58			
					2014/05/23	rpr window JH	2.00
					2014/05/16	window rpr JH	1.00
2014/04/30	WO100099812		REPAIR WINDOW ROLLER FI	951.30			
2014/04/30	WO100099812		REPAIR HYD LEAKS JD	1,017.64			
					2014/04/14	weld rpr bckt RA	5.00
2014/02/07	PS100495218		BATTERIES JD	649.00			
2014/02/05	PS100494950		HOSES/PUMP JD	1,082.44			
2014/02/26	WO100097735		HYD PUMP /ORINGS/FLANGI	12,594.39			
2014/02/26	WO100097735		PISTON PUMP/HOSES & MON	1,918.73			
2014/02/26	WO100097735		OIL COOLER GASK/SEALS/O	24.89			
2014/02/26	WO100097735		ENG OIL LINES/ADAPTER PL	366.57			
2014/02/26	WO100097735		BATT CS	42.25			
2014/02/26	WO100097735		UPGRADE HYD FAN PUMP D	233.24			
2014/02/26	WO100097735		R/R PISTON PMP/HOSE/MON	5,793.75			
2014/02/26	WO100097735		R/R OIL COOLER CS	2,812.50			
2014/02/26	WO100097735		R/R OIL HOSES/ADAPTER PL	3,768.75			
2014/02/26	WO100097735		R/R BATT CS	843.75			
2014/02/26	WO100097735		R/R HYD PMP/FLANGE/HOSE	1,631.25			
2014/02/26	WO100097735		REPL REMOTE OIL FILTER L	2,306.25			

2000 HRS
SINCE
RPR.

Equip Num: 20.58L**05 CAT 330CL QC D TMB HD**Model: 330CLSerial Number: DKY03714Date Purchased: 2005/06/22

Vendor And Parts Information					Labor Repair Information		
<u>Inv Date</u>	<u>Inv No.</u>	<u>Vendor</u>	<u>Inv Descr</u>	<u>Amount</u>	<u>Date</u>	<u>Mechanic Repair Descr</u>	<u>Hours</u>
					2010/10/11	bucket opin,dw	2.00
2010/09/09	SVWO0334842		RELIEF VALVE PWS	204.55			
2010/09/09	SVWO0334842		REPLACED RELIEF VALVE PWS	91.18			
2010/09/09	SVWO0334842		DECAL & COOLANT PWS	77.25			
2010/09/15	PCSL0842360		THUMB PIN/RETAINER PWS	973.38			
2010/09/09	SVWO0334842		SUPER-TUEN HYD PWS	1,462.03			
2010/08/19	PCSL0832942		BUCKET PARTS PWS	584.60			
2010/08/25	SVWO0331731		TRACK LINKS/SHOES PWS	13,520.69			
2010/08/25	SVWO0331731		RECOIL SPRING/ROD PWS	2,951.53			
2010/08/25	SVWO0331731		DISASSEM RECOIL SPRING PWS	317.14			
2010/08/25	SVWO0331731		R & I TRACK SHOES PWS	2,188.40			
2010/08/25	SVWO0331731		ASSEM RECOIL SPRING PWS	138.76			
2010/08/25	SVWO0331860		BOOM CYL SLS/BEARINGS PWS	615.33			
2010/08/25	SVWO0331860		BUCK.CYL ROD,SEALS/BRGS	1,986.10			
2010/08/25	SVWO0331860		THUMB CYL SEALS PWS	125.68			
2010/08/25	SVWO0331860		REBUILD CYL ROD PWS	538.54			
2010/08/25	SVWO0331860		RECONDITION BOOM CYL PWS	610.93			
2010/08/25	SVWO0331860		RECONDITION BUCKET CYL	519.74			
2010/08/25	SVWO0331860		RECOND. THUMB CYL PWS	310.02			
2010/08/25	SVWO0331860		THUMB ROD/BEARING PWS	350.78			
2010/08/31	SVWO0334407		PAINT FULL MACHINE DK	5,216.96			
2010/08/19	9516554		WELDING SUPPLY DK	496.49			
2010/08/11	29547		BREAK STEEL-BUCKET DK	1,218.40			
2010/08/07	PCSL0828950		FUEL VALVE & FRAME SUPP	539.41			

Equip Num: **20.58L**

05 CAT 330CL QC D TMB HD

Model: **330CL**

Serial Number: **DKY03714**

Date Purchased: **2005/06/22**

Vendor And Parts Information					Labor Repair Information		
<u>Inv Date</u>	<u>Inv No.</u>	<u>Vendor</u>	<u>Inv Descr</u>	<u>Amount</u>	<u>Date</u>	<u>Mechanic Repair Descr</u>	<u>Hours</u>
2010/08/07	PCSL0828951		BUCKET PARTS PWS	200.74			
2010/08/10	PCSL0829415		GREASE LINE PWS	60.67			
2010/08/11	PCSL0829914		TRACK ADJ PARTS PWS	72.96			
2010/08/11	PCSL0829915		LIGHT BRACKET PWS	62.24			
2010/08/12	PCSL0830488		BOOM & STICK PINS/BEAR. 1	8,190.27			
2010/08/12	PCSL0830488		SIDE DOORS/SEAT PWS	1,706.00			
2010/08/12	PCSL0830488		IDLERS/ROLLERS PWS	5,089.96			
2010/08/04	PCSL0827293		FUEL TANK VALVE PWS	47.14			
2010/08/05	PCSL0827882		COUPLER PARTS PWS	286.86			
2010/08/12	PCSL0830490		FINAL DRIVE BOLTS PWS	8.68			
2010/08/12	PCSL0830491		FINAL DRIVE PARTS PWS	68.74			
2010/08/12	PCSL0830492		WINDSHIELD WIPER MOTO	228.49			
2010/08/06	PCSL0828342		SIDE BUMPER & VALVE PWS	184.54			
2010/08/13	PCSL0830969		WINDSHEILD WASHER VALV	2.37			
2010/08/13	PCSL0830973		HYD HOSE SEALS PWS	26.46			
2010/08/14	PCSL0831441		BUCKET THUMB PARTS PWS	185.58			
2010/08/14	PCSL0831442		QUICK COUPLER SPACERS P	138.72			
2010/08/17	PCSL0831888		HYD LINE CLAMP PWS	23.18			
2010/08/18	PCSL0832414		HYD HOSES PWS	440.36			
2010/08/19	PCSL0832935		BUCKET PARTS PWS	173.40			
2010/08/04	184553		FLAT STEEL BUCKET DK	357.50			
2010/08/06	116 IV-099742		STEEL FOR BUCKET PWS	564.50			
2010/08/04	9467838		WELDING SUPPLIES DK	483.75			
2010/07/27	183753		CREDIT	-583.82			