

Unit 1360 2007 KENWORTH T800

\*Unit ID:

1360

\*Description:

2007 KENWORTH T800

Exclude Reports Only Exclude Inactive

Definition Meters Fluids Specs PM Warranty Cost Shifts History Licenses Misc After Market Assignments Accessories User Fields

Drag a column header here to group by that column

Component	Description	Position	Make	Part ID	Model	Capacity	Serial Number	Part Type	String1
011	Axles - Non-driven, Front		DANAX		E1202I		SE0634576129		
012	Axles - Non-driven, Rear		LINKN		8A000490		06145009		
022	Axles - Driven, Rear	REAR01	DANAX		DSP40		SHN02626449	3.90	
022	Axles - Driven, Rear	REAR02	DANAX		DSP40		SHN02626450		
026	Transmission - Main, Manual		FULLR		FR016210C		S0627197		
045	Power Plant		CTRPL		C13 335		KCB83739		

## Repair Order Detail

### TranSpec Leasing, Inc.

Repair Order: OMA-00040892	Status: CLOSED	Repair Class: NONSCHEDULED
Shop: OMA		Repair Site: FACILITY
Unit: 1360	Customer: TRALEA	Opened: 1/15/2015
2007 KENWORTH T800	I/CO-TL - TRANSPEC	Closed: 1/23/2015
		Completed: 1/21/2015
Domicile: OMA	Make: KNWRT	Odometer: 509,309
Cost Cntr: 1101 OMA	Model: T800	
License:	Year: 2007	
VIN: 1XKDDU9X87J205538	In Service: 1/25/2011	

Section: 1	Complaint: LEAKING	Comments:
Priority: 1	Rep Reason: INSPECTION	Reseal Trans Top Plate, Oil Filter Housing Gasket, Due For A, B, C
Component: 026-009	Unit War: None	Services
Cover Assembly		
War. Type: NO WARRANTY		

Vendor: AUTOBRA AUTO BRAKE & CLUTCH INC

#### Comments

Date:	Comment Text	Vendor
01/19/15	finish removing trans steam trans remove top cover [LONWIL]	N
01/20/15	seal top cover install clutch and trans adjust clutch [LONWIL]	N

#### Labor

Date:	Mechanic	Description	Vendor	Hours	Rate	Total
01/15/15	ROGSAL	Cover Assembly	N	1.03	\$25.00	\$25.75
01/15/15	ROGSAL	Cover Assembly	N	3.65	\$25.00	\$91.25
01/19/15	LONWIL	Cover Assembly	N	3.53	\$25.00	\$88.25
01/19/15	LONWIL	Cover Assembly	N	0.27	\$25.00	\$6.75
01/19/15	LONWIL	Cover Assembly	N	3.67	\$25.00	\$91.75
01/20/15	LONWIL	Cover Assembly, LEAKING, REPAIRED	N	3.03	\$25.00	\$75.75

#### Parts

Date:	Part ID	Description	After Mkt	Vendor	Qty	Unit Price	Total
01/19/15	26-4302156	FRO16210 TRANSMISSION TOP PLATE GASKET		N	1.00	\$1.70	\$1.70
01/20/15	26-4305294	SHIFT GASKET		N	1.00	\$4.80	\$4.80

#### Services

Date:	Description	Vendor	Charge	Total
01/19/15	CLUTCH & RESURFACE FLYWHEEL	Y	\$647.83	\$647.83

## Repair Order Detail

### TranSpec Leasing, Inc.

Repair Order: OMA-00040892		Unit: 1360	
Section: 2	Complaint: LEAKING	Comments:	
Priority: 5	Rep Reason: OILCONSUMPT	replace oil filter housing gasket	
Component: 045-011	Unit War: None		
Filter Assembly - Oil			
War. Type: NO WARRANTY			

#### Comments

Date:	Comment Text
01/15/15	disassembled oil filter housing [JACTHE]
01/19/15	cleaned parts [ROGSAL]
01/19/15	started to put together [ROGSAL]
01/20/15	road tested w ith a load [ROGSAL]

#### Labor

Date:	Mechanic	Description	Hours	Rate	Total
01/15/15	JACTHE	Filter Assembly - Oil, LEAKING, DISASSEMBLE	4.35	\$25.00	\$108.75
01/15/15	DOUREI	Filter Assembly - Oil	1.25	\$25.00	\$31.25
01/19/15	ROGSAL	Filter Assembly - Oil	1.12	\$25.00	\$28.00
01/19/15	ROGSAL	Filter Assembly - Oil	0.70	\$25.00	\$17.50
01/19/15	ROGSAL	Filter Assembly - Oil	3.55	\$25.00	\$88.75
01/20/15	ROGSAL	Filter Assembly - Oil	2.82	\$25.00	\$70.50
01/20/15	ROGSAL	Filter Assembly - Oil	0.05	\$25.00	\$1.25
01/20/15	ROGSAL	Filter Assembly - Oil, NO PROBLEM, ROADTEST	0.82	\$25.00	\$20.50

#### Parts

Date:	Part ID	Description	After Mkt	Qty	Unit Price	Total
01/20/15	45-B99-MPG	OIL FILTER	Y	1.00	\$13.25	\$13.25
01/20/15	53-ANTIFREEZE	ANTIFREEZE		2.00	\$8.84	\$17.68
01/20/15	42-2398140	hose WTR I NL	E	1.00	\$26.52	\$26.52
01/20/15	42-2398144	hose WTR O UT	E	1.00	\$38.12	\$38.12
01/20/15	45-0619455	SEAL	Y	1.00	\$8.51	\$8.51
01/20/15	45-1135304	SEAL	Y	2.00	\$12.48	\$24.96
01/20/15	45-1978418	GASKET	Y	1.00	\$2.14	\$2.14
01/20/15	45-1978418	GASKET	Y	1.00	\$2.15	\$2.15
01/20/15	45-1978419	GASKET	Y	2.00	\$2.18	\$4.36
01/20/15	45-2242675	seal press	Y	1.00	\$7.37	\$7.37
01/20/15	45-2246360	SEAL	Y	2.00	\$9.60	\$19.20
01/20/15	45-2894135	turbo gasket	Y	1.00	\$11.32	\$11.32
01/20/15	45-2894135	turbo gasket	Y	1.00	\$11.26	\$11.26
01/20/15	45-2274892	GASKET	Y	1.00	\$6.09	\$6.09

# Repair Order Detail

## TranSpec Leasing, Inc.

**Repair Order:** OMA-00040892      **Unit:** 1360

<b>Section:</b> 3	Complaint: PM	Comments:
<b>Priority:</b> 5	Rep Reason: PM	A service
<b>Component:</b> 000-002	Unit War: None	
<b>Pm Level A</b>		
<b>War. Type:</b> NO WARRANTY		

### Labor

Date:	Mechanic	Description	Hours	Rate	Total
01/20/15	ROGSAL	Pm Level A, PM, PERFORMED	2.20	\$25.00	\$55.00
01/20/15	ROGSAL	Pm Level A, PM, PERFORMED	0.02	\$25.00	\$0.50

### Parts

Date:	Part ID	Description	After Mkt	Qty	Unit Price	Total
01/20/15	44-BF1259	FUEL FILTER	Y	1.00	\$7.50	\$7.50
01/20/15	44-BF7587	FUEL FILTER	Y	1.00	\$6.49	\$6.49
01/20/15	53-3909	OIL SAMPLE	Y	1.00	\$11.50	\$11.50
01/20/15	53-CD550	15W/40 ENGINE OIL	Y	11.00	\$8.01	\$88.11
01/20/15	53-HD2	CHASSIS LUBE	Y	3.00	\$3.19	\$9.57

<b>Section:</b> 4	Complaint: PM	Comments:
<b>Priority:</b> 5	Rep Reason: PM	B service
<b>Component:</b> 000-003	Unit War: None	
<b>Pm Level B</b>		
<b>War. Type:</b> NO WARRANTY		

### Labor

Date:	Mechanic	Description	Hours	Rate	Total
01/20/15	ROGSAL	Pm Level B, PM, PERFORMED	1.65	\$25.00	\$41.25

### Parts

Date:	Part ID	Description	After Mkt	Qty	Unit Price	Total
01/20/15	13-AV950011	DRIER CARTRIDGE MODEL 1200	E	1.00	\$16.79	\$16.79
01/20/15	13-K022105	PURGE VALVE KIT	E	1.00	\$92.61	\$92.61
01/20/15	15-P528	Power Steering Filter KW	E	1.00	\$6.91	\$6.91
01/20/15	53-DEXRON	ATF	E	1.00	\$2.10	\$2.11

<b>Section:</b> 5	Complaint: PM	Comments:
<b>Priority:</b> 5	Rep Reason: PM	C service due
<b>Component:</b> 000-004	Unit War: None	
<b>Pm Level C</b>		
<b>War. Type:</b> NO WARRANTY		

### Comments

Date:      Comment Text



## Repair Order Detail

### TranSpec Leasing, Inc.

**Repair Order:** OMA-00040892      **Unit:** 1360

01/19/15      STARTED C SERVICE DRAIN AND FILLED REAR REAR END ONLY [LONWIL]

#### Labor

Date:	Mechanic	Description	Hours	Rate	Total
01/19/15	LONWIL	Pm Level C	0.68	\$25.00	\$17.00
01/20/15	LONWIL	Pm Level C, PM, PERFORMED	3.07	\$25.00	\$76.75
01/21/15	LONWIL	Pm Level C, PM, PERFORMED	0.02	\$25.00	\$0.50

#### Parts

Date:	Part ID	Description	After Mkt	Qty	Unit Price	Total
01/21/15	53-75/90	SYN 75/90		60.00	\$3.12	\$187.20
01/21/15	53-TL50	SYN 50 WT.		30.00	\$3.36	\$100.74

**Section:** 6      Complaint: IRREGULAR WE      Comments:  
**Priority:** 5      Rep Reason: INSPECTION      swap LF & LR outside tires  
**Component:** 017-001      Unit War: None  
**Tire - Pneumatic**  
**War. Type:** NO WARRANTY

#### Comments

Date:      Comment Text

01/20/15      sw apped tires and torqued to 450 [ROGSAL]

#### Labor

Date:	Mechanic	Description	Hours	Rate	Total
01/20/15	ROGSAL	Tire - Pneumatic, NO PROBLEM, INSPECTED	0.70	\$25.00	\$17.50

**Section:** 7      Complaint: DIRTY      Comments:  
**Priority:** 5      Rep Reason: PRE-DELIVERY  
**Component:** 999-999      Unit War: None  
**Total Vehicle**  
**War. Type:** NO WARRANTY

#### Labor

Date:	Mechanic	Description	Hours	Rate	Total
01/20/15	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	0.92	\$25.00	\$23.00

**Section:** 8      Complaint: LEAKING      Comments:  
**Priority:** 5      Rep Reason: DRIVERREPORT      replace leaking trans cooler hoses  
**Component:** 042-005      Unit War: None  
**Water Manifold**  
**War. Type:** NO WARRANTY

#### Comments

Date:      Comment Text

# **Repair Order Detail** TranSpec Leasing, Inc.

**Repair Order:** OMA-00040892      **Unit:** 1360

01/21/15      replaced trans cooler lines [MATGIL]

## **Labor**

Date:	Mechanic	Description	Hours	Rate	Total
01/21/15	MATGIL	Water Manifold, LEAKING, REPLACED NEW	1.73	\$25.00	\$43.25

## **Parts**

Date:	Part ID	Description	After Mkt	Qty	Unit Price	Total
01/21/15	53-ANTIFREEZE	ANTIFREEZE		3.00	\$8.84	\$26.52
01/21/15	94-28442	3/4 HEATER HOSE GREEN	Y	5.00	\$2.84	\$14.20

## **Totals Repair Order OMA-00040892**

Total Parts Issued:	139.00
Total Labor Hours:	40.83
Total Part Charges:      \$	769.68
Total Labor Charges:	1,020.75
Total Tax Charges:	0.00
Total Fee Charges:	0.00
Total Service Charges:      \$	647.83
<b>Repair Total:</b>	<b>2,438.26</b>