# DA0534

# Repair Order Detail TranSpec Leasing, Inc.

Repair Order: OMA-00046952

Shop:

Status: CLOSED Repair Class: NONSCHEDULED

OMA

1196 Unit:

Customer: TRSPLF

**FACILITY** 

Repair Site:

4/7/2016

2002 FREIGHTLINER

TRANSPEC LEASE FLEET

Opened:

Closed:

Domicile: Cost Cntr: **OMA** 

Make:

Completed:

6/7/2016 5/26/2016

1101 OMA

Model:

**FRGHT** 

License:

Year:

FLD120

1FUJAHCG32LG30228

2002

VIN:

In Service: 5/5/2006

Section:

Complaint:

DIRTY

Comments:

Priority:

5

Rep Reason: PRE-DELIVERY

Component: 999-999 Unit War:

None

Total Vehicle

War. Type:

NO WARRANTY

#### Comments

Date:	Comment Text
04/07/16	cleaned engine and frame [CLAWIL]
04/07/16	replacing batteries [CLAWIL]
04/09/16	buffing outside [CLAWIL]

## Labor

Date:	Mechanic	Description	Hours	Rate	Total
04/07/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	1.63	\$25.00	\$40.75
04/07/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	1.40	\$25.00	\$35.00
04/07/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	1.10	\$25.00	\$27.50
04/08/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	5.27	\$25.00	\$131.75
04/08/16	CLAWIL	Total Vehicle, NO PROBLEM	5.65	\$25.00	\$141.25
04/09/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	0.68	\$25.00	\$17.00
04/09/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	0.65	\$25.00	\$16.25
04/11/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	0.18	\$25.00	\$4.50
04/11/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	3.10	\$25.00	\$77.50
04/11/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	5.83	\$25.00	\$145.75
04/12/16	CLAWIL	Total Vehicle, NO PROBLEM, CLEANED	4.75	\$25.00	\$118.75
05/26/16	ROGSAL	Total Vehicle, NO PROBLEM, CLEANED	0.00	\$25.00	\$0.00

Priority:

War. Type:

Section: 2 5

MISSING Complaint:

Rep Reason: INSPECTION

Comments: Install Sleeper Cabinets

Component: 002-050

Sleeper

Unit War: None

## Comments

Date:

Comment Text

NO WARRANTY

Version: 13.20.1

TRANSMAN by TMT Softw are

Page: 1 2/2/2017 3:06:56 PM

## Repair Order Detail

TranSpec Leasing, Inc.

1196 Repair Order: OMA-00046952 Unit:

04/12/16 installed cabnets in same spot they were b4 they were removed. used all new

screws do not know where the old screws

went. had to cut new vent holes for ducts that were installed after cabnets were 04/12/16

removed. [MATGIL]

#### Labor

Date:	Mechanic	Description	Hours	Rate	Total
04/12/16	MATGIL	Sleeper, NOT CONNECTE, DRILLED	2.53	\$25.00	\$63.25
05/17/16	ROGSAL	Sleeper, ROUTINE, REASSEMBLE	0.02	\$25.00	\$0.50

Priority:

3 5 Complaint:

ROUTINE

Comments:

LTO

999-100 Component:

Unit War:

Rep Reason: PRE-DELIVERY None

COMPLETE LTO INSPECTION

War. Type:

Section:

NO WARRANTY

#### Comments

Date: Comment Text

05/09/16 LTO inspection [ROGSAL]

#### Labor

Date:	Mechanic	Description	Hours	Rate	Total
05/09/16	ROGSAL	COMPLETE LTO INSPECTION	5.05	\$25.00	\$126.25
05/09/16	ROGSAL	COMPLETE LTO INSPECTION, ROUTINE,	0.33	\$25.00	\$8.25
05/17/16	ROGSAL	COMPLETE LTO INSPECTION, ROUTINE,	0.00	\$25.00	\$0.00

Section: Priority:

4 5 Complaint: **INOPERATIVE** Rep Reason: INSPECTION

Comments:

Pull one rod & one main to inspect

Component: 045

Power Plant

War. Type:

Unit War: None

#### Comments

Date: Comment Text

05/09/16

need to replace rods and mains [ROGSAL]

05/10/16

replaced rods mains gaskets and o-ring [ROGSAL]

05/10/16 finished A service [ROGSAL]

**NO WARRANTY** 

## Labor

Date:	Mechanic	Description	Hours	Rate	Total
05/09/16	ROGSAL	Pow er Plant	2.13	\$25.00	\$53.25
05/10/16	ROGSAL	Pow er Plant	5.08	\$25.00	\$127.00
05/10/16	ROGSAL	Pow er Plant, WORN OUT, REPLACED USE	1.75	\$25.00	\$43.75
05/17/16	ROGSAL	Pow er Plant, WORN OUT, REPLACED REB	0.02	\$25.00	\$0.50

Generated by: MIKE.BEAMAN

Version: 13.20.1

TRANSMAN by TMT Softw are

Page: 2

2/2/2017 3:06:56 PM

# Repair Order Detail

TranSpec Leasing, Inc.

Parts						
Date:	Part ID	Description	After Mkt	Qty	Unit Price	Tota
05/09/16	45-23539104	OIL PAN GASKET, BLACK, S60	Е	1.00	\$57.71	\$57.7
05/09/16	45-27531606	rod and main bearing kit w /thrust w ash	ers E	1.00	\$352.51	\$352.5
05/10/16	44-BF5800	FUEL FILTER	E	1.00	\$3.81	\$3.8
05/10/16	44-BF5810	FUEL FILTER	E	1.00	\$3.64	\$3.6
05/10/16	45-B495-MPG	OIL FILTER	E	2.00	\$16.05	\$32.1
05/10/16	53-CD550	15W/40 ENGINE OIL		11.00	\$7.36	\$80.9
05/10/16	53-HD2	CHASSIS LUBE		3.00	\$2.32	\$6.9
Section: Priority: Component: Cab & Shee War. Type:		Complaint: BROKEN Comments Rep Reason: INSPECTION REAR MUD Unit War: None	S: FLAPS NEED REPL	ACED		
Comments						
Date:	Comment Text					
05/10/16	replaced mud flaps	[ROGSAL]				
Labor						
Date:	Mechanic	Description		Hours	Rate	Tota
05/09/16	ROGSAL	Cab & Sheet Metal		0.03	\$25.00	\$0.75
05/10/16	ROGSAL	Cab & Sheet Metal, WORN OUT, REPLAC	CED NEW	1.03	\$25.00	\$25.75
05/17/16	ROGSAL	Cab & Sheet Metal, WORN OUT, REPLACED NEW		0.00	\$25.00	\$0.00
Parts						
Date:	Part ID	Description	After Mkt	Qty	Unit Price	Tota
05/10/16	02-24X30BP	BLACK PLASTIC MUD FLAP	Υ	2.00	\$4.00	\$8.00
Section: Priority: Component: Cab & Sheet War. Type:	6 5 002 Metal NO WARRANTY	Complaint: IMPROPERLY A Comments Rep Reason: INSPECTION MATCH Q FE Unit War: None				
Comments						
Comments Date:	Comment Text					
		s the same [ROGSAL]				
Date: 05/11/16		s the same [ROGSAL]				
Date: 05/11/16 .abor		s the same [ROGSAL]  Description		Hours	Rate	Tota
Date:	made quater fenders			Hours 0.52	Rate \$25.00	Total \$13.00