



We have an APP for that! See our website for details!

page 1

Repair Order #65193 Sub-Estimate #10

COMMUNITY LIVING



Day Phone :



Fax Number :

Vehicle : 2005 Ford Truck Freestar 3.9 L 238 CID V6

VIN : 2FMZA51685BA76975

Fleet # : 12

Created : 8/23/2016 2:02:09 PM

Contact : Marty Wexler



Srv Writer: L.S.

Tag/State : &CT45S / MO

Color : White

Last Mileage : 119764

Odometer In : 119764

Odometer Out : 119764

Qty	Code/Tech*	Reference	Description	Condition	Unit Price	Price
1	--	MISC	G.E.M.Module assy		\$637.88	\$637.88
1	D.O.*	999-I-FLASH	PCM Reflash programming procedure		\$149.95	\$149.95
1	D.O.*	ProDemand	CONTROL MODULES Remove & Replace	M	\$96.50	\$96.50
1	--	SHIPPING	Freight charges		\$22.00	\$22.00

Note: M - Labor Database, Copyright, Mitchell International, All Rights Reserved

Labor	\$270.72	less discount : \$24.27	\$246.45
Parts			\$659.88
Sublet/Misc.			\$0.00
Env. Fees/Shop Supp.			\$35.00
Charges			\$0.00
Sales Tax			\$0.00
Tax Exempt			\$0.00

Tech
D.O.

Certification #
Doug O MRRT092-3807

Repair Total
\$941.33