

|               |               |                                   |                   |         |                 |         |
|---------------|---------------|-----------------------------------|-------------------|---------|-----------------|---------|
| COLOR         | YEAR          | MAKE/MODEL                        | VIN               | LICENSE | MILEAGE IN/ OUT | IAG     |
|               | 00            | FORD F-350 DRW                    | 1FDWF37F1YEA87809 |         | 36193/36193     |         |
| DEL DATE      | PROD. DATE    | WARR. EXP.                        | PROMISED          | PO NO.  | RATE            | PAYMENT |
|               |               |                                   | 18:30 07JUL14     |         |                 | CASH    |
| R.O. OPENED   | READY         | OPTIONS: ENG:7.3_Liter_D-TURBO-DI |                   |         |                 |         |
| 08:28 07JUL14 | 08:49 30JUL14 |                                   |                   |         |                 |         |

| LINE | OPCODE | TECH | TYPE | HOURS | LIST | NET | TOTAL |
|------|--------|------|------|-------|------|-----|-------|
|------|--------|------|------|-------|------|-----|-------|

A RUNS ROUGH

60 DIAG AND REPLACE ENGINE

|                                   |         |         |          |
|-----------------------------------|---------|---------|----------|
| 540 CEF                           |         | 2200.00 | 2200.00  |
| 1 XC3Z*6007*CARM REMAN ENGINE ASY | 9251.53 | 9251.53 | 9251.53  |
| CORE CHARGE C                     |         | 3200.00 | 3200.00  |
| 1 397115520 TUBE                  | 24.60   | 16.85   | 16.85    |
| 1 F81Z*8600*MA FAN ASY            | 114.62  | 114.62  | 114.62   |
| 2 203PP BEARING                   | 25.55   | 11.24   | 22.48    |
| 1 VC*5* ANTI-FREEZE               | 16.56   | 13.66   | 13.66    |
| 15 15W40D 15W40 DIESEL            | 2.90    | 2.59    | 38.85    |
| 1 XT*5*QMC FLUID - TRANSMISSION   | 6.26    | 5.17    | 5.17     |
| -1 XC3Z*6007*CARM CORE RETURN     | 3200.00 | 3200.00 | -3200.00 |

PARTS: 9463.16 LABOR: 2200.00 OTHER: 0.00 TOTAL LINE A: 11663.16

SERIAL# 454512

\*\*\*\*\*

CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER 25.00

ATTENTION ATTENTION ATTENTION ATTENTION  
 Manufacturers recommend wheel stud nuts be  
 retorqued after 500 miles whenever wheels  
 have been removed for service.  
 ATTENTION ATTENTION ATTENTION ATTENTION

Customer Signature X

THANK YOU

| DESCRIPTION            | TOTALS   |
|------------------------|----------|
| LABOR AMOUNT           | 2200.00  |
| PARTS AMOUNT           | 9463.16  |
| GAS, OIL, LUBE         | 0.00     |
| SUBLET AMOUNT          | 0.00     |
| MISC. CHARGES          | 25.00    |
| TOTAL CHARGES          | 11688.16 |
| LESS INSURANCE         | 0.00     |
| SALES TAX              | 981.81   |
| PLEASE PAY THIS AMOUNT | 12669.97 |

CUSTOMER COPY