

MB
242 Invoice

Date	Invoice #
3/7/2014	13434Z

		T	
		D	
MODEL		VIN	ODOMETER
01 FREIGHTLINER FL80		1FVHBXAK71HH69062	288716
Item	Description	Qty	Rate
2613816	PAN GASKET	1	
7W5340	GASKET	1	
3P1156	O-RING	2	
1R739	FILTER OIL	1	
15W40G	ROTELLA	7	
NPN	BOLT 1/4 X 1	4	
AP10051	J-NUT	1	
L0034-094	ASY LUBE	1	
FREIGHT	DROP SHIP	1	
LABOR	REMOVED OIL PAN. REPLACED ROD AND MAIN BEARINGS, OIL PICKUP TUBE, O-RING AND GASKET. INSTALLED NEW PAN GASKET AND RE-INSTALLED OIL PAN. CHANGED OIL AND FILTER.	10	
LABOR	DIAGNOSE OIL LEAK ON LEFT OF ENGINE - COULD NOT TELL FOR SURE. NEEDS ENGINE PRESSURE WASHED AND RE-CHECKED.	1	
Date paid:		Subtotal \$3,616.50	
Check #		Sales Tax (7.475%) \$0.00	
Credit Card		Total \$3,616.50	
Cash		Payments/Credits \$0.00	
		Balance Due \$3,616.50	

Invoice

Date	Invoice #
3/7/2014	13434Z

					T
					D
MODEL		VIN	ODOMETER	MISC.	
01 FREIGHTLINER FL80		1FVHBXAK71HH69062	278716		
Item	Description		Qty	Rate	Amount
SUBLET	TURN FLYWHEEL		1		
107342-12	CLUTCH		1		
105C137	CLUTCH FORK		1		
FUL8677	BUSHING		1		
FUL12815	BUSHINGS		2		
797700C1	CLUTCH BRAKE		1		
SP/106C1498	CLUTCH SHAFT		1		
02-09788-007	CLUTCH SHAFT		1		
2223909	REAR MAIN SEAL		1		
4305294	SHIFT TOWER GASKET		1		
3669086C2	BEARING		1		
PF-4A	CLAMP 4"		1		
LABOR	REMOVED TRANSMISSION. REPLACED REAR MAIN SEAL, CLUTCH, CLUTCH SHAFTS, CLUTCH FORK, CLUTCH BRAKE, PILOT BEARING, SHAFT BUSHINGS, SHIFT TOWER GASKET AND EXHAUST CLAMP. RE-INSTALLED TRANSMISSION. TEST DROVE.		14		
2124893	BEARING		1		
1077708	BEARING		6		
2246638	BEARING		6		
			Subtotal		
			Sales Tax (7.475%)		
			Total		
			Payments/Credits		
			Balance Due		