

#77

Mower
#62

1994 FORD 8770 TRACTOR

D402704

Tires: Rear 18.4 R 42
Front 16.9 R 28

TRACTOR Number

D402704

Model

MC915V

unit

4F16B

? D402490

ENGINE

WD 467540

TRANSMISSION

94015456

Front axle

49856

Hyd. Pump

N541186

Engine Serial: WE 471960

Engine Model: WEX211

FWD Factor: 1.324

Filters: oil - 86605897 New Holland

water - 861361 " "

Fuel 87840136

Air - outside 9846494 510

Inside 9846495 250

Wix Baldwin

oil 51158 - B7215

Water 24071-BW 5137

Fuel 33231

FAN Belt: New Holland North America 86013678

STARTER: Delco Remy

Series - 37MT

TYPE - 300

Model - 1993988

Serial - 94E28

Volt - 12 G L

Rotation - CW

89th

CAB - outside cab FILTER

New Holland

Baldwin

9823782

PA 3824

1994 Ford Tractor 8770

6-15-04 relocated trans. breater to fill spout

2-1-05 Removed rear wheel weights & front end weights

2-2-05 Removed main fuel tank to look for leak

2-3-05 Replaced fuel tank

7-24-06 Put in two new batteries & blowed out radiator

10-2-06 Checking out seat & blowed out radiator

10-23-06 Repairing broken fuel hose

7-24-07 Went to country & cked hyd. oil & tractor & gearboxes on mower

8-15-07 Blowed out Radiator

11-6-07 Repairing 2WAY Radio

11-14-07 Repairing Leaking Fuel Line

7-15-08 Working on signal Flasher - put in new flash

8-27-08 Put one can of Freon in AC & put New cylinder on left door

9-3-08

9-4-08 Working on elect. trouble

- 9-16-08 Put new drive line on from tractor to mower
- 11-10-08 Put on new windshield wiper blade
- 9-2-09 Put in one can of Freon in AC
- 12-3-09 Changed engine oil & filter, water filter, washed out radiator
- 7-19-10 Working on AC + 1 trip to Cadyer
- 8-25-10 Checking temp. Senders.
- 9-14-10 Replacing O-Ring in center hyd. hose to mower
- 10-7-10 Removing top of cab to get to expansion valve & evaporator
- 10-11-10 1 trip to HAYS + working on AC pick up drier
- 10-12-10 Working on AC R & R expansion valve + Drier + Blowing out evaporator + put top back on
- 10-14-10 Vacuumed system & charged $4\frac{1}{2}$ cans - Freon
- 6-1-11 Bleeding brakes, replaced broken fuel line & helped haul to country
- 6-2-11 Working steering wheel - 2 trips Added 4 cans - Freon
- 6-6-11 Working on AC. Removing top of cab

6-8-11 Put in new hyd. cyl. on steering wheel till
+ working on beacon light.

6-15-11 Put in new high & low pressure switches for AC

7-19-11 Charge batteries & started - filled with Anti-Freeze

7-20-11 charging batteries & started

7-21-11 Put in two new batteries

8-11-11 Went to Ogallah to Bleed Brakes

9-20-11 Bleed brakes

9-29-11 Bleeding brakes

10-26-11 Bleeding brakes, open heater valves & filling
engine oil

11-24-11 Changed oil & put away

5-9-12 charging Batteries & started

5-31-12

7-31-12 Blowed out Radiator & removed Stops on 3rd

8-27-12 Blowed out Radiator

11-14-12 chg. Batteries & started

- 1-30-13 Bleed ~~of~~ Brakes
- 2-1-13 Took to P.V.I.I To have brakes Repaired & hyd. connection
Valves Resealed
- 8-7-13 chg. BAT & started unhooked mower & Removed rollers
on Front end
- 8-8-13 Working on PTO & Air SEAT
- 8-9-13 Replaced PTO shaft with larger one & SEAT and
put in New Rollers
- 8-12-13 Working on SEAT Air system
- 8-20-13 Changed Hyd. & TRANS. Filters
- 10-16-13 Installed new batteries
- 11-4-13 Changed Fuse Behind Radio (Buss 320 7AMP)
Nice ~~are~~ Roof insulation
- 11-3-14 Arel Speed sensor was unplugged plugged in / Blew out
Radiator (10-27-14)
- 12-18-14 Serviced Changed oil & Filter, Air cleaner, Water Filter
for Radiator. Fuel Filter was Not in AT Drenches, CAB in.
Air Filter changed
- 7/29/15 Charged AC 3 CANS Neon Changed oil & Fuel Filter
Top off Hyd oil Hyd lever should NOT RAISE DIAL
ON CONSOLE WAS SET AT MAX moved TO HALF worked
Fine

8-22-16

ADD 3 CANS FERRON, 1 CAN STOP LEAK, 1 CAN PAG OIL
COOLED TO 45° GREASED FRONT END.

9-29-16

CHANGED FRONT DRIVE SHAFT SEAL KIT 87324559
CHANGED OUT BACKED OUT PUT SHAFT.

11-3-17

R&R RIGHT REAR SIDE WINDOW BROKE ON WAY
BACK FROM FARM EMP, FARM EMP REPAIR REMOTE
LEAKS