

Front Diff.
Zahnradfabrik Passau GmbH
Serial # 12584
Type - APL-365E
Part List No. 4472055021
TOTAL RATIO/Version 19.06/SP

Belts : FAN. Belt - Gates 9590
ALT. Belt - Gates 9580
A.C. Belt - Gates 9560

CAB Filter : PA 3798 BALD 46697 WIX

Freon : 41BS

1998 Ford TW35

- 8-3-00 Checking on trans. oil temp light
- 8-10-00 Welded hyd. hose bracket back on
- 8-24-00 Replaced belt & bolted AC drive
back up.
- 4-4-02 Repairing leaking hyd. line
- 5-13-02 one trip to Collyer then to country to
remove broken ignition key & put on new
right hand rear view mirror
- 8-1-02 Put repaired dash back in tractor
& took borrowed dash back to Melson's
- 8-21-03 two trips to country - 1 trip to Collyer replaced
tachometer sender on back of injection pump.
- 9-16-03 Removed starter put on new solenoid
- 9-17-03. Put starter back on
- 1-20-04 Put on new water pump
- 2-24-05 Went to country, charged battery & help start
- 9-14-05 Replacing blown power steering hose
- 10-13-05 R+R fuel priming pump on injection pump
- 8-28-06 Replacing blown hyd. hose

10-25-05	Cleaned battery post & put in new battery hold
11-3-05	Replaced one power steering hose
2-9-06	Put on new left ft. tire
5-25-06	2 trips cking fuses & replacing blown fuse
6-5-06	Cking fuses & led trouble - took to Calgar
7-19-06	Replacing all belts
8-10-06	RTR 2 AC hoses & drier & vac. system & recharged
10-10-06	Put 2 way radio in tractor
10-11-06	Put new filter in power steering conister
10-18-06	Put on new fan belt
8-12-08	cking AC
11-3-08	Put on two new battery cables
3-23-10	Cking Battery & ordering one
3-25-10	Put in New battery
9-1-10	RTR 1 power steering hose

- 12-8-11 3 trips to location, charging battery starting, chg. oil + filter & filled with oil
- 5-10-12 Added $1\frac{1}{2}$ cans of Freon
- 5-24-12 Trouble with Power Steering
- 5-29-12 Removing Power Steering Pump
- 5-31-12 Put on new Power Steering pump
- 9-19-12 Ching AC
- 10-21-14 Jump START operator STATES when cold HARD TO START
checked either Solenoid Replace order
- 10/31/16 R&R AC Compressor TO 134A New lines, New Drier
New expansion valve - Changed Winter Cooler water hoses
leaky, ORDERED STARTER/START AND

Alternator: Delco Remy

Air Conditioner Compressor: SANDEN

S/N. 1566303470

Model - U4637

Refrigerant 134a

Turbo charger: Garrett

Customer PT. No. 87840269

GAG PT. No. 452076-2

S/N. EXD105A TD4E36

Front Axle TAG: SPIECER



P.N. 070BP167-1

S/N. 53670 ISO

DATE: 07-08-94

Cab: Outside Air Filter

New Holland

Baldwin

9823782

PA3824

Air Cond. Pts. Expansion Valve 38880

Four Seasons

Dryer

33470 Four Seasons

GAS Cyl. For Steering Col. Pt. No. 86502831

Ford
CNA

AC Compressor Clutch: 86002087

1988 Ford TW35

TRACTOR # A921918

Hyd. Pump ?

Unit 8K03B

Trans. No. 8786B

Engine 8J23A

Hours 1113.6 hrs.

Tires - Front - 14.9-28

Rear - 18.4-38

Ford-New
Holland

5gal oil	Engine oil (2) -	Baldwin	Wix	
		BT 355	51774	86546616
	Fuel -	BF 884	33196	86570171
	air -	PA 2620	outer	PBNN 9B618AA
		PA 2621	inner	
	Hyd. -	BT 342		08 86546610
		BT 425		08NN-11903-EB
	Water -	BT 8504	Wix 51712	08NN-B486-CA
	Water -	BW 5137		9672301

Engine oil - 15W40

TRANS. TH oil

Rear - TH oil

Front Axle 90W

Front Hubs. 90W